

RESERVE ANALYSIS REPORT

Pine Mountain Club Property Owner's Association

Pine Mountain, CA

Report Period: Jul 01, 2023 - Jun 30, 2024

Pine Mountain Club Property Owner's Association 600 B Street, Ste 300, San Diego, CA, 92101 info@smartproperty.com | 877-864-8955 | http://www.smartproperty.com



TABLE OF CONTENTS

Reserve Study Introduction	2
Executive Summary	7
Component Inventory	10
Anticipated Expenditures (5 Years)	21
Funding Models	24
Target Funding - 75% in 30 Years	24
2023-2024 Reserve Budget (TBD) - Ladder	25
Minimum Threshold	26
Target Funding - 100% in 30 Years	27
Percent Funded Analysis	28
Anticipated Expenditures (30 Years)	34



Reserve Study Introduction

The purpose of the Reserve Analysis Report is to help you better understand what you own, in order to develop a financial plan, and adequately budget to pay for future expenses. It consists of a component inventory, life cycle assessment, snapshot of current financial condition, and multiple funding plan options that give you more customization in selecting a strategy that's right for you.

What Should I Expect In My Reserve Analysis Report?

By definition, the reserve analysis report is a budget-planning tool, which identifies the current status of the reserve fund and provides a stable and equitable funding plan to offset the anticipated expenditures of tomorrow. The contents are based on estimates of the most probable current replacement costs and remaining useful lives. Accordingly, the funding plans reflect judgments based on circumstances of the most likely replacement costs and the assumption of regular maintenance of useful and remaining lives. The property may elect to adopt any of the funding plans presented, or may implement some variation developed from the reserve analysis.

The report includes the following:

Executive Summary: Provides project description, financial information, assumptions used in calculations, key indicators of current funding plan, and category summary of expenditures.

Anticipated Expenditures: Includes expenditures associated with the components you will refurbish, replace or repair in a given year.

Component Inventory: Includes the useful life and remaining life of each component, current replacement cost, projected annual expenditures, and source of component information.

Percent Funded Analysis: Provides a snapshot of the financial condition on a component basis by looking at how much you have in reserves vs. how much you should ideally have.

Summary of Funding Plans: An overview of different funding plans that include key performance indicators of financial strength. The funding plans may include:

- Current Funding / Adopted Funding: This funding model projects the reserve fund over the next 20-30 years based on a funding level equal to the Association's current assessments for reserve assets.
- Baseline Funding: Baseline Funding is "a reserve-funding goal of allowing the reserve cash balance to never be below zero during the cash flow projection." Since reserve cash balance is the numerator in percent-funded calculations, Baseline Funding can also be described as not allowing percent funded to drop below zero.
- Threshold Funding Minimum \$/%: A funding model designed to provide the lowest annual funding feasible over the next 30 years which will meet all reserve requirements as they occur. This plan is calculated in which a minimum annual contribution is sought with the constraint that the ending reserve balance or percentage for each year (1 through 30) must be greater than or equal to a specified dollar or percent funded amount. The calculation takes into consideration only the immediate total annual expense requirements. Due to this fact, annual allocations may fluctuate widely from year to year. This plan provides a minimal contingency for unanticipated emergency expenditures. Baseline Funding is a form of Threshold Funding where the minimum balance is \$1.00 for the duration of the report.
- Target Funding: A funding model designed to achieve a specific goal (percentage) over a projected time frame. Example of a typical target funding model would be "Target Funding 100% in 10 Years". This example is designed to achieve the fully funded mark of 100% in year 10. Once the target is hit, the model will then adjust to maintain this level of funding for the remaining years of the report. The target and designated time frame can be adjusted to meet specific requirements of a property.
- Full Funding: A full funding model is designed to achieve and maintain a funding goal near or at 100%. This model can be calculated by designating a specific time frame to hit the 100% funded level (see Target Funding).
- Ladder Funding: A funding plan designed to incorporate varying funding percent increases or dollar amounts to meet specific funding goals or expense requirements. This funding model may incorporate varying contribution percentage increases at different intervals throughout the projected time frame.
- Compliance Funding / Statutory Funding: Funding model designed to comply with specific state statute requirements. These



will vary from state to state.

How Do I Read My Reserve Study?

Here are four easy steps to help you better understand your reserve study so you can use it as an effective tool to budget and plan for your future needs.

Step One (1): **Understand What You Own.** First things first. Whether you are evaluating the need to increase your reserve contributions or leaving them the same, everybody wants to know – "where is the money going ?" Typically, 3 to 5 categories make up 80 % to 90 % of the anticipated expenditures.Review the Executive Summary and Component Inventory to understand what you own.

Step Two (2): **Review Your Upcoming Anticipated Expenditures.** It's important to evaluate what projects are expected for repair, refurbishment, and/or replacement within the next 3 to 5 years. Review the Anticipated Expenditures report and if you don't agree or don't plan to complete those improvements, make sure your component inventory is adjusted accordingly.

Step Three (3): **Analyze Your Current Funding Plan.** Always look to see if your Current Funding Plan is solvent. In other words, are you going to run out of money? Look to see if your current reserve contributions meet your anticipated expenditures over the life of the plan? If yes, great! If not, look at the year the ending reserve balance goes negative (the plan runs out of money), see what the anticipated expenditures driving the shortfall are, and make adjustments accordingly.

Step Four (4): Adopt a Funding Plan that Meets Your Needs. We believe it's important to give you options. That's why we designed the Summary of Funding Plans for you to review. We show you what you are currently contributing to reserves, and let you compare to a minimum threshold amount, as well as a more conservative approach of 100% reserve funding in 10 years. If you don't like those options we also give you the flexibility to create your own customized funding plans.

What Does Percent Funded Mean?

This is an indicator of your financial strength. The ratio of Starting Reserve Balance divided by Fully Funded Reserve Balance is expressed as a percentage. Calculating percent funded is a three-step process. First, Calculate the fully funded balance (FFB) for each component. Per National Reserve Study Standards, FFB = Current Cost X Effective Age / Useful Life. Second, sum the individual component FFB values together for a property total. Third, divide the actual (or projected) total reserve balance by the property total FFB. Important to note, the percent funded is calculated relative to the fiscal year end.

The higher the percentage is, the stronger or healthier your reserve fund is and the more confidence you'll have to pay for future repairs. If your Reserve Fund Balance equals the Fully Funded Reserve Balance, the reserve fund would be considered fully funded, or 100% funded. This is considered an ideal amount.

Think of the Reserve Fund Balance as the gas in your tank and the Fully Funded Reserve Balance as the ideal amount you need to fund your road trip. It's okay if the two don't match perfectly. Usually 70% funded or above is considered strong or healthy.

What Are The Assumptions Used In The Reserve Analysis?

Assumptions are applied in calculating the inflation rate, average interest rate, and rate of reserve contribution increases over the duration of funding plan.

The inflation rate is the percentage rate of change of a price index over time. Future-cost calculations include an assumed annual inflationary factor, which is incorporated into the component inventory, anticipated expenditures, and reserve funding projections. Typically the cost of goods and services will increase over time, so the analysis wants to take that into consideration as it projects long-term, future costs. The current replacement cost of each common area component will be annually compounded by the inflation rate selected. Historical inflation rates in this industry are about 3%, but users can increase or decrease the rate depending on the applicable economic climate. These costs should be updated and reincorporated into your reserve analysis on an ongoing basis.

For planning purposes, interest is applied to the average annual reserve balance represented in the reserve funding plans. Reserve funds deposited in certificates of deposit or money market accounts will generate interest income, increasing the reserves. Interest



rates can be pegged to current bank rates or CD rates. Obviously, a lower rate is more conservative for planning purposes. Note that income from the reserve and operating accounts is taxable to an association, even if the association is established as a non-profit organization. Adjustments to the operating budget may be required to account for applicable federal and state taxes.

Annual reserve contribution increases are assumed in the reserve funding plans provided for future projections. Generally, this is established at the same rate as inflation with the school of thought being that contributions will, at a minimum, be raised to pace inflationary increases in the cost of goods and services. However, it's important for users to be realistic. If users set it to 3% and then do not increase the annual reserve contributions by 3% annually, there will be a shortfall. If there is no plan or expectation to increase reserve contributions, it is best to leave at zero to develop a more realistic plan.

What Methodology Is Used to Perform the Reserve Analysis?

The Cash Flow Method of calculation is utilized to perform your Reserve Analysis. In other words the reserves are 'pooled' together into one reserve account. This is a method of developing a reserve funding plan where contributions to the reserve fund are designed to offset the projected annual expenditures from year to year. At any given point in time using the Cash Flow Method, all components are funded equally in relation to the overall percent funded. If you are 88% funded, all of your components are equally funded at 88%.

This method gives you the flexibility to pursue a solvent, reasonably funded reserve plan when multiple components on different life cycles exist. It allows for minor adjustments to the reserve plan without worry of funding shortfalls. If one or more of the anticipated expenditures are slightly higher than expected there should be cushion to absorb the shortfall and avoid a special assessment or the need to borrow money.

Disclosure

The Reserve Analysis report is to be used only for the purpose stated herein, any use or reliance for any other purpose is invalid. The analysis provided is applicable as of the report completion date, and those items, which are not expected to undergo major repair or replacement within the duration of the report, have been defined as 'life of the project' and may not be included. It is imperative that these components be reviewed annually to consider the impact of changing conditions. Adjustments to the component useful lives and replacement costs should be made whenever the rate of deterioration has changed or when there have been significant changes in the cost of materials and/or labor. Some assumptions have been made about costs, conditions, and future events and circumstances that may occur. Some assumptions inevitably will not materialize and unanticipated events and circumstances may occur subsequent to the date of this report. Therefore, the actual replacement costs and remaining lives may vary from this report and the variations could be material.

No conclusion or any other form of assurance on the reserve funding plans or projections is provided because the compilation of the reserve funding plans and related projections is limited as described above.

No responsibility to update this report for events and circumstances occurring after the date of this report is assumed.

The lack of reserve funding, or funding the reserve below the baseline funding, or the failure to fund some components, or the failure to include a component in the Reserve Study may, under some circumstances, require the association to (1) increase future reserve contributions, (2) defer major repair, replacement, or maintenance, (3) impose special assessments for the cost of major maintenance, repair, or replacement, or (4) borrow funds to pay for major maintenance, repair, or replacement.

The site visit of the community is a limited scope visual inspection of all accessible common areas, or visible from the street, or other common areas. Hidden components, such as but not limited to, irrigation system, vault, and stormwater facilities, electric, plumbing, utility, structural, foundations, construction defects known or unknown, are not included in the scope of this reserve study. The site visit does not include any destructive or other testings. Measurements are taken on the field and/or using satellite mapping. The Reserve Study may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years.

Construction pricing, costs, and life expectancies included in the reserve study may have been obtained from numerous vendors, contractors, historical data and costs, proposals and quotes obtained; and our general experience in the field with similar components or projects. Data and information obtained from previous reserve studies provided by the client were not audited and



the client is considered to have deemed previous reserve studies accurate and reliable.

This Reserve Study is provided as guidance for budgeting and planning purposes and not as an accounting tool. The information provided by the Board Members or official representative(s) of the Association, contractors, vendors, or other supplies about the financials, the actual or projected reserve balance, physical details and/or quantities of the components, or historical issues/conditions will be deemed reliable and is not intended to be used for the purpose of any type of audit, quality/forensic analysis, or background checks of historical records. Therefore, the information provided to us has not been independently verified or audited.

Glossary of Terms:

Annual Fully Funded Requirement: This is a theoretical value represented in the Percent Funded Analysis report per component. It's also considered the annual accrued depreciation. In other word it's the ideal amount required to Fully Fund the replacement on an annual basis. The amount is calculated based on the useful life and replacement cost and makes no adjustment to eliminate any current reserve deficits.

Annual Reserve Contributions: The total assessments, fees, or dues are apportioned between annual operating costs (paying for trash, water, utilities, maintenance, insurance, management fees) and the money you are setting aside every year to pay for anticipated expenditures. This value should not include interest earned as that is already calculated into the reserve funding plans. Our Reserve Analysis Report compares the annual reserve contributions vs. the anticipated expenditures over the duration of the reserve funding plan.

Component: Components are all the different common parts of the property (that typically an HOA would be responsible for). They are everything from the roof to asphalt or concrete to decking and balconies to landscaping, lighting, and painting. All of these things need to be repaired or replaced eventually. Our Reserve Analysis Report provides estimates of those current replacement costs to help determine how much money will be required in the bank to pay for them eventually.

Fully Funded Reserve Balance: The Fully Funded Reserve Balance is the total accrued depreciation. In other words it's the amount of life "used up" for each one of your components translated into a dollar value. This is calculated by multiplying the fractional age of each component by its current estimated replacement cost, then adding them all together, otherwise known as straight-line depreciation. Its purpose is to help you measure the strength of your reserve fund.

Here's a simple example not taking interest and inflation into consideration: If the association's reserve study says replace the roof every 10 years at a cost of \$100,000, Fully Funded does not mean \$100,000 is required today. It means that \$10,000 is required in the bank this year, \$20,000 next year, \$30,000 the following year, and so on until you have \$100,000 on the 10th year when the roof is scheduled to be replaced.

Reserve Balance: This is how much money you have in the bank set aside for reserves at a given point in time, like at the start of each fiscal year called 'Starting Reserve Balance' or at the end of the fiscal year called 'Ending Reserve Balance.' It can also be the reserve accumulated to date, like in the Percent Funding Analysis report where each component has an 'Accumulated Reserve Balance' value.

Reserves are the money set aside for anticipated common area expenses. The reserve account (also called cash reserves or reserve funds) is funded by dues collected from owners (like HOA fees).

Just like an emergency fund or a rainy-day fund to cover personal expenses if the car breaks down or the kitchen sink leaks, HOAs with commonly owned space like condominiums must set aside a healthy percentage of funds every year to plan for the future.

Without it, paying for big expenses becomes difficult. It may require a special assessment to raise the funds to pay for a repair, putting an oversized financial burden on owners. Or a capital improvement loan may be required. The Reserve Analysis report will help figure out a sufficient amount of money to put away in reserves each year to pay for those eventual expenses. Usually a 70% funded reserve balance or above is considered strong.

Remaining Useful Life (RUL): Remaining useful life is how many remaining years of use a component should have left before it has to be replaced. For example, if the useful life of your roof is 20 years and it is five years old, the remaining useful life would be 15 years.



Reserve Study Introduction

Replacement Contingency %: The replacement contingency percentage is a budgeting option that gives you the flexibility to determine the amount or percentage to fund replacements. This gives you more control to establish the funds available to make the necessary repairs on a cycled basis. For example, the retaining walls may be estimated to be replaced over 25 years, but the budget may call to phase the replacement in stages of 20% every five years. It may be determined to only account for that percentage of the replacement cost in your budget.

Source: These are the source(s) utilized to obtain component repair or replacement cost estimates and can be reviewed on the Component Inventory report.

Useful Life (UL): Useful life is how many years a component is expected to be in use from the time it's new (or refurbished); to the time it has to be replaced. For example, the roof – depending on what kind it is – might have a useful life of 20 years. After 20 years, you'd expect to replace it.



Units: 2,887 | Start Date: 7/1/2023

Property De	escription	Financial Summary	
Property Name:	Pine Mountain Club	Starting Reserve Balance:	\$4,100,000
	Property Owner's Association	Fully Funded Reserve Balance:	\$8,680,345
Location:	Pine Mountain, CA	Percent Funded:	47%
Project Type:	Master Association	Current Replacement Cost:	\$13,491,513
Number of Units:	2887	Deficit/Surplus vs. Fully Funded Reserve:	(\$4,580,345) or (\$1,586.54) Per Unit Avg
Age of Project:	45 Year(s)		

Assumed Inflation, Interest & Rate of Annual Reserve Contribution Increase

Funding and anticipated expenditures have been computed with a time value of money approach with the following rates:

Inflation:	Interest:	Annual Reserve Contribution Increase:
4.00 %	3.00 %	Varies
Applied to the anticipated expenditures	Applied to the average annual reserve balance	See individual funding models



Summary of Funding Plans

★ Recommended funding plan

Funding Plans	Annual Reserve Contributions	Yearly Reserve Contributions (Avg. Per Unit)	Meet All Anticipated Expenditures During Next 30 Years	1st Year of Reserve Deficit (if Applicable)	Average Reserve Balance Over 30 Years	Average Percent Funded Over 30 Years	
Target Funding - 75% in 30 Years 🔺	\$797,310	\$276.17	Yes	N/A	\$7,068,384	50%	
2023-2024 Reserve Budget (TBD) - Ladd	ler \$706,212	\$244.62	Yes	N/A	\$10,539,483	76%	
Minimum Threshold	\$728,390	\$252.30	Yes	N/A	\$2,079,653	18%	
Target Funding - 100% in 30 Years	\$868,860	\$300.96	Yes	N/A	\$9,325,915	66%	
\$20,000,000 \$15,000,000 \$10,000,000							
\$5,000,000 25 ^{C2} 25 ^{C2} 25 ^{C2} 25 ^{C2} 25 ^{C2}	20 ¹² 20 ¹² 20 ³² 20 ³² 20 ³² 20 ³² 20 ³²		p ³¹ p ³⁹ p ³⁹ p ⁴⁰ p ⁴⁰	042 2043 2044 2045	204° 204' 204° 204°	10 ⁵⁰ 25 ⁵ 20 ⁵²	
Target Funding - 75% in 30 Years	2023-2024 Reserve Ladder	e Budget (TBD)	- Minimum	Threshold 📕 ⁻ Year	Farget Funding -∶ s	100% in 30	



Expenditures by Category

Current Replacement Cost: \$13,491,513.00





	UL	RUL	Current	Accumulated	Annual Fully	Fully Funded	Annual
			Replacement	Reserve	Funded	Reserve	Reserve
			Cost	Balance	Requirement	Balance	Contribution
Asphalt & Concrete Surfaces	5-30	1-29	\$520,875	\$103,432	\$23,518	\$218,982	\$24,371
Campground	15-20	11-17	\$29,000	\$2,897	\$1,583	\$6,133	\$1,641
Clubhouse - Bar	8-30	0-24	\$145,900	\$35,126	\$10,450	\$74,367	\$10,829
Clubhouse - Bistro	5-20	0-15	\$171,438	\$71,802	\$14,111	\$152,016	\$14,623
Clubhouse - Exterior	5-25	1-20	\$601,915	\$134,347	\$30,745	\$284,433	\$31,860
Clubhouse - General	45-45	2-8	\$4,765,000	\$2,032,075	\$105,889	\$4,302,222	\$109,729
Clubhouse - Lobby	15-30	3-3	\$24,625	\$9,651	\$1,398	\$20,433	\$1,448
Clubhouse - Mech Equipment	12-25	10-13	\$233,667	\$36,937	\$13,030	\$78,201	\$13,503
Clubhouse - Offices	4-14	0-8	\$169,700	\$54,875	\$27,096	\$116,180	\$28,079
Clubhouse - Patrol Offices	5-20	3-18	\$82,815	\$13,001	\$7,763	\$27,526	\$8,045
Clubhouse - Rec Room	12-20	3-4	\$20,115	\$7,381	\$1,316	\$15,627	\$1,363
Clubhouse - Utility Room	10-25	2-2	\$36,280	\$14,388	\$2,909	\$30,462	\$3,014
Golf Course	5-30	0-16	\$989,680	\$288,310	\$64,728	\$610,397	\$67,076
Golf Course - Pro Shop	10-12	1-1	\$95,500	\$41,128	\$8,425	\$87,075	\$8,731
Lampkin Park	15-30	3-19	\$188,822	\$30,450	\$10,156	\$64,468	\$10,524
Maintenance - Building	20-35	0-3	\$39,220	\$18,059	\$1,715	\$38,234	\$1,777
Maintenance - Equipment	5-25	0-23	\$2,970,690	\$790,980	\$231,655	\$1,674,629	\$240,056
Miscellaneous	10-25	2-17	\$195,673	\$56,815	\$13,450	\$120,287	\$13,938
Pavilion	5-25	1-5	\$140,500	\$58,344	\$11,417	\$123,523	\$11,831
Pool & Spa	3-50	1-48	\$1,140,492	\$42,481	\$44,969	\$89,938	\$46,600
Septic Systems	10-30	0-24	\$294,380	\$116,475	\$17,679	\$246,596	\$18,320
Stables	5-30	0-17	\$450,512	\$85,068	\$28,678	\$180,103	\$29,718
Tennis Courts	5-50	0-25	\$184,714	\$55,978	\$8,818	\$118,514	\$9,138
		Totals	\$13,491,513	\$4,100,000	\$681,497	\$8,680,345	\$706,212



Units: 2,887 | Start Date: 7/1/2023

Current Replacement Cost: \$13,491,513

							ourrent hepte	icement cost. ș	10, 191,010
Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
Asphalt & Concrete Surfaces	;								
Asphalt (Campground) - Repair/Replace	1001		25	24	\$3.50 / SF	35,000	\$122,500	\$314,005	On File
Asphalt (Clubhouse) - Repair/Replace	1002		25	6	\$3.50 / SF	50,250	\$175,875	\$222,538	On Fil
Asphalt (Main) - Chip/Seal/Replace (Maintenance / Operating) Included in annual operating b	1003 budget. Moni	tored closely ar	0 nd evalua	0 ated ann	\$0.00 / ually to determine are	0 eas of need.	\$0*	\$0*	On Fil
Asphalt (Maint Yard) - Repair/Replace (1) Maint yard asphalt is in varying costs of each phase may vary.		th repairs and r	30 eplacem	20 nents to l	\$3.50 / SF	15,000 ncluded in r	\$52,500 eserve plan on a 3 pha	\$115,034 se replacement cycle.	On Fil
Asphalt (Maint Yard) - Repair/Replace (2)	1005		30	29	\$3.50 / SF	15,000	\$52,500	\$163,729	On File
Asphalt (Maint Yard) - Repair/Replace (3)	1006		30	8	\$3.50 / SF	15,000	\$52,500	\$71,850	On File
Concrete - Kitchen Access Road			30	28	\$40,000.00 / Total	1	\$40,000	\$91,517	On File
Concrete - Repair Contingency General contingency for repai	1007 rs to the corr	imon area conc	5 crete. Re		\$25,000.00 / Total d replacements comp	1 bleted on an	\$25,000 "as needed" basis. Am	\$26,000 ount and cycle to be re	On File
adjusted annually.						Totals	\$520.875	\$1,004,673	

					Totals	\$520,875	\$1,004,673	
					* Non-reserv	e components exclu	uded from totals	
Campground								
Campground - Comp Shingle Roof	1012	20	17	\$4,000.00 / Total	1	\$4,000	\$7,792	On File
Replaced as part of restrooms (ref	urb)							
Campground - Dog Park	1013	0	0	\$0.00 /	0	\$0*	\$0*	On File
Fence/Furnishings (Maintenance / Operating)								
Campground - Fencing (Chain Link) (Maintenance / Operating)	1008	0	0	\$0.00 /	0	\$0*	\$0*	On File
Campground - Furnishings	1009	20	16	\$1,700.00 / EA	10	\$17,000	\$31,841	On File
Campground - Restrooms (Refurb)	1010	15	11	\$4,000.00 / EA	2	\$8,000	\$12,316	On File
Campground - Upgrades/Redesign <i>(Other)</i>	1011	0	0	\$0.00 /	0	\$0*	\$0*	On File
Possible upgrades and additional L	use development	s. To be determin	ed.					
Campground - Wood Surfaces (Paint/Repair) (Maintenance / Operating)	1013	0	0	\$0.00 /	0	\$0*	\$0*	On File
					Totals	\$29,000	\$51,948	
					* Non-reserv	e components exclu	uded from totals	
Clubhouse - Bar								
Bar - Appliances/Serving Systems	1014	12	7	\$28,000.00 / Total	1	\$28,000	\$36,846	On File
Bar - Audio/Video Equip.	1015	8	0	\$5,400.00 / Total	1	\$5,400	\$5,400	On File

Pine Mountain Club Property Owner's Association

info@smartproperty.com | 877-864-8955 | www.smartproperty.com

10

Component Inventory

Stations

Units: 2,887 | Start Date: 7/1/2023

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
Bar - Flooring/Furnishings	1016		10	2	\$52,000.00 / Total	1	\$52,000	\$56,243	On File
Includes upper utility room.									
Bar - JukeBox	1017		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Bar - Lighting	1018		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Bar - Remodel/Refurbish	1019		30	24	\$56,000.00 / EA	1	\$56,000	\$143,545	On File
Bar - Restroom (Refurb)	1020		12	0	\$4,500.00 / EA	1	\$4,500	\$4,500	On File
Bar - Wine Lockers	1021		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									

1 3.								
					Totals	\$145,900	\$246,534	
					* Non-reserv	e components exclu	ded from totals	
Clubhouse - Bistro								
Bistro - Drink Ftn	1022	0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)								
Bistro - Flooring	1023	20	15	\$13.50 / SF	988	\$13,338	\$24,021	On File
Bistro - Furnishings	1024	10	5	\$17,800.00 / Total	1	\$17,800	\$21,656	On File
(Chairs/Tables)								
Includes (41) chairs, (22) tables an	d associated furni	shings.						
Bistro - Office/Equip (Refurb)	1025	5	0	\$3,245.00 / EA	1	\$3,245	\$3,245	On File
Bistro - Paint	1026	0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)								
Completed in house on an "as ne	eded" basis.							
Bistro - Restroom	1027	14	0	\$4,325.00 / EA	1	\$4,325	\$4,325	On File
Bistro - Washer/Dryer	1028	10	3	\$865.00 / EA	2	\$1,730	\$1,946	On File
(Whirlpool)								
Kitchen -	1029	12	0 9	\$108,000.00 / Total	1	\$108,000	\$108,000	On File
Appliances/Cookware								
Kitchen - Flooring/Prep	1030	15	0	\$23,000.00 / Total	1	\$23,000	\$23,000	On File

\$171,438 * Non-reserve components excluded from totals

Totals

Clubhouse - Exterior								
Decking, Ramps, Rails (New)		22	20 \$27	5,000.00 / Total	1	\$275,000	\$496,681	On File
Ext - Backflow Device	1031	18	1	\$11,350.00 / EA	1	\$11,350	\$11,804	On File
Ext - Decking / Siding / Rails	1032	22	4 \$17	'5,000.00 / Total	1	\$175,000	\$204,725	On File
Ext - Lighting	1033	15	9	\$34,600.00 / EA	1	\$34,600	\$49,247	On File
Includes bollards and parking post	fixtures and asso	orted wall fixtures.	Condition	s vary.				
Ext - Paint/Repairs	1034	5	1 \$1	.9,465.00 / Total	1	\$19,465	\$20,244	On File
Ext - Roofing	1035	25	3\$8	6,500.00 / Total	1	\$86,500	\$97,301	On File
					Totals	\$601,915	\$880,001	
Clubhouse - General								
Clubhouse - Doors/Access Systems <i>(Other)</i>	1036	0	0	\$0.00 /	0	\$0*	\$0*	On File
Clubhouse - Electrical Systems (Other)	1037	0	0	\$0.00 /	0	\$0*	\$0*	On File
Clubhouse - Lighting Upgrades <i>(Other)</i>	1038	0	0	\$0.00 /	0	\$0*	\$0*	On File
Clubhouse - Plumbing Systems	1039	0	0	\$0.00 /	0	\$0*	\$0*	On File



\$186,193

Component Inventory

Units: 2,887 | Start Date: 7/1/2023

Component	GL Code	Project UL Number	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
(Other)								
Clubhouse - Remodel/Design Phase 3	1041	45	2	\$2,000,000.00 / Total	1	\$2,000,000	\$2,163,200	On File
Awaiting confirmation of Dates ar	nd Cost							
New Admin Building/Pro Shop	ia cost.							
Clubhouse - Remodel/Design	1042	45	5	\$1,765,000.00 /	1	\$1,765,000	\$2,147,392	On File
Phase 4	1042	45	5	\$1,765,000.007 Total	T	\$1,765,000	\$2,147,592	On File
Awaiting confirmation of Dates ar	ad Cast			rotut				
New Kitchen/remodel front entry								
Clubhouse - Remodel/Design	1043	45	8	\$1,000,000.00 /	1	\$1,000,000	\$1,368,569	On File
Phase 5 & 6	1043		0	Total	T	\$1,000,000	\$1,500,505	On the
Awaiting confirmation of Dates ar	nd Cost.							
Remodel upper and lower meetir								
Clubhouse -	1044	0	0	\$0.00 /	0	\$0*	\$0*	On File
Windows/Doors/Sliders								
(Other)								
					Totals	\$4,765,000	\$5,679,161	
					* Non-rese	erve components exc	luded from totals	
Clubhouse - Lobby								
Lobby - Flooring/Furnishings	1045	30	3	\$7,325.00 / Total	1	\$7,325	\$8,240	On File
Lobby - Restrooms	1046	15	3	\$8,650.00 / EA	2	\$17,300	\$19,460	On File
Lobby - Signage	1047	0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)								
					Totals	\$24,625	\$27,700	
					* Non-rese	erve components exc	luded from totals	
Clubhouse - Mech Equipment								
Club - Emergency Generator	1048	25	12	\$118,500.00 / EA	1	\$118,500	\$189,722	On File
Club - Fire Systems -	1049	15	13	\$24,332.00 / Total	1	\$24,332	\$40,515	On File
Upgrade/Repairs				+,,		+= .,===	+ ,	
Club - Heating/Cooling	1050	15	13	\$54,075.00 / Total	1	\$54,075	\$90,039	On File
Systems								
Club - Sump Pumps - Lift	1051	12	10	\$9,730.00 / EA	2	\$19,460	\$28,806	On File
Station								
Club - Water Heat Systems	1052	12	10	\$17,300.00 / Total	1	\$17,300	\$25,608	On File
					Totals	\$233,667	\$374,690	
Clubhouse - Offices								
HOA/Patrol Offices -	1053	4	2	\$80,000.00 / Total	1	\$80,000	\$86,528	On File
Computers/Equipment								
Includes Computers, servers, offic	ce equipm	ent and phone systems	;					
HOA/Patrol Offices -	1054	14		\$55,500.00 / Total	1	\$55,500	\$55,500	On File
Furnishings/Flooring	1001	11	Ŭ	\$55,500,00 / Totat	-	\$55,500	\$55,500	onnie
HOA/Patrol Offices -	1055	12	0	\$8,650.00 / EA	2	\$17,300	\$17,300	On File
Restrooms (Refurb)								
Office - Phone System		10	8	\$16,900.00 / Total	1	\$16,900	\$21,408	On File
					Totals	\$169,700	\$180,736	
Clubhouse - Patrol Offices								
HOA/Patrol Offices - Security	1056	10	5	\$40,000.00 / Total	1	\$40,000	\$48,666	On File
Cameras								
Includes 22 security cameras and	associate	d recoding equipment.						
	4057	20	19	\$72,000,00 / Total	1	\$32,000	\$64,826	On File
HOA/Patrol Offices - Security	1057	20	10	\$32,000.00 / Total	1	\$32,000	\$04,020	Onnic
HOA/Patrol Offices - Security Communications	1057	20	10	\$52,000.00 / Totat	I	\$32,000	Ş04,020	onnie

Pine Mountain Club Property Owner's Association

info@smartproperty.com | 877-864-8955 | www.smartproperty.com

Component Inventory

Component	GL Code	Project UL Number	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
					Totals	\$82,815	\$125,310	
Clubhouse - Rec Room								
Rec Rm - Flooring	1058	12	3	\$9,300,00 / Total	1	\$9,300	\$10,461	On File
Rec Rm - Furnishings/Miscl	1050	20	4	\$10,815,00 / Total		\$10,815	\$12,652	On File
Game tables, TV's, displays, cha					T	\$10,815	\$12,052	On File
Game lables, TV s, displays, cha	and turnisr	ings. Replaced on	an as need	ied basis.	Totals	\$20,115	\$23,113	
Clubhouse - Utility Room					Totats	<i>QLU/LLU</i>	420,220	
Utility Room -	1060	10	2	\$21,630.00 / Total	1	\$21,630	\$23,395	On File
Furnishings/Miscl	1000	10	2	\$21,000.00 / Totat	-	<i>\$21,030</i>	\$20,000	onnie
Furnishings, A/V Equipment and	h miscl furnitu	ro						
Utility Room - Kitchen	1061	15	2	\$6,000.00 / Total	1	\$6,000	\$6,490	On File
•	1001	15	2	\$0,000.00 / Totat	Т	\$0,000	\$0,490	On File
(Appliances)	1000	25	2	60.000 (T-t-l		¢0.050	60 7FC	0
Utility Room - Kitchen	1062	25	2	\$8,650.00 / Total	1	\$8,650	\$9,356	On File
(Refurbish)					Tatala	676 200	670.940	
					Totals	\$36,280	\$39,240	
Golf Course								
Golf Course - Aerators	2001	10	2	\$5,675.00 / EA	3	\$17,025	\$18,414	On File
Golf Course - Bridges	2002	15	10	\$6,350.00 / Total	1	\$6,350	\$9,400	On File
(Rebuild/Repair)								
Golf Course - Cart Paths	2003	10	1	\$9.72 / SF	17,655	\$17,161	\$17,847	On File
(Concrete Repairs 10%)								
Golf Course - Cart Path's / Rehab (25%)	2004	5	3	\$3.50 / SF	52,572	\$46,001	\$51,744	On File
Rehab cycle for damaged cart j	oaths. Curren	t allowance is for 2.	5% to be co	ompleted every 6 vea	rs. Evaluatio	n to determine which	n areas are to be addr	essed. Amount
and cycle to be adjusted as nee								
Golf Course - Course	2005	15	10	\$40,000.00 / EA	1	\$40,000	\$59,210	On File
Restroom (Refurb)								
Completed in 2018. Awaiting a	ictual costs.							
Golf Course - Driving Range	2006	0	0	\$0.00 /	0	\$0*	\$0*	On File
Mats								
(Maintenance / Operating)								
Golf Course - Driving Range	2007	0	0	\$0,00 /	0	\$0*	\$0*	On File
Netting/Posts								
(Maintenance / Operating)								
Golf Course - Gate Valves	2008	20	0	\$2,200.00 / EA	4	\$8,800	\$8,800	On File
(Canal)	2000			<i><i><i>v</i>=<i>/</i>=<i>v</i>=<i>v</i>=<i>v</i></i></i>	·	<i>+0,000</i>	<i>Q(0)000</i>	••••••
Golf Course - Irr Pumps	2009	15	4	\$22,700.00 / EA	3	\$68,100	\$79,667	On File
(Replace)	2005	15	-	\$22,700.007 EA	5	\$00,100	\$75,007	onnie
Golf Course - Irr System	2010	30	16	\$350,000.00 / Total	1	\$350,000	\$655,543	On File
(Replace)	2010	50	10	\$550,000.00 / Totat	T	\$550,000	\$000,040	On the
Contingency included for budg		s Upgrades and m	aior roplac	omonts to the irrigati	on a stora ca	n yary graatly dapan	ding on type and love	l of system
upgrades. To be monitored and			iajoi replac	ernents to the imgati	JII System Co	in vary greatty depen	ang on type and teve	a or system
Golf Course - Lake Systems	2011	10 Ieeded annuality.	z	\$248,745.00 / Total	1	\$248,745	\$279,804	On File
(Maintenance)	2011	10	5		Т	JZ70,/4J	şz/ 9,004	On File
Lake repairs completed in 2019	1 for \$22 775 (E	Pipe Repairs)						
		0	0	\$0.00 /	0	\$0*	\$0*	On File
		0	0	\$0,007	U	ŞŪ	ŞŪ	On file
Golf Course - Practice Green	2012							
Golf Course - Practice Green (Maintenance / Operating)		70	4	\$120 780 00 / Tat-1	1	¢120 700	¢174 074	
Golf Course - Practice Green (Maintenance / Operating) Golf Course - Spillway	2012	30	1	\$129,780.00 / Total	1	\$129,780	\$134,971	On File
Golf Course - Practice Green (<i>Maintenance / Operating</i>) Golf Course - Spillway (Repairs)	2013							
Golf Course - Practice Green (Maintenance / Operating) Golf Course - Spillway (Repairs) Golf Course - Split Rail		30 20	1	\$129,780.00 / Total \$24.00 / LF	1 1,326	\$129,780 \$31,824	\$134,971 \$55,109	On File On File
Golf Course - Practice Green (Maintenance / Operating) Golf Course - Spillway (Repairs) Golf Course - Split Rail Fencing	2013							
Golf Course - Practice Green (Maintenance / Operating) Golf Course - Spillway (Repairs) Golf Course - Split Rail	2013							

Component Inventory

Units: 2,887 | Start Date: 7/1/2023

-								•	
Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
(Maintenance / Operating)									
Golf Course - Tee's / Green's / Fairways (Maintenance / Operating)	2016		0	0	\$0.00 /	0	\$0*	\$0*	On File
Golf Course - Vertical Cutting Reels	2017		12	11	\$2,865.00 / EA	3	\$8,595	\$13,232	On File
Golf Course - Wood Ret Walls (Repairs)	2018		20	2	\$17,300.00 / Total	1	\$17,300	\$18,712	On File
						Totals	\$989,680	\$1,402,453	
						* Non-rese	erve components exc	luded from totals	
Golf Course - Pro Shop									
Pro Shop -	3001		0	0	\$0.00 /	0	\$0*	\$0*	On File
Equipment/Lighting (Maintenance / Operating)				·	÷0.007	Ū.	ŶŬ	÷	
Pro Shop -	3002		10	1	\$28,000.00 / Total	1	\$28,000	\$29,120	On File
Furnishings/Displays/Flooring									
Pro Shop - Golf Carts	3003		12	1	\$6,750.00 / EA	10	\$67,500	\$70,200	On File
Pro Shop - Golf Pull Carts/Rentals (Maintenance / Operating)	3004		0	0	\$0.00 /	0	\$0*	\$0*	On File
						Totals	\$95,500	\$99,320	
						* Non-rese	erve components exc	luded from totals	
Lampkin Park									
Lampkin - Baseball Field (Bleachers)	4001		25	5	\$5,785.00 / EA	2	\$11,570	\$14,077	On File
Aluminum, 5-row with upper rails	i.								
Lampkin - Baseball Field	4002		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Refurbish/Maint)									
<i>(Maintenance / Operating)</i> Status of field to be determined.									
Lampkin - Bball Ct (Resurface)	4003		20	19	\$4.25 / SF	14,584	\$61,982	\$130,587	On File
Reduced useful life	4005		20	19	54.257 51	14,304	\$01,902	\$130,367	On the
Lampkin - Bball Ct	4004		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Seal/Repair) (Maintenance / Operating)									
Done annually out of the mainter	nance .								
Lampkin - Chain Link Fencing	4005		30	3	\$22.00 / LF	650	\$14,300	\$16,086	On File
(Field)									
Lampkin - Cover Structure (Repair/Replace)	4006		25	8	\$17,300.00 / Total	1	\$17,300	\$23,676	On File
Lampkin - Playground - Safety Surface / Barrier	4007		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Lampkin - Playground (Structures)	4008		15	10	\$68,000.00 / Total	1	\$68,000	\$100,657	On File
Includes to lots and climbing wal									
Lampkin - Restrooms	4009		15	6	\$3,245.00 / EA	2	\$6,490	\$8,212	On File
(Refurbish)			0	0	\$0.00 /	0	\$0*	\$0*	On File
Lampkin – Retaining Wall	4010		U			-	÷ •		
Lampkin - Retaining Wall (Block)	4010		0	-					
	4010		0						
(Block)	4010 4011		20	18	\$7.20 / SF	1,275	\$9,180	\$18,597	On File

info@smartproperty.com | 877-864-8955 | www.smartproperty.com

Component Inventory

Units: 2,887 | Start Date: 7/1/2023

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
(Replenish/Nets)							COSI		
(Maintenance / Operating)									
Lampkin - Wood Split Rail	4013		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
To be repaired and or replaced	on an "as ne	eded" basis.							
						Totals	\$188,822	\$311,891	
						* Non-res	erve components exc	luded from totals	
Maintenance - Building									
Maint Bldg - Comp Shingle	5001		20	0	\$7.20 / SF	3,850	\$27,720	\$27,720	On File
Roofing									
Maint Bldg - Ext Paint/Repairs	5002		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Maint Bldg - Garage Doors	5003		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Maint Bldg - RV Chain Link	5004		35	3	\$23.00 / LF	500	\$11,500	\$12,936	On File
						Totals	\$39,220	\$40,656	
						* Non-res	erve components exc	luded from totals	
Maintenance - Equipment									
2 Snow Plow kits (191 & 192)			5	3	\$19,500.00 / Total	1	\$19,500	\$21,308	On File
2010 Dodge Truck 2500			15		\$43,260.00 / Total	1	\$43,260	\$44,558	On File
Air Compressor (Champion)	6001		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)			•	•	<i>t</i> ,	-	ψ.º	ψ.º	
Asphalt - Crack Filler	6002		16	7	\$62,000.00 / EA	1	\$62,000	\$81,588	On File
Asphalt - Roller CAT (#2055)	6004		20	3	\$69,000.00 / EA	1	\$69,000	\$77,616	On File
Auto Lift - Hydraulic	6005		25	5	\$24,000.00 / EA	1	\$24,000	\$29,200	On File
Backhoe - New Holland (#143)	6006		20	11	\$86,000.00 / EA	1	\$86,000	\$132,393	On File
Boat - Lake Maintenance			20	19	\$8,650.00 / EA	1	\$8,650	\$18,224	On File
(TBD)									
Bobcat Compact Track Loader			10	8 9	\$142,000.00 / Total	1	\$142,000	\$194,337	On File
(2021)									
Cardboard Bailer	6007		25	23	\$16,000.00 / EA	1	\$16,000	\$39,435	On File
Cinder Spreader - Meyer	6008		15	2	\$9,000.00 / EA	1	\$9,000	\$9,734	On File
(#012-1)									
Cinder Spreader - Meyer	6009		15	2	\$9,000.00 / EA	1	\$9,000	\$9,734	On File
(#012-2)									
Diesel Tank/Pump (1) - 2,000	6010		18	1	\$23,795.00 / EA	1	\$23,795	\$24,747	On File
Gal									
Diesel Tank/Pump (2) - 1,000	6011		18	1	\$17,500.00 / EA	1	\$17,500	\$18,200	On File
Gal					**** *** *** / F.		407.000	40.1750	
Diesel Tank/Pump (3) - 2,000	6012		18	1	\$23,800.00 / EA	1	\$23,800	\$24,752	On File
Gal	6071		10	7	¢40 500 00 / 54	1	¢40.500	¢ 45 557	
EC Vehicle - Subaru (#161)	6031		10	3	\$40,500.00 / EA	1	\$40,500	\$45,557	On File
Forklift - Nissan 5K (#062)	6013		15	4	\$14,000.00 / EA	1	\$14,000	\$16,378	On File
Front Loader - JCB (#2081)	6014		20	6	\$102,000.00 / EA	1	\$102,000	\$129,063	On File
Front Loader - Komatsu 250 (#2041)	6015		20	2	\$200,000.00 / EA	1	\$200,000	\$216,320	On File
Front Loader - Komatsu WA	6016		20	10	\$183,000.00 / EA	1	\$183,000	\$270,885	On File
250 (#121)	0010		20	10	9103,000,00 / EA	T	\$103,000	2270,000	On File
Frontier BB4278H - 6ft. 6in.			10	9	\$5,350.00 / Total	1	\$5,350	\$7,615	On File
Hydraulic Scarifier Box Blade				2	+=,===0100 / 10tat	-	<i>\$3,330</i>	¢,,510	ennie
Golf - Aerator (ProCore 864)	6017		10	6	\$38,800.00 / EA	1	\$38,800	\$49,094	On File
"	6018		10	2	\$12,735.00 / EA	1	\$12,735	\$13,774	On File

Pine Mountain Club Property Owner's Association

info@smartproperty.com | 877-864-8955 | www.smartproperty.com

Component Inventory

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
Golf - Green Sweeper	6019		15	14	\$11,680.00 / EA	1	\$11,680	\$20,226	On File
Golf - Mower JD2500 (#2002)	6021		10	9	\$34,770.00 / EA	1	\$34,770	\$49,489	On File
Golf - Mower Reelmaster	6022		10	6	\$44,610.00 / EA	1	\$44,610	\$56,446	On File
3100-D Sidewinder									
Golf - Sod Cutters	6023		15	2	\$8,650.00 / EA	2	\$17,300	\$18,712	On File
Golf - Toro Green Mower	6024		10	2	\$60,000.00 / EA	1	\$60,000	\$64,896	On File
(#157)									
Golf - Toro Rough Mower	6025		11	10	\$61,000.00 / EA	1	\$61,000	\$90,295	On File
(#2093)									
Extending life 3 years									
John Deere 5065E Utility			10	9	\$59,500.00 / Total	1	\$59,500	\$84,687	On File
Tractor									
John Deere 520M Loader			10	9	\$12,600.00 / Total	1	\$12,600	\$17,934	On File
Maintenance - Emergency			25	22	\$32,000.00 / EA	1	\$32,000	\$75,837	On File
Generator									
Added.									
Patrol Vehicle - Colorado			5	3	\$41,000.00 / Total	1	\$41,000	\$44,802	On File
Crew									
Patrol Vehicle - Colorado			5	3	\$37,850.00 / Total	1	\$37,850	\$42,576	On File
extended									
Roto Chopper (#141)	6034		15	7	\$420,000.00 / EA	1	\$420,000	\$552,691	On File
Snow Plow - Attachment (#163)	6038		10	10	\$8,000.00 / EA	1	\$8,000	\$11,842	On File
Snow Plow - Attachment (#182)	6037		10	6	\$11,250.00 / EA	1	\$11,250	\$14,235	On File
Replaced in 2019.									
Snow Plow - Blade (#131)	6041		20	3	\$21,630.00 / EA	1	\$21,630	\$24,331	On File
Snow Plow - Front Loader (#121) Attachment for Komatsu.	6042		20	11	\$32,000.00 / EA	1	\$32,000	\$49,263	On File
Snow Plow - Front Loader (#2041)	6043		15	3	\$24,000.00 / EA	1	\$24,000	\$26,997	On File
Life extended 5 yrs. Snow Plow - Front Loader (#2081)	6044		20	6	\$30,000.00 / EA	1	\$30,000	\$37,960	On File
Attachment for JCB.									
Snow Plow (#171)	6046		10	10	\$8,400.00 / EA	1	\$8,400	\$12,434	On File
Replaced in 2019.									
Snow Plow (#172)			10	10	\$8,400.00 / Total	1	\$8,400	\$12,434	On File
Snow Plow (#2010)	6045		10	10	\$7,900.00 /	1	\$7,900*	\$11,694*	On File
(Maintenance / Operating)									
Spreader - Turfco 1550	6047		15	11	\$20,000.00 / EA	1	\$20,000	\$30,789	On File
Life extended.									
Street Sweeper (#2044)	6048		15	0	\$102,000.00 / EA	1	\$102,000	\$102,000	On File
Sweeper Vac - PTO (#2006)	6049		16	7	\$28,000.00 / EA	1	\$28,000	\$36,846	On File
Telehandler - Gradall (#061)	6050		15	5	\$44,000.00 / EA	1	\$44,000	\$53,533	On File
Tire Changer (Triumph)	6051		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)			-	2	··	-	* -		
Tractor - John Deere (#083)	6052		20	6	\$37,850.00 / EA	1	\$37,850	\$47,892	On File
Trash Compactor (A)	6053		20	4	\$23,790.00 / EA	1	\$23,790	\$27,831	On File
Major repairs completed, life ext		ars.			,	-		, 302	
, ,									
Trash Compactor (B)	6054		20	4	\$23,790.00 / EA	1	\$23,790	\$27,831	On File



Component Inventory

Units: 2,887 | Start Date: 7/1/2023

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
(Maintenance / Operating)									
Truck - Chevy 3500 (#2053)	6057		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Not going to be replaced. Repa	airs and Main	t to be funded fr	rom op	erating b	udget.				
Truck - Chevy 3500 (#2054)	6058		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Not going to be replaced. Repa	airs and Main	t to be funded fr	rom op	erating b	udget.				
Truck - Dodge 2500 (#182)	6061		10	5	\$56,000.00 / EA	1	\$56,000	\$68,133	On File
Truck - Dodge 2500 (#2101)	6059		10	6	\$56,000.00 / EA	1	\$56,000	\$70,858	On File
Truck - Dodge 2500 (191)	6060		10	6	\$56,000.00 / EA	1	\$56,000	\$70,858	On File
Truck - Dodge 3500 (#163)	6062		10	3	\$50,000.00 / EA	1	\$50,000	\$56,243	On File
Truck - Dodge 4500 (#171)	6063		10	3	\$50,000.00 / EA	1	\$50,000	\$56,243	On File
Truck - Dodge 5500 (#172)	6064		10	4	\$82,000.00 / EA	1	\$82,000	\$95,928	On File
Truck - Ford F-550 (#131)	6065		10	0	\$69,000.00 / EA	1	\$69,000	\$69,000	On File
Truck - Trailer - Boander 20'	6066		20	12	\$14,500.00 / EA	1	\$14,500	\$23,215	On File
(#142)									
Utility Vehicle - John Deere Gator	6069		8	5	\$18,385.00 / EA	1	\$18,385	\$22,368	On File
Utility Vehicle - John Deere Gator (50014)			10	9	\$17,000.00 / Total	1	\$17,000	\$24,196	On File
Utility Vehicle - John Deere Gator (50018)			10	9	\$17,000.00 / Total	1	\$17,000	\$24,196	On File
Utility Vehicle - Kubota 1100	6068		8	7	\$28,000.00 / EA	1	\$28,000	\$36,846	On File
Utility Vehicle - Kubota 900	6070		8	7	\$18,000.00 / EA	1	\$18,000	\$23,687	On File
Water Tank - 2,000 Gal	6071		10	1	\$8,650.00 / EA	1	\$8,650	\$8,996	On File
Watering Tank	6072		12	1	\$17,845.00 / EA	1	\$17,845	\$18,559	On File
Life extended.									
Welders (2) - Ranger	6074		10	8	\$7,000.00 / Total	1	\$7,000	\$9,580	On File
						Totals	\$2,970,690	\$3,788,225	
						* Non-rese	rve components exc	luded from totals	
Miscellaneous									
				_		-			
Archery Area - Maint	7001		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)					Ac === 0 0 0 (= 1 1		4.5.75.5	*** ***	
Electronic Speed limit sign			15	12	\$6,758.00 / Total	1	\$6,758	\$10,820	On File
Added component.	7000		10		617.000.00 (Talal		617.000	¢10.000	0
Emergency Preparedness -	7002		10	4	\$17,000.00 / Total	1	\$17,000	\$19,888	On File
Equip/Materials	7007		10	•	¢с гоо оо (т. н.)	4	¢6 500	ćo 252	0
Entry Monuments - Maint/Refurb	7003		10	9	\$6,500.00 / Total	1	\$6,500	\$9,252	On File
	7004		25	•	624 670 00 (T-+-)		624 670	670 70 <i>C</i>	0
Gazebo - Roofing/Repairs	7004		25	9	\$21,630.00 / Total	1	\$21,630	\$30,786	On File
Gazebo - Waterproof/Seal	7005		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)	7000		0	~	ćo oo /	0	¢0+	¢0+	O 51
Greenbelt / Forest Management	7006		0	0	\$0.00 /	0	\$0*	\$0*	On File
Management (Maintenance / Operating)									
Mailboxes	7007		10	7	\$19,450.00 / Total	1	\$19,450	\$25,595	On File
Association responsibility due to		ith LISPO	TO	/	519,400,00 / TOtal	T	şt9,450	323,393	On File
Mailboxes -		iai 051 O.	20	17	\$27,000.00 / Total	1	\$27,000	\$52,593	On File
Enclosure/Structure			20	1/		Ŧ	şz7,000	<i>JJC,JJJ</i>	On File

Signage -

Streets/Directional/Warning (Maintenance / Operating) Trash Receptacles 7008

7009



0

15

0

2

\$0.00/

\$10,815.00 / EA

0

9



\$0*

\$105,278

\$0*

\$97,335

On File

On File

Component Inventory

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
						Totals	\$195,673	\$254,211	
							erve components exc		
Pavilion									
Pavilion (Ext) - Balc/Patio	7010		10	5	\$13,900.00 / Total	1	\$13,900	\$16,911	On File
Furnishings									
Pavilion (Ext) - Balc/Walkway (Repair/Replace)	8001		25	1	\$51,000.00 / Total	1	\$51,000	\$53,040	On File
Pavilion (Ext) - Paint/Repairs/Replace	8002		5	1	\$18,600.00 / Total	1	\$18,600	\$19,344	On File
Pavilion (Ext) - Roofing (Flat/Mansards)	8003		15	1	\$26,000.00 / Total	1	\$26,000	\$27,040	On File
Pavilion (Int) - Furnishings/Carpeting/Miscl	8004		10	1	\$14,000.00 / Total	1	\$14,000	\$14,560	On File
Pavilion (Int) - Kitchen (Remodel/Refurbish)	8005		15	1	\$17,000.00 / Total	1	\$17,000	\$17,680	On File
						Totals	\$140,500	\$148,575	
Pool & Spa									
Pool - Resurface/Tile	8006		12	10	\$23,795.00 / Total	1	\$23,795	\$35,222	On File
Pool & Spa - Replace			40	38	\$225,000.00 / Total	1	\$225,000	\$691,826	On File
Pool Area - Cover & Reel	9001		15	13	\$7,000.00 / Total	1	\$7,000	\$11,656	On File
Pool Area - Deck (Repairs - 5%)	9002		10	8	\$54.00 / SF	5,200	\$14,040	\$19,215	On File
Pool Area - Deck (Replace)	9002		50	48	\$54.00 / SF	5,200	\$280,800	\$1,845,004	On File
Pool Area - Deck (Reseal/Waterproof)	9003		10	8	\$6.50 / SF	5,200	\$33,800	\$46,258	On File
Pool Area - Ext Showers (Tile)	9004		20	18	\$34,600.00 / Total	1	\$34,600	\$70,093	On File
Pool Area - Furnishings	9005		12	10	\$19,500.00 / Total	1	\$19,500	\$28,865	On File
Pool Area - Lifeguard Stands (Maintenance / Operating)	9006		0	0	\$0.00 /	0	\$0*	\$0*	On File
Pool Area - Pump Rm - Paint <i>(Maintenance / Operating)</i>	9008		0	0	\$0.00 /	0	\$0*	\$0*	On File
Pool Area - Pump Rm Roofing	9007		25	23	\$8.65 / SF	342	\$2,958	\$7,291	On File
Pool Area - Wood Trellis	9009		20	18	\$34.00 / SF	400	\$13,600	\$27,551	On File
Pool Area - Wood Trellis - Paint/Seal (Maintenance / Operating)	9010		0	0	\$0.00 /	0	\$0*	\$0*	On File
Pool Bathrooms			30	28	\$297,000.00 / Total	1	\$297,000	\$890,615	On File
Pool Equipment Room			30	28		1	\$19,000	\$43,471	On File
Pool Shade Structure			30	28	\$27,000.00 / Total	1	\$27,000	\$61,774	On File
Pool/Spa - Chem Systems	9011		12	10	\$3,460.00 / EA	2	\$6,920	\$10,243	On File
Pool/Spa - Coping	9012		30	28	\$45.00 / LF	324	\$14,580	\$43,721	On File
Pool/Spa - Fencing (W.I.)	9013		25	23	\$82.00 / LF	338	\$27,716	\$68,312	On File
Pool/Spa - Fencing (W.I.) - Paint	9014		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Pool/Spa – Filters	9015		15	13	\$6,500.00 / EA	6	\$39,000	\$64,938	On File
Pool/Spa - Heater (Pool)	9016		10	8	\$11,355.00 / EA	1	\$11,355	\$15,540	On File
Pool/Spa - Heater (Spa)	9017		10	8	\$9,000.00 / EA	1	\$9,000	\$12,317	On File
Pool/Spa - Mastic/Waterproof	9018		3	1	\$9.50 / LF	324	\$3,078	\$3,201	On File
Pool/Spa - Pumps/Motors	9019		10	8	\$3,500.00 / EA	4	\$14,000	\$19,160	On File
Solar Stubs			10	8	\$11,350.00 / Total	1	\$11,350	\$15,533	On File
Spa - Resurface/Tile	9020		10	8	\$5,400.00 / EA	1	\$5,400	\$7,390	On File



Component Inventory

Units: 2,887 | Start Date: 7/1/2023

_									-
Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
						Totals	\$1,140,492	\$4,039,197	
						* Non-rese	erve components exc	uded from totals	
Septic Systems									
Septic System - Campground	9021		30	0	\$16,000.00 / Total	1	\$16,000	\$16,000	On File
Life extended.				-			+,		
Septic System - Clubhouse	1101		10	0	\$118,000.00 / Total	1	\$118,000	\$118,000	On File
Septic System - Golf Course	1102		30	4	\$17,000.00 / Total	1	\$17,000	\$19,888	On File
Septic System - Golf Pro-Shop	1103		30	2	\$23,000.00 / Total	1	\$23,000	\$24,877	On File
Septic System - Grease Trap			30	0	\$16,700.00 / Total	1	\$16,700	\$16,700	On File
Septic System - Lampkin Park	1104		30	0	\$32,000.00 / Total	1	\$32,000	\$32,000	On File
Septic System - Maint Bldg	1105		30	24	\$32,000.00 / Total	1	\$32,000	\$82,026	On File
Septic System - Oil Seperater			30	0	\$16,700.00 / Total	1	\$16,700	\$16,700	On File
Septic System - Stables	1106		30	24	\$22,980.00 / Total	1	\$22,980	\$58,905	On File
						Totals	\$294,380	\$385,095	
Stables									
Stables - Arena & Pen	1201		20	16	\$3.37 / SF	13,800	\$46,506	\$87,105	On File
Upgrades/Maint									
Round Pen upgrades completed	l in FY 2019	-20 for a repo	orted \$44,	451.					
Stables - Breakroom			0	0	\$0.00 /	0	\$0*	\$0*	On File
(Remodel/Appliances)									
(Maintenance / Operating)									
Stables - Comp Shingle	1202		25	9	\$7.25 / SF	4,540	\$32,915	\$46,848	On File
Roofing									
Stable & Hay Barn.									
Stables - Ext Wood (Paint)	1203		5	4	\$2.32 / SF	8,500	\$19,720	\$23,070	On File
Stables - Ext Wood (Repairs-	1204		15	14	\$15.00 / SF	8,500	\$25,500	\$44,158	On File
20%)	1205		20	10	Ć70.00 (F	420	¢16.264	670.460	
Stables - Fencing (Arena Fencing)	1205		20	16	\$38.00 / LF	428	\$16,264	\$30,462	On File
Stables - Fencing (Split Rail)	1207		20	10	\$25.00 / LF	1,768	\$44,200	\$65,427	On File
Includes fencing at stables and a	ilong Aleuti	ian Drive.				·			
Stables - Horse Watering	1208		20	0	\$43,260,00 / Total	1	\$43,260	\$43,260	On File
System									
Stables - Hot Walker	1209		18	0	\$8,400.00 / EA	1	\$8,400	\$8,400	On File
Replaced in 2019.									
Stables - Lighting (Bldg &	1210		0	0	\$0.00 /	0	\$0*	\$0*	On File
Perimeter)									
(Maintenance / Operating)									
Stables - Lower Barn Rebuild	1211		30	3	\$51,912.00 / Total	1	\$51,912	\$58,394	On File
Stables - Office/RR (Refurb)	1212		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Maintenance / Operating)									
Stables - Panels/Gates	1206		10	9	\$33,450.00 / Total	1	\$33,450	\$47,610	On File
(Contingency) - 1									
Stables - Panels/Gates			10	9	\$44,885.00 / Total	1	\$44,885	\$63,885	On File
(Contingency) - 2									
Stables - Round Pen			20		\$83,500.00 / Total	1	\$83,500	\$138,013	On File
Stables - Structures	1213		0	0	\$0.00 /	0	\$0*	\$0*	On File
(Repair/Replace/Upgrades)									
(Maintenance / Operating)						.	A	*	
						Totals	\$450,512	\$656,631	

Tennis Courts

info@smartproperty.com | 877-864-8955 | www.smartproperty.com



Component Inventory

Units: 2,887 | Start Date: 7/1/2023

Component	GL Code	Project Number	UL	RUL	Unit Price	Quantity	Current Replacement Cost	Anticipated Expenditures	Source
Tennis Cts - Chain Link Fence	1301		35	10	\$42.00 / LF	475	\$19,950	\$29,531	On File
Tennis Cts - Lighting	1302		20	0	\$2,025.00 / EA	12	\$24,300	\$24,300	On File
Tennis Cts - Lighting (Paint) (Maintenance / Operating)	1303		0	0	\$0.00 /	0	\$0*	\$0*	On File
Tennis Cts - Nets / Furnishings / Divider (Maintenance / Operating)	1304		0	0	\$0.00 /	0	\$0*	\$0*	On File
Tennis Cts - Replace	1305		50	25	\$56,000.00 / EA	2	\$112,000	\$298,574	On File
Tennis Cts - Resurface	1306		5	0	\$9,732.00 / EA	2	\$19,464	\$19,464	On File
Tennis Cts - Windscreens	1307		10	5	\$9,000.00 / EA	1	\$9,000	\$10,950	On File
						Totals	\$184,714	\$382,818	

* Non-reserve components excluded from totals

Measure key: SF = Square Feet, EA = Each, SY = Square Yard(s), LF = Linear Feet, ALW = Allowance, BLD = Building(s), CY = Cubic Yard(s), LT = Lot, PLC = Place(s), SQ = Square(s), TN = Ton(s), LS = Lump Sum



Units: 2,887 | Start Date: 7/1/2023



Clubhouse - Exterior

Clubhouse - Exterior

1031

1034

Gal

Ext - Backflow Device

Ext - Paint/Repairs



\$11,350

\$19,465

\$11,804

\$20,244

Anticipated Expenditures (5 Years)

						•
Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Golf Course - Cart Paths		2003		Golf Course	\$17,161	\$17,847
(Concrete Repairs 10%)						
Golf Course - Spillway (Repairs)		2013		Golf Course	\$129,780	\$134,971
Pavilion (Ext) - Balc/Walkway		8001		Pavilion	\$51,000	\$53,040
(Repair/Replace)						
Pavilion (Ext) -		8002		Pavilion	\$18,600	\$19,344
Paint/Repairs/Replace						
Pavilion (Ext) - Roofing		8003		Pavilion	\$26,000	\$27,040
(Flat/Mansards)						
Pavilion (Int) -		8004		Pavilion	\$14,000	\$14,560
Furnishings/Carpeting/Miscl						
Pavilion (Int) - Kitchen		8005		Pavilion	\$17,000	\$17,680
(Remodel/Refurbish)					<i> </i>	+
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$3,201
Pro Shop -		3002		Golf Course - Pro Shop	\$28,000	\$29,120
Furnishings/Displays/Flooring				ч	,	<i>+</i> / - _/
Pro Shop - Golf Carts		3003		Golf Course - Pro Shop	\$67,500	\$70,200
Water Tank - 2,000 Gal		6071		Maintenance - Equipment	\$8,650	\$8,996
Watering Tank		6072		Maintenance - Equipment	\$17,845	\$18,559
		0072		• •	al for 2024-2025:	\$18,559
2025-2026				TOU	at 101 2024-2025.	30 4 ,002
					<u> </u>	
Bar - Flooring/Furnishings		1016		Clubhouse - Bar	\$52,000	\$56,243
Cinder Spreader - Meyer (#012- 1)		6008		Maintenance - Equipment	\$9,000	\$9,734
Cinder Spreader - Meyer (#012- 2)		6009		Maintenance - Equipment	\$9,000	\$9,734
Clubhouse - Remodel/Design Phase 3		1041		Clubhouse - General	\$2,000,000	\$2,163,200
Front Loader - Komatsu 250 (#2041)		6015		Maintenance - Equipment	\$200,000	\$216,320
Golf - Green Roller (#158)		6018		Maintenance - Equipment	\$12,735	\$13,774
Golf - Sod Cutters		6023		Maintenance - Equipment	\$17,300	\$18,712
Golf - Toro Green Mower (#157)		6024		Maintenance - Equipment	\$60,000	\$64,896
Golf Course - Aerators		2001		Golf Course	\$17,025	\$18,414
Golf Course - Wood Ret Walls (Repairs)		2018		Golf Course	\$17,300	\$18,712
HOA/Patrol Offices - Computers/Equipment		1053		Clubhouse - Offices	\$80,000	\$86,528
Septic System - Golf Pro-Shop		1103		Septic Systems	\$23,000	\$24,877
Trash Receptacles		7009		Miscellaneous	\$97,335	\$105,278
Utility Room - Furnishings/Miscl		1060		Clubhouse - Utility Room	\$97,333	\$105,278
				•		
Utility Room - Kitchen		1061		Clubhouse - Utility Room	\$6,000	\$6,490
(Appliances)		1062		Clubbeurg Litility Deem	<u> </u>	¢0.756
Utility Room - Kitchen (Refurbish)		1062		Clubhouse - Utility Room	\$8,650	\$9,356
				Tota	al for 2025-2026:	\$2,845,663
2026-2027						
2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$21,308
Asphalt - Roller CAT (#2055)		6004		Maintenance - Equipment	\$69,000	\$77,616
Bistro - Washer/Dryer (Whirlpool)		1028		Clubhouse - Bistro	\$1,730	\$1,946
EC Vehicle - Subaru (#161)		6031		Maintenance - Equipment	\$40,500	\$45,557



Anticipated Expenditures (5 Years)

Units: 2,887 | Start Date: 7/1/2023

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Ext - Roofing		1035		Clubhouse - Exterior	\$86,500	\$97,301
Golf Course - Cart Path's / Rehab (25%)		2004		Golf Course	\$46,001	\$51,744
Golf Course - Lake Systems (Maintenance)		2011		Golf Course	\$248,745	\$279,804
Lampkin - Chain Link Fencing (Field)		4005		Lampkin Park	\$14,300	\$16,086
Lobby - Flooring/Furnishings		1045		Clubhouse - Lobby	\$7,325	\$8,240
Lobby - Restrooms		1046		Clubhouse - Lobby	\$17,300	\$19,460
Maint Bldg - RV Chain Link		5004		Maintenance - Building	\$11,500	\$12,936
Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$44,802
Patrol Vehicle - Colorado extended				Maintenance - Equipment	\$37,850	\$42,576
Rec Rm - Flooring		1058		Clubhouse - Rec Room	\$9,300	\$10,461
Snow Plow - Blade (#131)		6041		Maintenance - Equipment	\$21,630	\$24,331
Snow Plow - Front Loader (#2041)		6043		Maintenance - Equipment	\$24,000	\$26,997
Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$11,818
Stables - Lower Barn Rebuild		1211		Stables	\$51,912	\$58,394
Truck - Dodge 3500 (#163)		6062		Maintenance - Equipment	\$50,000	\$56,243
Truck - Dodge 4500 (#171)		6063		Maintenance - Equipment	\$50,000	\$56,243
				Tota	l for 2026-2027:	\$963,862
2027-2028						
Emergency Preparedness - Equip/Materials		7002		Miscellaneous	\$17,000	\$19,888
Ext - Decking / Siding / Rails		1032		Clubhouse - Exterior	\$175,000	\$204,725
Forklift - Nissan 5K (#062)		6013		Maintenance - Equipment	\$14,000	\$16,378
Golf Course - Irr Pumps (Replace)		2009		Golf Course	\$68,100	\$79,667
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$3,601
Rec Rm - Furnishings/Miscl		1059		Clubhouse - Rec Room	\$10,815	\$12,652
Septic System - Golf Course		1102		Septic Systems	\$17,000	\$19,888
Stables - Ext Wood (Paint)		1203		Stables	\$19,720	\$23,070
Trash Compactor (A)		6053		Maintenance - Equipment	\$23,790	\$27,831
Trash Compactor (B)		6054		Maintenance - Equipment	\$23,790	\$27,831
Truck - Dodge 5500 (#172)		6064		Maintenance - Equipment	\$82,000	\$95,928
				Tota	l for 2027-2028:	\$531,459



Target - 75% Funded in 30 Years

This plan represents a first-year reserve contribution of \$797,310 or \$276.17 yearly per unit and is calculated to achieve the target funding goal of 75% in 30 years. Upon meeting the designated target, the funding will adjust to maintain this percentage for the remaining years. Assumptions used in this model include a component inflation factor of 4% per year, annual average interest rate of 3% per year and a varied annual contribution rate calculated to meet target requirements.



Annual **Yearly Reserve** Starting Interest Total Anticipated Ending **Fully Funded** Percent Year Reserve Contributions Reserve Earned Reserve **Expenditures** Reserve Reserve Funded Contributions (Avg. Per Unit) Funds Balance Balance Balance 2023-2024 48% \$797.310 \$276.17 \$4,100,000 \$124,105 \$5,021,415 \$723,614 \$4,297,801 \$8,982,038 2024-2025 \$829,202 \$287.22 \$4,297,801 \$132,599 \$5,259,603 \$584,862 \$4,674,741 \$9,467,911 49% 2025-2026 \$298.71 \$4,674,741 \$110,493 \$5,647,604 \$2,845,663 37% \$862,370 \$2,801,941 \$7,650,436 2026-2027 \$310.66 \$2,801,941 \$83.053 \$3,781,860 \$963.862 \$2,817,998 \$7,747,678 36% \$896.865 2027-2028 \$932,740 \$323.08 \$2,817,998 \$90,559 \$3,841,297 \$531,459 \$3,309,838 \$8,329,256 40% 2028-2029 \$970,050 \$336.01 \$3,309,838 \$76,938 \$2,460,515 \$1,896,311 \$6,959,830 27% \$4,356,826 2029-2030 \$1,008,852 \$349.45 \$1,896,311 \$58,699 \$2,963,862 \$888,178 \$2,075,684 \$7,204,060 29% 2030-2031 \$1,049,206 \$2,075,684 \$66,036 \$3,190,926 \$2,392,776 \$7,586,195 32% \$363.42 \$798,149 2031-2032 \$1,091,174 \$377.96 \$2,392,776 \$57,591 \$3,541,541 \$2,037,319 \$1,504,222 22% \$6,731,857 2032-2033 \$1,134,821 \$393,08 \$1,504,222 \$54,892 \$2,693,935 \$483,812 \$2,210,123 \$7,496,291 29% 2033-2034 \$1,180,214 \$408.80 \$2,210,123 \$65,643 \$3,455,980 \$1,224,254 \$2,231,726 \$7,560,007 30% 37% 2034-2035 \$425.15 \$78,771 \$3,537,919 \$439,469 \$3,098,450 \$8,482,732 \$1,227,422 \$2,231,726 2035-2036 \$1,276,519 \$442.16 \$3.098.450 \$101.704 \$4,476,673 \$693.164 \$3,783,509 \$9,220,391 41% 2036-2037 \$1,327,580 \$459.85 \$3,783,509 \$114,214 \$5,225,303 \$1,280,338 \$3,944,965 \$9,421,453 42% 2037-2038 \$1,380,683 \$478.24 \$3,944,965 \$130,551 \$5,456,199 \$567,209 \$4,888,990 \$10,417,463 47% 2038-2039 \$1,435,910 \$497.37 \$4,888,990 \$158,671 \$6,483,571 \$635,818 \$5,847,754 \$11,428,990 51% \$175,693 2039-2040 52% \$1,493,347 \$517.27 \$5,847,754 \$7.516.794 \$1,475,978 \$6,040,816 \$11,656,783 2040-2041 \$1,553,081 \$537.96 \$6,040,816 \$196,926 \$7,790,822 \$506,332 \$7,284,490 \$12,954,320 56% 2041-2042 \$223,770 58% \$1,615,204 \$559,47 \$7,284,490 \$9,123,465 \$1,266,153 \$7,857,312 \$13,567,905 2042-2043 \$1,679,812 \$581.85 \$7,857,312 \$244,767 \$9,781,890 \$1,076,663 \$8,705,227 \$14,458,086 60% 2043-2044 \$1,747,004 \$605.13 \$8,705,227 \$265,612 \$10,717,843 \$1,450,014 \$9,267,829 \$15,057,701 62% 2044-2045 \$297,879 65% \$1.816.885 \$629.33 \$9.267.829 \$11.382.593 \$493,924 \$10.888.668 \$16.735.175 65% 2045-2046 \$1,889,560 \$654.51 \$10,888,668 \$319,357 \$13,097,585 \$2,376,419 \$10,721,166 \$16,583,836 2046-2047 \$1,965,142 \$680.69 \$10,721,166 \$321,024 \$13,007,333 \$2,005,858 \$11,001,475 \$16,877,551 65% 2047-2048 67% \$2,043,748 \$707,91 \$11,001,475 \$338,385 \$13,383,607 \$1,487,729 \$11,895,879 \$17,788,758 \$369,797 69% 2048-2049 \$2,125,498 \$736.23 \$11,895,879 \$14,391,174 \$1,264,092 \$13,127,082 \$19,038,516 2049-2050 \$2,210,518 \$765.68 \$13,127,082 \$394,800 \$15,732,400 \$2,144,713 \$13,587,686 \$19,494,674 70% 2050-2051 \$2,298,939 \$796.31 \$13,587,686 \$440,205 \$16,326,830 \$127,324 \$16,199,506 \$22,142,265 73% 73% 2051-2052 \$2,390,896 \$828.16 \$16,199,506 \$474,614 \$19,065,016 \$3,148,959 \$15,916,058 \$21,835,302 2052-2053 \$2,486,532 \$861,29 \$15,916,058 \$497,993 \$18,900,583 \$1,119,097 \$17,781,486 \$23,708,368 75%



2023-2024 Reserve Budget (TBD) -

Pine Mountain Club Property Owner's Association

Units: 2,887 | Start Date: 7/1/2023

Ladder

Variable Annual Increase Funding Model

This plan represents first-year reserve contribution of \$706,522 or \$2.11.32 years per unit and incorporates the following valuable annual incorporates as they occur over the projected 30 years. If designated future year increases are not maintained the association may be unable to meet all future expense requirements. If adopted, this plan should be reviewed annually and adjusted accordingly to ensure all funding goals and expectations are being met.



🗾 Total Reserve Funds 🛛 🔄 Anticipated Expenditures 📰 Ending Reserve Balance

Year	Annual Reserve Contributions	Yearly Reserve Contributions (Avg. Per Unit)	Starting Reserve Balance	Interest Earned	Total Reserve Funds	Anticipated Expenditures	Ending Reserve Balance	Fully Funded Reserve Balance	Percent Funded
Duration: 1 yea	rs	Rat	e of Annual Rese	rve Contributio	n Increases: 20.0	00%	Add	ditional Funds To R	leserves: \$0.00
2023-2024	\$706,212	\$244.62	\$4,100,000	\$122,739	\$4,928,951	\$723,614	\$4,205,337	\$8,982,038	47%
Duration: 1 yea	rs	Rat	e of Annual Rese	rve Contributio	n Increases: 19.0	0%	Add	ditional Funds To R	leserves: \$0.00
2024-2025	\$847,454	\$293.54	\$4,205,337	\$130,099	\$5,182,890	\$584,862	\$4,598,028	\$9,467,911	49%
Duration: 1 yea	rs	Rat	e of Annual Rese	erve Contributio	on Increases: 18.0	0%	Ado	ditional Funds To R	leserves: \$0.00
2025-2026	\$1,008,471	\$349.31	\$4,598,028	\$110,383	\$5,716,882	\$2,845,663	\$2,871,219	\$7,650,436	38%
Duration: 27 ye	ars	Ra	te of Annual Res	erve Contributi	on Increases: 2.5	0%	Ade	ditional Funds To R	eserves: \$0.00
2026-2027	\$1,189,995	\$412,19	\$2,871,219	\$89,529	\$4,150,743	\$963,862	\$3,186,881	\$7,747,678	41%
2027-2028	\$1,219,745	\$422.50	\$3,186,881	\$105,931	\$4,512,557	\$531,459	\$3,981,098	\$8,329,256	48%
2028-2029	\$1,250,239	\$433.06	\$3,981,098	\$101,279	\$5,332,616	\$2,460,515	\$2,872,101	\$6,959,830	41%
2029-2030	\$1,281,495	\$443.88	\$2,872,101	\$92,063	\$4,245,659	\$888,178	\$3,357,481	\$7,204,060	47%
2030-2031	\$1,313,532	\$454.98	\$3,357,481	\$108,455	\$4,779,468	\$798,149	\$3,981,319	\$7,586,195	52%
2031-2032	\$1,346,371	\$466.36	\$3,981,319	\$109,075	\$5,436,765	\$2,037,319	\$3,399,446	\$6,731,857	50%
2032-2033	\$1,380,030	\$478.02	\$3,399,446	\$115,427	\$4,894,903	\$483,812	\$4,411,091	\$7,496,291	59%
2033-2034	\$1,414,531	\$489.97	\$4,411,091	\$135,187	\$5,960,808	\$1,224,254	\$4,736,554	\$7,560,007	63%
2034-2035	\$1,449,894	\$502.21	\$4,736,554	\$157,253	\$6,343,701	\$439,469	\$5,904,232	\$8,482,732	70%
2035-2036	\$1,486,141	\$514,77	\$5,904,232	\$189,022	\$7,579,395	\$693,164	\$6,886,232	\$9,220,391	75%
2036-2037	\$1,523,295	\$527.64	\$6,886,232	\$210,231	\$8,619,758	\$1,280,338	\$7,339,420	\$9,421,453	78%
2037-2038	\$1,561,377	\$540.83	\$7,339,420	\$235,095	\$9,135,892	\$567,209	\$8,568,683	\$10,417,463	82%
2038-2039	\$1,600,412	\$554.35	\$8,568,683	\$271,529	\$10,440,624	\$635,818	\$9,804,807	\$11,428,990	86%
2039-2040	\$1,640,422	\$568.21	\$9,804,807	\$296,611	\$11,741,839	\$1,475,978	\$10,265,861	\$11,656,783	88%
2040-2041	\$1,681,432	\$582.42	\$10,265,861	\$325,602	\$12,272,896	\$506,332	\$11,766,565	\$12,954,320	91%
2041-2042	\$1,723,468	\$596.98	\$11,766,565	\$359,857	\$13,849,890	\$1,266,153	\$12,583,737	\$13,567,905	93%
2042-2043	\$1,766,555	\$611.90	\$12,583,737	\$387,860	\$14,738,152	\$1,076,663	\$13,661,489	\$14,458,086	94%
2043-2044	\$1,810,719	\$627.20	\$13,661,489	\$415,255	\$15,887,463	\$1,450,014	\$14,437,449	\$15,057,701	96%
2044-2045	\$1,855,987	\$642.88	\$14,437,449	\$453,554	\$16,746,990	\$493,924	\$16,253,066	\$16,735,175	97%
2045-2046	\$1,902,386	\$658.95	\$16,253,066	\$480,481	\$18,635,934	\$2,376,419	\$16,259,514	\$16,583,836	98%
2046-2047	\$1,949,946	\$675.42	\$16,259,514	\$486,947	\$18,696,407	\$2,005,858	\$16,690,549	\$16,877,551	99%
2047-2048	\$1,998,695	\$692.31	\$16,690,549	\$508,381	\$19,197,625	\$1,487,729	\$17,709,896	\$17,788,758	100%
2048-2049	\$2,048,662	\$709.62	\$17,709,896	\$543,065	\$20,301,624	\$1,264,092	\$19,037,532	\$19,038,516	100%
2049-2050	\$2,099,879	\$727.36	\$19,037,532	\$570,453	\$21,707,864	\$2,144,713	\$19,563,151	\$19,494,674	100%
2050-2051	\$2,152,376	\$745.54	\$19,563,151	\$617,270	\$22,332,797	\$127,324	\$22,205,473	\$22,142,265	100%
2051-2052	\$2,206,185	\$764.18	\$22,205,473	\$652,023	\$25,063,681	\$3,148,959	\$21,914,723	\$21,835,302	100%
2052-2053	\$2,261,340	\$783.28	\$21,914,723	\$674,575	\$24,850,638	\$1,119,097	\$23,731,541	\$23,708,368	100%



Minimum Threshold

Units: 2,887 | Start Date: 7/1/2023

Min Balance: \$675,000 (5% of Current Replacement Cost)

This plan represents the minimum annual reserve contribution of \$728,390 or \$252.30 yearly per unit for the first year of implementation to meet all future anticipated expenditures each year over the next 30 years. The minimum threshold amount is calculated by ensuring the ending reserve balance is equal to or greater than \$675,000 (or 5% of the current replacement cost) over the duration of the plan. The annual reserve contributions may also fluctuate from year to year because the plan only takes into consideration meeting anticipated expenditures.



🗾 Total Reserve Funds 🔄 Anticipated Expenditures 🔛 Ending Reserve Balance

Year	Annual	Yearly Reserve	Starting	Interest	Total	Anticipated	Ending	Fully Funded	Percent
	Reserve	Contributions	Reserve	Earned	Reserve	Expenditures	Reserve	Reserve	Funded
	Contributions	(Avg. Per Unit)	Balance		Funds		Balance	Balance	
2023-2024	\$728,390	\$252.30	\$4,100,000	\$123,072	\$4,951,462	\$723,614	\$4,227,848	\$8,982,038	47%
2024-2025	\$757,526	\$262.39	\$4,227,848	\$129,425	\$5,114,799	\$584,862	\$4,529,936	\$9,467,911	48%
2025-2026	\$787,827	\$272.89	\$4,529,936	\$105,031	\$5,422,793	\$2,845,663	\$2,577,131	\$7,650,436	34%
2026-2027	\$819,340	\$283.80	\$2,577,131	\$75,146	\$3,471,617	\$963,862	\$2,507,754	\$7,747,678	32%
2027-2028	\$852,113	\$295.16	\$2,507,754	\$80,042	\$3,439,910	\$531,459	\$2,908,452	\$8,329,256	35%
2028-2029	\$886,198	\$306.96	\$2,908,452	\$63,639	\$3,858,288	\$2,460,515	\$1,397,773	\$6,959,830	20%
2029-2030	\$921,646	\$319.24	\$1,397,773	\$42,435	\$2,361,854	\$888,178	\$1,473,676	\$7,204,060	20%
2030-2031	\$958,512	\$332.01	\$1,473,676	\$46,616	\$2,478,803	\$798,149	\$1,680,654	\$7,586,195	22%
2031-2032	\$996,852	\$345.29	\$1,680,654	\$34,813	\$2,712,319	\$2,037,319	\$675,000	\$6,731,857	10%
2032-2033	\$812,599	\$281.47	\$675,000	\$25,182	\$1,512,781	\$483,812	\$1,028,969	\$7,496,291	14%
2033-2034	\$845,103	\$292.73	\$1,028,969	\$25,182	\$1,899,254	\$1,224,254	\$675,000	\$7,560,007	9%
2034-2035	\$878,907	\$304.44	\$675,000	\$26,842	\$1,580,749	\$439,469	\$1,141,280	\$8,482,732	13%
2035-2036	\$914,064	\$316.61	\$1,141,280	\$37,552	\$2,092,895	\$693,164	\$1,399,732	\$9,220,391	15%
2036-2037	\$950,626	\$329.28	\$1,399,732	\$37,046	\$2,387,404	\$1,280,338	\$1,107,066	\$9,421,453	12%
2037-2038	\$988,651	\$342.45	\$1,107,066	\$39,534	\$2,135,251	\$567,209	\$1,568,042	\$10,417,463	15%
2038-2039	\$1,028,197	\$356.15	\$1,568,042	\$52,927	\$2,649,166	\$635,818	\$2,013,348	\$11,428,990	18%
2039-2040	\$1,069,325	\$370.39	\$2,013,348	\$54,301	\$3,136,974	\$1,475,978	\$1,660,996	\$11,656,783	14%
2040-2041	\$1,112,098	\$385,21	\$1,660,996	\$58,916	\$2,832,011	\$506,332	\$2,325,679	\$12,954,320	18%
2041-2042	\$1,156,582	\$400.62	\$2,325,679	\$68,127	\$3,550,388	\$1,266,153	\$2,284,235	\$13,567,905	17%
2042-2043	\$1,202,845	\$416.64	\$2,284,235	\$70,420	\$3,557,500	\$1,076,663	\$2,480,837	\$14,458,086	17%
2043-2044	\$1,250,959	\$433.31	\$2,480,837	\$71,439	\$3,803,235	\$1,450,014	\$2,353,221	\$15,057,701	16%
2044-2045	\$1,300,997	\$450.64	\$2,353,221	\$82,703	\$3,736,921	\$493,924	\$3,242,997	\$16,735,175	19%
2045 - 2046	\$1,353,037	\$468.67	\$3,242,997	\$81,939	\$4,677,973	\$2,376,419	\$2,301,554	\$16,583,836	14%
2046-2047	\$1,407,159	\$487.41	\$2,301,554	\$60,066	\$3,768,779	\$2,005,858	\$1,762,921	\$16,877,551	10%
2047-2048	\$1,463,445	\$506.91	\$1,762,921	\$52,523	\$3,278,890	\$1,487,729	\$1,791,161	\$17,788,758	10%
2048-2049	\$1,521,983	\$527.18	\$1,791,161	\$57,603	\$3,370,747	\$1,264,092	\$2,106,655	\$19,038,516	11%
2049-2050	\$1,582,862	\$548.27	\$2,106,655	\$54,772	\$3,744,290	\$2,144,713	\$1,599,576	\$19,494,674	8%
2050-2051	\$1,646,177	\$570.20	\$1,599,576	\$70,770	\$3,316,523	\$127,324	\$3,189,199	\$22,142,265	14%
2051-2052	\$1,712,024	\$593.01	\$3,189,199	\$74,122	\$4,975,345	\$3,148,959	\$1,826,387	\$21,835,302	8%
2052-2053	\$1,780,505	\$616.73	\$1,826,387	\$64,713	\$3,671,604	\$1,119,097	\$2,552,507	\$23,708,368	11%



Target - 100% Funded in 30 Years

This plan represents a first-year reserve contribution of \$868,860 or \$300.96 yearly per unit and is calculated to achieve the target funding goal of 100% in 30 years. Upon meeting the designated target, the funding will adjust to maintain this percentage for the remaining years. Assumptions used in this model include a component inflation factor of 4% per year, annual average interest rate of 3% per year and a varied annual contribution rate calculated to meet target requirements.



🗾 Total Reserve Funds 🛛 🔄 Anticipated Expenditures 📰 Ending Reserve Balance

Year	Annual	Yearly Reserve	Starting	Interest	Total	Anticipated	Ending	Fully Funded	Percent
	Reserve	Contributions	Reserve	Earned	Reserve	Expenditures	Reserve	Reserve	Funded
	Contributions	(Avg. Per Unit)	Balance		Funds		Balance	Balance	
2023-2024	\$868,860	\$300.96	\$4,100,000	\$125,179	\$5,094,039	\$723,614	\$4,370,425	\$8,982,038	49%
2024-2025	\$903,614	\$312.99	\$4,370,425	\$135,894	\$5,409,933	\$584,862	\$4,825,071	\$9,467,911	51%
2025-2026	\$939,759	\$325.51	\$4,825,071	\$116,164	\$5,880,993	\$2,845,663	\$3,035,331	\$7,650,436	40%
2026-2027	\$977,349	\$338.53	\$3,035,331	\$91,262	\$4,103,942	\$963,862	\$3,140,080	\$7,747,678	41%
2027-2028	\$1,016,443	\$352.08	\$3,140,080	\$101,477	\$4,258,000	\$531,459	\$3,726,542	\$8,329,256	45%
2028-2029	\$1,057,101	\$366.16	\$3,726,542	\$90,745	\$4,874,388	\$2,460,515	\$2,413,873	\$6,959,830	35%
2029-2030	\$1,099,385	\$380.81	\$2,413,873	\$75,584	\$3,588,842	\$888,178	\$2,700,664	\$7,204,060	37%
2030-2031	\$1,143,360	\$396.04	\$2,700,664	\$86,198	\$3,930,223	\$798,149	\$3,132,073	\$7,586,195	41%
2031-2032	\$1,189,095	\$411.88	\$3,132,073	\$81,239	\$4,402,407	\$2,037,319	\$2,365,089	\$6,731,857	35%
2032-2033	\$1,236,659	\$428.35	\$2,365,089	\$82,245	\$3,683,993	\$483,812	\$3,200,180	\$7,496,291	43%
2033-2034	\$1,286,125	\$445.49	\$3,200,180	\$96,933	\$4,583,239	\$1,224,254	\$3,358,985	\$7,560,007	44%
2034-2035	\$1,337,570	\$463.31	\$3,358,985	\$114,241	\$4,810,796	\$439,469	\$4,371,327	\$8,482,732	52%
2035-2036	\$1,391,073	\$481.84	\$4,371,327	\$141,608	\$5,904,009	\$693,164	\$5,210,845	\$9,220,391	57%
2036-2037	\$1,446,716	\$501.11	\$5,210,845	\$158,821	\$6,816,382	\$1,280,338	\$5,536,044	\$9,421,453	59%
2037-2038	\$1,504,584	\$521.16	\$5,536,044	\$180,142	\$7,220,770	\$567,209	\$6,653,561	\$10,417,463	64%
2038-2039	\$1,564,768	\$542.00	\$6,653,561	\$213,541	\$8,431,870	\$635,818	\$7,796,053	\$11,428,990	68%
2039-2040	\$1,627,358	\$563.68	\$7,796,053	\$236,152	\$9,659,563	\$1,475,978	\$8,183,585	\$11,656,783	70%
2040-2041	\$1,692,453	\$586.23	\$8,183,585	\$263,299	\$10,139,338	\$506,332	\$9,633,006	\$12,954,320	74%
2041-2042	\$1,760,151	\$609.68	\$9,633,006	\$296,400	\$11,689,557	\$1,266,153	\$10,423,404	\$13,567,905	77%
2042-2043	\$1,830,557	\$634.07	\$10,423,404	\$324,011	\$12,577,972	\$1,076,663	\$11,501,309	\$14,458,086	80%
2043-2044	\$1,903,779	\$659.43	\$11,501,309	\$351,846	\$13,756,934	\$1,450,014	\$12,306,920	\$15,057,701	82%
2044-2045	\$1,979,930	\$685.81	\$12,306,920	\$391,498	\$14,678,348	\$493,924	\$14,184,423	\$16,735,175	85%
2045 - 2046	\$2,059,128	\$713,24	\$14,184,423	\$420,773	\$16,664,324	\$2,376,419	\$14,287,905	\$16,583,836	86%
2046-2047	\$2,141,493	\$741.77	\$14,287,905	\$430,672	\$16,860,069	\$2,005,858	\$14,854,211	\$16,877,551	88%
2047-2048	\$2,227,152	\$771.44	\$14,854,211	\$456,718	\$17,538,081	\$1,487,729	\$16,050,353	\$17,788,758	90%
2048-2049	\$2,316,239	\$802.30	\$16,050,353	\$497,293	\$18,863,884	\$1,264,092	\$17,599,792	\$19,038,516	92%
2049-2050	\$2,408,888	\$834.39	\$17,599,792	\$531,956	\$20,540,637	\$2,144,713	\$18,395,923	\$19,494,674	94%
2050-2051	\$2,505,244	\$867.77	\$18,395,923	\$587,547	\$21,488,714	\$127,324	\$21,361,390	\$22,142,265	96%
2051-2052	\$2,605,453	\$902.48	\$21,361,390	\$632,689	\$24,599,532	\$3,148,959	\$21,450,574	\$21,835,302	98%
2052-2053	\$2,709,672	\$938.58	\$21,450,574	\$667,376	\$24,827,621	\$1,119,097	\$23,708,524	\$23,708,368	100%



Units: 2,887 | Start Date: 7/1/2023

Current Percent Funded: 47%

					Cu	rentrei	aed: 47%	
Component	UL	RUL	Effective	Current	Starting	Annual	Fully	Annual
			Age	Replacement	Reserve	Fully	Funded	Reserve
				Cost	Balance	Funding	Reserve	Contrib.
			C	P	-	Reqmt.	Balance	
ASPHALT & CONCRETE SURFACES	A	В	С	D	E	F	G	Н
Asphalt (Campground) - Repair/Replace	25	24	1	\$122,500	\$2,314	\$4,900	\$4,900	\$5,078
Asphalt (Clubhouse) - Repair/Replace	25	6	19	\$175,875	\$63,134	\$7,035	\$133,665	\$7,290
Asphalt (Maint Yard) - Repair/Replace (1)	30	20	19	\$175,875	\$8,266	\$1,750	\$133,003	\$1,813
Asphalt (Maint Yard) - Repair/Replace (2)	30	29	10	\$52,500	\$827	\$1,750	\$1,750	\$1,813
Asphalt (Maint Yard) - Repair/Replace (3)	30	8	22	\$52,500	\$18,185	\$1,750	\$38,500	\$1,813
Concrete - Kitchen Access Road	30	28	22	\$40,000	\$1,260	\$1,333	\$38,500	\$1,382
Concrete - Repair Contingency	5	1	4	\$40,000	\$9,447	\$5,000	\$20,000	\$5,181
	J	- 1	Total	\$520,875	\$103,432	\$23,518	\$218,982	\$24,371
			Totat	3320,873	3103,432	\$25,510	3210,302	324,371
CAMPGROUND								
Campground - Comp Shingle Roof	20	17	3	\$4,000	\$283	\$200	\$600	\$207
Campground - Furnishings	20	16	4	\$17,000	\$1,606	\$850	\$3,400	\$881
Campground - Restrooms (Refurb)	15	11	4	\$8,000	\$1,008	\$533	\$2,133	\$553
			Total	\$29,000	\$2,897	\$1,583	\$6,133	\$1,641
CLUBHOUSE - BAR								
Bar - Appliances/Serving Systems	12	7	5	\$28,000	\$5,511	\$2,333	\$11,667	\$2,418
Bar - Audio/Video Equip.	8	0	8	\$5,400	\$2,551	\$675	\$5,400	\$699
Bar - Flooring/Furnishings	10	2	8	\$52,000	\$19,649	\$5,200	\$41,600	\$5,389
Bar - Remodel/Refurbish	30	24	6	\$56,000	\$5,290	\$1,867	\$11,200	\$1,934
Bar - Restroom (Refurb)	12	0	12	\$4,500	\$2,125	\$375	\$4,500	\$389
			Total	\$145,900	\$35,126	\$10,450	\$74,367	\$10,829
CLUBHOUSE - BISTRO								
Bistro - Flooring	20	15	5	\$13,338	\$1,575	\$667	\$3,335	\$691
Bistro - Furnishings (Chairs/Tables)	10	5	5	\$17,800	\$4,204	\$1,780	\$8,900	\$1,845
Bistro - Office/Equip (Refurb)	5	0	5	\$3,245	\$1,533	\$649	\$3,245	\$673
Bistro - Restroom	14	0	14	\$4,325	\$2,043	\$309	\$4,325	\$320
Bistro - Washer/Dryer (Whirlpool)	10	3	7	\$1,730	\$572	\$173	\$1,211	\$179
Kitchen - Appliances/Cookware	12	0	12	\$108,000	\$51,012	\$9,000	\$108,000	\$9,326
Kitchen - Flooring/Prep Stations	15	0	15	\$23,000	\$10,864	\$1,533	\$23,000	\$1,589
			Total	\$171,438	\$71,802	\$14,111	\$152,016	\$14,623
CLUBHOUSE - EXTERIOR								
Decking, Ramps, Rails (New)	22	20	2	\$275,000	\$11,808	\$12,500	\$25,000	\$12,953
Ext - Backflow Device	18	1	17	\$11,350	\$5,063	\$631	\$10,719	\$653
Ext - Decking / Siding / Rails	22	4	18	\$175,000	\$67,629	\$7,955	\$143,182	\$8,243
Ext - Lighting	15	9	6	\$34,600	\$6,537	\$2,307	\$13,840	\$2,390
Ext - Paint/Repairs	5	1	4	\$19,465	\$7,355	\$3,893	\$15,572	\$4,034
Ext - Roofing	25	3	22	\$86,500	\$35,954	\$3,460	\$76,120	\$3,585
			Total	\$601,915	\$134,347	\$30,745	\$284,433	\$31,860
CLUBHOUSE - GENERAL								
Clubhouse - Remodel/Design Phase 3	45	2	43	\$2,000,000	\$902,678	\$44,444	\$1,911,111	\$46,056
Clubhouse - Remodel/Design Phase 4	45	5	40	\$1,765,000	\$741,036	\$39,222	\$1,568,889	\$40,645
Clubhouse - Remodel/Design Phase 5 & 6	45	8	37	\$1,000,000	\$388,361	\$22,222	\$822,222	\$23,028
			Total	\$4,765,000	\$2,032,075	\$105,889	\$4,302,222	\$109,729
CLUBHOUSE - LOBBY								
Lobby - Flooring/Furnishings								
LODDy - HOOHING/FURNISHINGS	Z 0	7	27	67 Z7E	CZ 11 4	¢044	56 507	¢757
Lobby - Restrooms	30 15	3 3	27 12	\$7,325 \$17,300	\$3,114 \$6,537	\$244 \$1,153	\$6,593 \$13,840	\$253 \$1,195



Percent Funded Analysis

Component	UL	RUL	Effective Age	Current Replacement Cost	Starting Reserve Balance	Annual Fully Funding Reqmt.	Fully Funded Reserve Balance	Annual Reserve Contrib.
	А	В	С	D	E	F	G	н
			Total	\$24,625	\$9,651	\$1,398	\$20,433	\$1,448
CLUBHOUSE - MECH EQUIPMENT								
Club - Emergency Generator	25	12	13	\$118,500	\$29,105	\$4,740	\$61,620	\$4,912
Club - Fire Systems - Upgrade/Repairs	15	13	2	\$24,332	\$1,532	\$1,622	\$3,244	\$1,68
Club - Heating/Cooling Systems	15	13	2	\$54,075	\$3,406	\$3,605	\$7,210	\$3,736
Club - Sump Pumps - Lift Station	12	10	2	\$19,460	\$1,532	\$1,622	\$3,243	\$1,680
Club - Water Heat Systems	12	10	2	\$17,300	\$1,362	\$1,442	\$2,883	\$1,494
			Total	\$233,667	\$36,937	\$13,030	\$78,201	\$13,503
CLUBHOUSE - OFFICES								
HOA/Patrol Offices - Computers/Equipment	4	2	2	\$80,000	\$18,893	\$20,000	\$40,000	\$20,725
HOA/Patrol Offices - Furnishings/Flooring	14	0	14	\$55,500	\$26,214	\$3,964	\$55,500	\$4,108
HOA/Patrol Offices - Restrooms (Refurb)	12	0	12	\$17,300	\$8,171	\$1,442	\$17,300	\$1,494
Office - Phone System	10	8	2	\$16,900	\$1,596	\$1,690	\$3,380	\$1,75
			Total	\$169,700	\$54,875	\$27,096	\$116,180	\$28,079
CLUBHOUSE - PATROL OFFICES								
HOA/Patrol Offices - Security Cameras	10	5	5	\$40,000	\$9,447	\$4,000	\$20,000	\$4,145
HOA/Patrol Offices - Security Communications	20	18	2	\$32,000	\$1,511	\$1,600	\$3,200	\$1,658
Solar Powered Cameras	5	3	2	\$10,815	\$2,043	\$2,163	\$4,326	\$2,24
			Total	\$82,815	\$13,001	\$7,763	\$27,526	\$8,04
CLUBHOUSE - REC ROOM								
Rec Rm - Flooring	12	3	9	\$9,300	\$3,295	\$775	\$6,975	\$803
Rec Rm - Furnishings/Miscl	20	4	16	\$10,815	\$4,087	\$541	\$8,652	\$560
			Total	\$20,115	\$7,381	\$1,316	\$15,627	\$1,363
CLUBHOUSE - UTILITY ROOM								
Utility Room - Furnishings/Miscl	10	2	8	\$21,630	\$8,173	\$2,163	\$17,304	\$2,241
Utility Room - Kitchen (Appliances)	15	2	13	\$6,000	\$2,456	\$400	\$5,200	\$415
Utility Room - Kitchen (Refurbish)	25	2	23	\$8,650	\$3,759	\$346	\$7,958	\$359
		_	Total	\$36,280	\$14,388	\$2,909	\$30,462	\$3,014
GOLF COURSE					1	,_,		
Golf Course - Aerators	10	2	8	\$17,025	\$6,433	\$1,703	\$13,620	\$1,764
Golf Course - Bridges (Rebuild/Repair)	15	10	5	\$6,350	\$1,000	\$423	\$2,117	\$439
Golf Course - Cart Paths (Concrete Repairs 10%)	10	10	9	\$17,161	\$7,295	\$1,716	\$15,445	\$1,778
Golf Course - Cart Path's / Rehab (25%)	5	3	2	\$46,001	\$8,691	\$9,200	\$18,400	\$9,534
Golf Course - Course Restroom (Refurb)	15	10	5	\$40,000	\$6,298	\$2,667	\$13,333	\$2,763
Golf Course - Gate Valves (Canal)	20	0	20	\$8,800	\$4,157	\$440	\$8,800	\$450
Golf Course - Irr Pumps (Replace)	15	4	11	\$68,100	\$23,588	\$4,540	\$49,940	\$4,70
Golf Course - Irr System (Replace)	30	16	14	\$350,000	\$77,147	\$11,667	\$163,333	\$12,090
Golf Course - Lake Systems (Maintenance)	10	3	7	\$248,745	\$82,243	\$24,875	\$174,122	\$25,77
Golf Course - Spillway (Repairs)	30	1	29	\$129,780	\$59,256	\$4,326	\$125,454	\$4,483
Golf Course - Split Rail Fencing	20	14	6	\$31,824	\$4,509	\$1,591	\$9,547	\$1,649
Golf Course - Vertical Cutting Reels	12	11	1	\$8,595	\$338	\$716	\$716	\$742
Golf Course - Wood Ret Walls (Repairs)	20	2	18	\$17,300	\$7,354	\$865	\$15,570	\$896
· · · · · · · · · · · · · · · · · · ·			Total	\$989,680	\$288,310	\$64,728	\$610,397	\$67,076
GOLF COURSE - PRO SHOP								
Pro Shop - Furnishings/Displays/Flooring	10	1	9	\$28,000	\$11,903	\$2,800	\$25,200	\$2,902
Pro Shop - Golf Carts	10	1	11	\$67,500	\$29,226	\$5,625	\$61,875	\$5,829
	12	-		<i>407,000</i>	÷=>,==0	40,0L0	÷=1,0,0	-0,0L



Percent Funded Analysis

Component			Effective Age	Current Replacement Cost	Starting Reserve Balance	Annual Fully Funding Reqmt.	Fully Funded Reserve Balance	Annual Reserve Contrib.
	Α	В	С	D	E	F	G	Н
Lampkin - Baseball Field (Bleachers)	25	5	20	\$11,570	\$4,372	\$463	\$9,256	\$480
Lampkin - Bball Ct (Resurface)	20	19	1	\$61,982	\$1,464	\$3,099	\$3,099	\$3,211
Lampkin - Chain Link Fencing (Field)	30	3	27	\$14,300	\$6,079	\$477	\$12,870	\$494
Lampkin - Cover Structure (Repair/Replace)	25	8	17	\$17,300	\$5,557	\$692	\$11,764	\$717
Lampkin - Playground (Structures)	15	10	5	\$68,000	\$10,706	\$4,533	\$22,667	\$4,698
Lampkin - Restrooms (Refurbish)	15	6	9	\$6,490	\$1,839	\$433	\$3,894	\$448
Lampkin - Roofing (RR/Cover)	20	18	2	\$9,180	\$434	\$459	\$918	\$476
			Total	\$188,822	\$30,450	\$10,156	\$64,468	\$10,524
MAINTENANCE - BUILDING								
Maint Bldg - Comp Shingle Roofing	20	0	20	\$27,720	\$13,093	\$1,386	\$27,720	\$1,436
Maint Bldg - RV Chain Link	35	3	32	\$11,500	\$4,966	\$329	\$10,514	\$340
			Total	\$39,220	\$18,059	\$1,715	\$38,234	\$1,777
MAINTENANCE - EQUIPMENT								
2 Snow Plow kits (191 & 192)	5	3	2	\$19,500	\$3,684	\$3,900	\$7,800	\$4,041
2010 Dodge Truck 2500	15	1	14	\$43,260	\$19,071	\$2,884	\$40,376	\$2,989
Asphalt - Crack Filler	16	7	9	\$62,000	\$16,473	\$3,875	\$34,875	\$4,016
Asphalt - Roller CAT (#2055)	20	3	17	\$69,000	\$27,702	\$3,450	\$58,650	\$3,575
Auto Lift - Hydraulic	25	5	20	\$24,000	\$9,069	\$960	\$19,200	\$995
Backhoe - New Holland (#143)	20	11	9	\$86,000	\$18,279	\$4,300	\$38,700	\$4,456
Boat - Lake Maintenance (TBD)	20	19	1	\$8,650	\$10,275	\$433	\$433	\$448
Bobcat Compact Track Loader (2021)	10	8	2	\$142,000	\$13,414	\$14,200	\$28,400	\$14,715
Cardboard Bailer	25	23	2	\$16,000	\$13,414	\$640	\$1,280	\$663
Cinder Spreader - Meyer (#012-1)	15	23	13	\$10,000	\$3,684	\$600	\$7,800	\$622
	15	2	13	\$9,000	\$3,684	\$600	\$7,800	\$622
Cinder Spreader - Meyer (#012-2)	13	1						
Diesel Tank/Pump (1) - 2,000 Gal Diesel Tank/Pump (2) - 1,000 Gal		1	17	\$23,795	\$10,615	\$1,322	\$22,473	\$1,370
	18		17	\$17,500	\$7,807	\$972	\$16,528	\$1,007
Diesel Tank/Pump (3) - 2,000 Gal	18	1	17	\$23,800	\$10,617	\$1,322	\$22,478	\$1,370
EC Vehicle - Subaru (#161)	10	3	7	\$40,500	\$13,391	\$4,050	\$28,350	\$4,197
Forklift - Nissan 5K (#062)	15	4	11	\$14,000	\$4,849	\$933	\$10,267	\$967
Front Loader - JCB (#2081)	20	6	14	\$102,000	\$33,724	\$5,100	\$71,400	\$5,285
Front Loader - Komatsu 250 (#2041)	20	2	18	\$200,000	\$85,020	\$10,000	\$180,000	\$10,363
Front Loader - Komatsu WA 250 (#121)	20	10	10	\$183,000	\$43,218	\$9,150	\$91,500	\$9,482
Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box Blade	10	9	1	\$5,350	\$253	\$535	\$535	\$554
Golf - Aerator (ProCore 864)	10	6	4	\$38,800	\$7,331	\$3,880	\$15,520	\$4,021
Golf - Green Roller (#158)	10	2	8	\$12,735	\$4,812	\$1,274	\$10,188	\$1,320
Golf - Green Sweeper	15	14	1	\$11,680	\$368	\$779	\$779	\$807
Golf - Mower JD2500 (#2002)	10	9	1	\$34,770	\$1,642	\$3,477	\$3,477	\$3,603
Golf - Mower Reelmaster 3100-D Sidewinder	10	6	4	\$44,610	\$8,428	\$4,461	\$17,844	\$4,623
Golf - Sod Cutters	15	2	13	\$17,300	\$7,082	\$1,153	\$14,993	\$1,195
Golf - Toro Green Mower (#157)	10	2	8	\$60,000	\$22,672	\$6,000	\$48,000	\$6,218
Golf - Toro Rough Mower (#2093)	11	10	1	\$61,000	\$2,619	\$5,545	\$5,545	\$5,747
John Deere 5065E Utility Tractor	10	9	1	\$59,500	\$2,810	\$5,950	\$5,950	\$6,166
John Deere 520M Loader	10	9	1	\$12,600	\$595	\$1,260	\$1,260	\$1,306
Maintenance - Emergency Generator	25	22	3	\$32,000	\$1,814	\$1,280	\$3,840	\$1,326
Patrol Vehicle - Colorado Crew	5	3	2	\$41,000	\$7,746	\$8,200	\$16,400	\$8,497
Patrol Vehicle - Colorado extended	5	3	2	\$37,850	\$7,151	\$7,570	\$15,140	\$7,845
Roto Chopper (#141)	15	7	8	\$420,000	\$105,802	\$28,000	\$224,000	\$29,015
Snow Plow - Attachment (#163)	10	10	0	\$8,000	\$0	\$800	\$0	\$829
Snow Plow - Attachment (#182)	10	6	4	\$11,250	\$2,125	\$1,125	\$4,500	\$1,166



Percent Funded Analysis

Units: 2,887 | Start Date: 7/1/2023

Component			Effective Age	Current Replacement Cost	Starting Reserve Balance	Annual Fully Funding Reqmt.	Fully Funded Reserve Balance	Annual Reserve Contrib.
	Α	В	С	D	E	F	G	Н
Snow Plow - Blade (#131)	20	3	17	\$21,630	\$8,684	\$1,082	\$18,386	\$1,121
Snow Plow - Front Loader (#121)	20	11	9	\$32,000	\$6,802	\$1,600	\$14,400	\$1,658
Snow Plow - Front Loader (#2041)	15	3	12	\$24,000	\$9,069	\$1,600	\$19,200	\$1,658
Snow Plow - Front Loader (#2081)	20	6	14	\$30,000	\$9,919	\$1,500	\$21,000	\$1,554
Snow Plow (#171)	10	10	0	\$8,400	\$0	\$840	\$0	\$870
Snow Plow (#172)	10	10	0	\$8,400	\$0	\$840	\$0	\$870
Spreader - Turfco 1550	15	11	4	\$20,000	\$2,519	\$1,333	\$5,333	\$1,382
Street Sweeper (#2044)	15	0	15	\$102,000	\$48,178	\$6,800	\$102,000	\$7,047
Sweeper Vac - PTO (#2006)	16	7	9	\$28,000	\$7,439	\$1,750	\$15,750	\$1,813
Telehandler - Gradall (#061)	15	5	10	\$44,000	\$13,855	\$2,933	\$29,333	\$3,040
Tractor - John Deere (#083)	20	6	14	\$37,850	\$12,514	\$1,893	\$26,495	\$1,961
Trash Compactor (A)	20	4	16	\$23,790	\$8,989	\$1,190	\$19,032	\$1,233
Trash Compactor (B)	20	4	16	\$23,790	\$8,989	\$1,190	\$19,032	\$1,233
Truck - Dodge 2500 (#182)	10	5	5	\$56,000	\$13,225	\$5,600	\$28,000	\$5,803
Truck - Dodge 2500 (#2101)	10	6	4	\$56,000	\$10,580	\$5,600	\$22,400	\$5,803
Truck - Dodge 2500 (191)	10	6	4	\$56,000	\$10,580	\$5,600	\$22,400	\$5,803
Truck - Dodge 3500 (#163)	10	3	7	\$50,000	\$16,532	\$5,000	\$35,000	\$5,181
Truck - Dodge 4500 (#171)	10	3	7	\$50,000	\$16,532	\$5,000	\$35,000	\$5,181
Truck - Dodge 5500 (#172)	10	4	6	\$82,000	\$23,239	\$8,200	\$49,200	\$8,497
Truck - Ford F-550 (#131)	10	0	10	\$69,000	\$32,591	\$6,900	\$69,000	\$7,150
Truck - Trailer - Boander 20' (#142)	20	12	8	\$14,500	\$2,740	\$725	\$5,800	\$751
Utility Vehicle - John Deere Gator	8	5	3	\$18,385	\$3,256	\$2,298	\$6,894	\$2,381
Utility Vehicle - John Deere Gator (50014)	10	9	1	\$17,000	\$803	\$1,700	\$1,700	\$1,762
Utility Vehicle - John Deere Gator (50018)	10	9	1	\$17,000	\$803	\$1,700	\$1,700	\$1,762
Utility Vehicle - Kubota 1100	8	7	1	\$28,000	\$1,653	\$3,500	\$3,500	\$3,627
Utility Vehicle - Kubota 900	8	7	1	\$18,000	\$1,063	\$2,250	\$2,250	\$2,332
Water Tank - 2,000 Gal	10	1	9	\$8,650	\$3,677	\$865	\$7,785	\$896
Watering Tank	12	1	11	\$17,845	\$7,726	\$1,487	\$16,358	\$1,541
Welders (2) - Ranger	10	8	2	\$7,000	\$661	\$700	\$1,400	\$725
			Total	\$2,970,690	\$790,980	\$231,655	\$1,674,629	\$240,056
MISCELLANEOUS								
Electronic Speed limit sign	15	12	3	\$6,758	\$638	\$451	\$1,352	\$467
Emergency Preparedness - Equip/Materials	10	4	6	\$17,000	\$4,818	\$1,700	\$10,200	\$1,762
Entry Monuments - Maint/Refurb	10	9	1	\$6,500	\$307	\$650	\$650	\$674
Gazebo - Roofing/Repairs	25	9	16	\$21,630	\$6,539	\$865	\$13,843	\$897
Mailboxes	10	7	3	\$19,450	\$2,756	\$1,945	\$5,835	\$2,016
Mailboxes - Enclosure/Structure	20	, 17	3	\$17,450	\$1,913	\$1,350	\$4,050	\$1,399
Trash Receptacles	15	2		\$97,335	\$39,844	\$6,489	\$84,357	\$6,724
	15	2	Total	\$195,673	\$56,815	\$13,450	\$120,287	\$13,938
PAVILION			Totat	\$155,675	\$50,015	Ş13,430	<i>JILU, 20</i>	\$15,550
	10	-	F	617.000	67 007	¢1 700	66.050	64 440
Pavilion (Ext) - Balc/Patio Furnishings	10	5	5	\$13,900	\$3,283	\$1,390	\$6,950	\$1,440
Pavilion (Ext) - Balc/Walkway (Repair/Replace)	25	1	24	\$51,000	\$23,125	\$2,040	\$48,960	\$2,114
Pavilion (Ext) - Paint/Repairs/Replace	5	1	4	\$18,600	\$7,028	\$3,720	\$14,880	\$3,855
Pavilion (Ext) - Roofing (Flat/Mansards)	15	1	14	\$26,000	\$11,462	\$1,733	\$24,267	\$1,796
Pavilion (Int) - Furnishings/Carpeting/Miscl	10	1		\$14,000	\$5,951	\$1,400	\$12,600	\$1,451
Pavilion (Int) - Kitchen (Remodel/Refurbish)	15	1		\$17,000	\$7,494	\$1,133	\$15,867	\$1,174
			Total	\$140,500	\$58,344	\$11,417	\$123,523	\$11,831
POOL & SPA								
Pool - Resurface/Tile	12	10	2	\$23,795	\$1,873	\$1,983	\$3,966	\$2,055

Pine Mountain Club Property Owner's Association

info@smartproperty.com | 877-864-8955 | www.smartproperty.com

Percent Funded Analysis

Component	UL	RUL	Effective Age	Current Replacement Cost	Starting Reserve Balance	Annual Fully Funding Reqmt.	Fully Funded Reserve Balance	Annual Reserve Contrib.
	Α	В	С	D	E	F	G	н
Pool & Spa - Replace	40	38	2	\$225,000	\$5,314	\$5,625	\$11,250	\$5,829
Pool Area - Cover & Reel	15	13	2	\$7,000	\$441	\$467	\$933	\$484
Pool Area - Deck (Repairs - 5%)	10	8	2	\$14,040	\$1,326	\$1,404	\$2,808	\$1,455
Pool Area - Deck (Replace)	50	48	2	\$280,800	\$5,305	\$5,616	\$11,232	\$5,820
Pool Area - Deck (Reseal/Waterproof)	10	8	2	\$33,800	\$3,193	\$3,380	\$6,760	\$3,503
Pool Area - Ext Showers (Tile)	20	18	2	\$34,600	\$1,634	\$1,730	\$3,460	\$1,793
Pool Area - Furnishings	12	10	2	\$19,500	\$1,535	\$1,625	\$3,250	\$1,684
Pool Area - Pump Rm Roofing	25	23	2	\$2,958	\$112	\$118	\$237	\$123
Pool Area - Wood Trellis	20	18	2	\$13,600	\$642	\$680	\$1,360	\$705
Pool Bathrooms	30	28	2	\$297,000	\$9,352	\$9,900	\$19,800	\$10,259
Pool Equipment Room	30	28	2	\$19,000	\$598	\$633	\$1,267	\$656
Pool Shade Structure	30	28	2	\$27,000	\$850	\$900	\$1,800	\$933
Pool/Spa – Chem Systems	12	10	2	\$6,920	\$545	\$577	\$1,153	\$598
Pool/Spa - Coping	30	28	2	\$14,580	\$459	\$486	\$972	\$504
Pool/Spa – Fencing (W.I.)	25	23	2	\$27,716	\$1,047	\$1,109	\$2,217	\$1,149
Pool/Spa – Filters	15	13	2	\$39,000	\$2,456	\$2,600	\$5,200	\$2,694
Pool/Spa - Heater (Pool)	10	8	2	\$11,355	\$1,073	\$1,136	\$2,271	\$1,177
Pool/Spa - Heater (Spa)	10	8	2	\$9,000	\$850	\$900	\$1,800	\$933
Pool/Spa – Mastic/Waterproof	3	1	2	\$3,078	\$969	\$1,026	\$2,052	\$1,063
Pool/Spa – Pumps/Motors	10	8	2	\$14,000	\$1,323	\$1,400	\$2,800	\$1,451
Solar Stubs	10	8	2	\$11,350	\$1,072	\$1,135	\$2,270	\$1,431
Spa - Resurface/Tile	10	8	2	\$5,400	\$1,072	\$540	\$1,080	\$560
	10	0	Total	\$1,140,492	\$42,481	\$44,969	\$89,938	\$46,600
SEPTIC SYSTEMS			Totat	<i>Q1,110,132</i>	<i>Q</i> 12, 101	Q 1 1,505	<i>Q</i> 03 ,3 30	\$10,000
Septic System - Campground	30	0	30	\$16,000	\$7,557	\$533	\$16,000	\$553
Septic System - Clubhouse	10	0	10	\$118,000	\$55,735	\$11,800	\$118,000	\$12,228
Septic System - Golf Course	30	4	26	\$17,000	\$6,959	\$567	\$14,733	\$587
Septic System - Golf Pro-Shop	30	2	28	\$23,000	\$10,139	\$767	\$21,467	\$794
Septic System - Grease Trap	30	0	30	\$16,700	\$7,888	\$557	\$16,700	\$577
Septic System - Lampkin Park	30	0	30	\$32,000	\$15,115	\$1,067	\$32,000	\$1,105
Septic System - Maint Bldg	30	24	6	\$32,000	\$3,023	\$1,067	\$6,400	\$1,105
Septic System - Oil Seperater	30	0	30	\$16,700	\$7,888	\$557	\$16,700	\$577
Septic System - Stables	30	24	6	\$22,980	\$2,171	\$766	\$4,596	\$794
			Total	\$294,380	\$116,475	\$17,679	\$246,596	\$18,320
STABLES								
Stables - Arena & Pen Upgrades/Maint	20	16	4	\$46,506	\$4,393	\$2,325	\$9,301	\$2,410
Stables - Comp Shingle Roofing	25	9	16	\$32,915	\$9,950	\$1,317	\$21,066	\$1,364
Stables - Ext Wood (Paint)	5	4	1	\$19,720	\$1,863	\$3,944	\$3,944	\$4,087
Stables - Ext Wood (Repairs-20%)	15	14	1	\$25,500	\$803	\$1,700	\$1,700	\$1,762
Stables - Fencing (Arena Fencing)	20	16	4	\$16,264	\$1,536	\$813	\$3,253	\$843
Stables - Fencing (Split Rail)	20	10	10	\$44,200	\$10,439	\$2,210	\$22,100	\$2,290
Stables - Horse Watering System	20	0	20	\$43,260	\$20,433	\$2,163	\$43,260	\$2,241
Stables - Hot Walker	18	0	18	\$8,400	\$3,968	\$467	\$8,400	\$484
	30	3	27	\$51,912	\$22,068	\$1,730	\$46,721	\$1,793
Stables - Lower Barn Rebuild	50			•		•		
		9	1	\$33.450	\$1,580	\$3,345	\$3,345	\$3,466
Stables - Lower Barn Rebuild Stables - Panels/Gates (Contingency) - 1	10		1	\$33,450 \$44,885	\$1,580 \$2,120	\$3,345 \$4,489	\$3,345 \$4,489	
Stables - Lower Barn Rebuild		9 9 17	1 1 3	\$33,450 \$44,885 \$83,500	\$1,580 \$2,120 \$5,916	\$3,345 \$4,489 \$4,175	\$3,345 \$4,489 \$12,525	\$3,466 \$4,651 \$4,326

TENNIS COURTS



Percent Funded Analysis

Units: 2,887 | Start Date: 7/1/2023

Component	UL	RUL	Effective Age	Current Replacement Cost	Starting Reserve Balance	Annual Fully Funding	Fully Funded Reserve	Annual Reserve Contrib.
	А	в	с	D	Е	Reqmt.	Balance G	н
Tennis Cts - Chain Link Fence	35	10	25	\$19,950	\$6,731	\$570	\$14,250	\$591
Tennis Cts - Lighting	20	0	20	\$24,300	\$11,478	\$1,215	\$24,300	\$1,259
Tennis Cts - Replace	50	25	25	\$112,000	\$26,451	\$2,240	\$56,000	\$2,321
Tennis Cts - Resurface	5	0	5	\$19,464	\$9,193	\$3,893	\$19,464	\$4,034
Tennis Cts - Windscreens	10	5	5	\$9,000	\$2,125	\$900	\$4,500	\$933
			Total	\$184,714	\$55,978	\$8,818	\$118,514	\$9,138
			Totals	\$13,491,513	\$4,100,000	\$681,497	\$8,680,345	\$706,212

Percent Funded Calculations: Effective Age (Column C): (A) – (B) = (C). Starting Reserve Balance (Column E): G (Individual) / G (Total) * E (Total) = E (Individual). Annual Fully Funding Requirement (Column F): (D) / (A) = (F). Fully Funded Reserve Balance (Column G): (C) * (F) = (G)



Anticipated Expenditures (30 Years)



Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
2023-2024						
Bar - Audio/Video Equip.		1015		Clubhouse - Bar	\$5,400	\$5,400
Bar - Restroom (Refurb)		1020		Clubhouse - Bar	\$4,500	\$4,500
Bistro - Office/Equip (Refurb)		1025		Clubhouse - Bistro	\$3,245	\$3,245
Bistro - Restroom		1027		Clubhouse - Bistro	\$4,325	\$4,325
Golf Course - Gate Valves (Canal)		2008		Golf Course	\$8,800	\$8,800
HOA/Patrol Offices - Furnishings/Flooring		1054		Clubhouse - Offices	\$55,500	\$55,500
HOA/Patrol Offices - Restrooms (Refurb)		1055		Clubhouse - Offices	\$17,300	\$17,300
Kitchen - Appliances/Cookware		1029		Clubhouse - Bistro	\$108,000	\$108,000
Kitchen - Flooring/Prep Stations		1030		Clubhouse - Bistro	\$23,000	\$23,000
Maint Bldg - Comp Shingle Roofing		5001		Maintenance - Building	\$27,720	\$27,720
Septic System - Campground		9021		Septic Systems	\$16,000	\$16,000
Septic System - Clubhouse		1101		Septic Systems	\$118,000	\$118,000
Septic System - Grease Trap				Septic Systems	\$16,700	\$16,700
Septic System - Lampkin Park		1104		Septic Systems	\$32,000	\$32,000
Septic System - Oil Seperater				Septic Systems	\$16,700	\$16,700
Stables - Horse Watering System		1208		Stables	\$43,260	\$43,260
Stables - Hot Walker		1209		Stables	\$8,400	\$8,400
Street Sweeper (#2044)		6048		Maintenance - Equipment	\$102,000	\$102,000
Tennis Cts - Lighting		1302		Tennis Courts	\$24,300	\$24,300
Tennis Cts - Resurface		1306		Tennis Courts	\$19,464	\$19,464
Truck - Ford F-550 (#131)		6065		Maintenance - Equipment	\$69,000	\$69,000
				Tota	l for 2023-2024:	\$723,614
2024-2025						
2010 Dodge Truck 2500				Maintenance - Equipment	\$43,260	\$44,558
Concrete - Repair Contingency		1007		Asphalt & Concrete Surfaces	\$25,000	\$26,000
Diesel Tank/Pump (1) - 2,000 Gal		6010		Maintenance - Equipment	\$23,795	\$24,747
Diesel Tank/Pump (2) - 1,000 Gal		6011		Maintenance - Equipment	\$17,500	\$18,200
Diesel Tank/Pump (3) - 2,000 Gal		6012		Maintenance - Equipment	\$23,800	\$24,752
Ext - Backflow Device		1031		Clubhouse - Exterior	\$11,350	\$11,804
Ext - Paint/Repairs		1034		Clubhouse - Exterior	\$19,465	\$20,244



Anticipated Expenditures (30 Years)

Units: 2,887 | Start Date: 7/1/2023

· · · ·					1
Component	Location GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Golf Course - Cart Paths (Concrete Repairs 10%)	2003		Golf Course	\$17,161	\$17,847
Golf Course - Spillway (Repairs)	2013		Golf Course	\$129,780	\$134,971
Pavilion (Ext) - Balc/Walkway	8001		Pavilion	\$51,000	\$53,040
(Repair/Replace)					
Pavilion (Ext) - Paint/Repairs/Replace	8002		Pavilion	\$18,600	\$19,344
Pavilion (Ext) - Roofing (Flat/Mansards)	8003		Pavilion	\$26,000	\$27,040
Pavilion (Int) - Furnishings/Carpeting/Miscl	8004		Pavilion	\$14,000	\$14,560
Pavilion (Int) - Kitchen (Remodel/Refurbish)	8005		Pavilion	\$17,000	\$17,680
Pool/Spa - Mastic/Waterproof	9018		Pool & Spa	\$3,078	\$3,201
Pro Shop - Furnishings/Displays/Flooring	3002		Golf Course - Pro Shop	\$28,000	\$29,120
Pro Shop - Golf Carts	3003		Golf Course - Pro Shop	\$67,500	\$70,200
Water Tank - 2,000 Gal	6071		Maintenance - Equipment	\$8,650	\$8,996
Watering Tank	6072		Maintenance - Equipment	\$17,845	\$18,559
				al for 2024-2025:	\$584,862
2025-2026					
Bar - Flooring/Furnishings	1016		Clubhouse - Bar	\$52,000	\$56,243
Cinder Spreader - Meyer (#012- 1)	6008		Maintenance - Equipment	\$9,000	\$9,734
Cinder Spreader - Meyer (#012- 2)	6009		Maintenance - Equipment	\$9,000	\$9,734
Clubhouse - Remodel/Design Phase 3	1041		Clubhouse - General	\$2,000,000	\$2,163,200
Front Loader - Komatsu 250 (#2041)	6015		Maintenance - Equipment	\$200,000	\$216,320
Golf - Green Roller (#158)	6018		Maintenance - Equipment	\$12,735	\$13,774
Golf - Sod Cutters	6023		Maintenance - Equipment	\$17,300	\$18,712
Golf - Toro Green Mower (#157)	6024		Maintenance - Equipment	\$60,000	\$64,896
Golf Course - Aerators	2001		Golf Course	\$17,025	\$18,414
Golf Course - Wood Ret Walls (Repairs)	2018		Golf Course	\$17,300	\$18,712
HOA/Patrol Offices - Computers/Equipment	1053		Clubhouse - Offices	\$80,000	\$86,528
Septic System - Golf Pro-Shop	1103		Septic Systems	\$23,000	\$24,877
Trash Receptacles	7009		Miscellaneous	\$97,335	\$105,278
Utility Room - Furnishings/Miscl	1060		Clubhouse - Utility Room	\$21,630	\$23,395
Utility Room - Kitchen (Appliances)	1061		Clubhouse - Utility Room	\$6,000	\$6,490
Utility Room - Kitchen	1062		Clubhouse - Utility Room	\$8,650	\$9,356
(Refurbish)					
2026-2027			Tota	al for 2025-2026:	\$2,845,663
2 Snow Plow kits (191 & 192)			Maintenance - Equipment	\$19,500	\$21,308
Asphalt - Roller CAT (#2055)	6004		Maintenance - Equipment	\$69,000	\$77,616
Bistro - Washer/Dryer (Whirlpool)	1028		Clubhouse - Bistro	\$1,730	\$1,946

Pine Mountain Club Property Owner's Association info@smartproperty.com | 877-864-8955 | www.smartproperty.com

6031

EC Vehicle - Subaru (#161)

\$40,500

Maintenance - Equipment

\$45,557
Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Ext - Roofing		1035		Clubhouse - Exterior	\$86,500	\$97,301
Golf Course - Cart Path's / Rehab (25%)		2004		Golf Course	\$46,001	\$51,744
Golf Course - Lake Systems (Maintenance)		2011		Golf Course	\$248,745	\$279,804
Lampkin - Chain Link Fencing (Field)		4005		Lampkin Park	\$14,300	\$16,086
Lobby - Flooring/Furnishings		1045		Clubhouse - Lobby	\$7,325	\$8,240
Lobby - Restrooms		1046		Clubhouse - Lobby	\$17,300	\$19,460
Maint Bldg - RV Chain Link		5004		Maintenance - Building	\$11,500	\$12,936
Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$44,802
Patrol Vehicle - Colorado extended				Maintenance - Equipment	\$37,850	\$42,576
Rec Rm - Flooring		1058		Clubhouse - Rec Room	\$9,300	\$10,461
Snow Plow - Blade (#131)		6041		Maintenance - Equipment	\$21,630	\$24,331
Snow Plow - Front Loader (#2041)		6043		Maintenance - Equipment	\$24,000	\$26,997
Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$11,818
Stables - Lower Barn Rebuild		1211		Stables	\$51,912	\$58,394
Truck - Dodge 3500 (#163)		6062		Maintenance - Equipment	\$50,000	\$56,243
Truck - Dodge 4500 (#171)		6063		Maintenance - Equipment	\$50,000 Il for 2026-2027:	\$56,243 \$963,862
2027-2028				100	it 10f 2020-2027.	3503,602
Emergency Preparedness -		7002		Miscellaneous	\$17,000	\$19,888
Equip/Materials						
Ext - Decking / Siding / Rails		1032		Clubhouse - Exterior	\$175,000	\$204,725
Forklift - Nissan 5K (#062)		6013		Maintenance - Equipment	\$14,000	\$16,378
Golf Course - Irr Pumps		2009		Golf Course	\$68,100	\$79,667
(Replace)						
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$3,601
Rec Rm - Furnishings/Miscl		1059		Clubhouse - Rec Room	\$10,815	\$12,652
Septic System - Golf Course		1102		Septic Systems	\$17,000	\$19,888
Stables - Ext Wood (Paint)		1203		Stables	\$19,720	\$23,070
Trash Compactor (A)		6053		Maintenance - Equipment	\$23,790	\$27,831
Trash Compactor (B)		6054		Maintenance - Equipment	\$23,790	\$27,831
Truck - Dodge 5500 (#172)		6064		Maintenance - Equipment	\$82,000	\$95,928
2028-2029				Tota	ll for 2027-2028:	\$531,459
		6005		Maintanana Fasianaat	¢24.000	¢20.200
Auto Lift - Hydraulic		6005 1024		Maintenance - Equipment Clubhouse - Bistro	\$24,000 \$17,800	\$29,200 \$21,656
Bistro - Furnishings (Chairs/Tables)						
Bistro - Office/Equip (Refurb)		1025		Clubhouse - Bistro	\$3,245	\$3,948
Clubhouse - Remodel/Design Phase 4		1042		Clubhouse - General	\$1,765,000	\$2,147,392
HOA/Patrol Offices - Security Cameras		1056		Clubhouse - Patrol Offices	\$40,000	\$48,666
Lampkin - Baseball Field (Bleachers)		4001		Lampkin Park	\$11,570	\$14,077
Pavilion (Ext) - Balc/Patio Furnishings		7010		Pavilion	\$13,900	\$16,911
Telehandler - Gradall (#061)		6050		Maintenance - Equipment	\$44,000	\$53,533
						+=3,000



Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Tennis Cts - Windscreens		1307		Tennis Courts	\$9,000	\$10,950
Truck - Dodge 2500 (#182)		6061		Maintenance - Equipment	\$56,000	\$68,133
Utility Vehicle - John Deere		6069		Maintenance - Equipment	\$18,385	\$22,368
Gator						
2029-2030				Tota	l for 2028-2029:	\$2,460,515
Asphalt (Clubhouse) -		1002		Asphalt & Concrete Surfaces	\$175,875	\$222,538
Repair/Replace		1001			\$27,0,07,0	\$EEE,000
Concrete - Repair Contingency		1007		Asphalt & Concrete Surfaces	\$25,000	\$31,633
Ext - Paint/Repairs		1034		Clubhouse - Exterior	\$19,465	\$24,629
Front Loader - JCB (#2081)		6014		Maintenance - Equipment	\$102,000	\$129,063
Golf - Aerator (ProCore 864)		6017		Maintenance - Equipment	\$38,800	\$49,094
Golf - Mower Reelmaster 3100- D Sidewinder		6022		Maintenance - Equipment	\$44,610	\$56,446
HOA/Patrol Offices - Computers/Equipment		1053		Clubhouse - Offices	\$80,000	\$101,226
Lampkin - Restrooms (Refurbish)		4009		Lampkin Park	\$6,490	\$8,212
Pavilion (Ext) -		8002		Pavilion	\$18,600	\$23,535
Paint/Repairs/Replace		0002		T dvilon	\$10,000	\$£3,333
Snow Plow - Attachment (#182)		6037		Maintenance - Equipment	\$11,250	\$14,235
Snow Plow - Front Loader (#2081)		6044		Maintenance - Equipment	\$30,000	\$37,960
Tractor - John Deere (#083)		6052		Maintenance - Equipment	\$37,850	\$47,892
Truck - Dodge 2500 (#2101)		6059		Maintenance - Equipment	\$56,000	\$70,858
Truck - Dodge 2500 (191)		6060		Maintenance - Equipment	\$56,000	\$70,858
				Tota	l for 2029-2030:	\$888,178
2030-2031						
Asphalt - Crack Filler		6002		Maintenance - Equipment	\$62,000	\$81,588
Bar - Appliances/Serving		1014		Clubhouse - Bar	\$28,000	\$36,846
Systems						
Mailboxes		7007		Miscellaneous	\$19,450	\$25,595
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$4,050
Roto Chopper (#141)		6034		Maintenance - Equipment	\$420,000	\$552,691
Sweeper Vac - PTO (#2006)		6049		Maintenance - Equipment	\$28,000	\$36,846
Utility Vehicle - Kubota 1100		6068		Maintenance - Equipment	\$28,000	\$36,846
Utility Vehicle - Kubota 900		6070		Maintenance - Equipment	\$18,000 Il for 2030-2031:	\$23,687 \$798,149
2031-2032				100	it for 2030-2031:	\$/ 30,14 3
2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$24,702
Asphalt (Maint Yard) - Repair/Replace (3)		1006		Asphalt & Concrete Surfaces	\$52,500	\$71,850
Bar - Audio/Video Equip.		1015		Clubhouse - Bar	\$5,400	\$7,390
Bobcat Compact Track Loader		1015		Maintenance - Equipment	\$142,000	\$194,337
(2021)					+= .=,	+== 1,==?
Clubhouse - Remodel/Design Phase 5 & 6		1043		Clubhouse - General	\$1,000,000	\$1,368,569
Golf Course - Cart Path's / Rehab (25%)		2004		Golf Course	\$46,001	\$62,955
Lampkin - Cover Structure		4006		Lampkin Park	\$17,300	\$23,676
(Repair/Replace)				Clubhouse - Offices	\$16,900	\$21,408
Office - Phone System Patrol Vehicle - Colorado Crew						\$21,408
Faciol Venicle - Colorado Crew				Maintenance - Equipment	\$41,000	221,938

Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Patrol Vehicle - Colorado extended				Maintenance - Equipment	\$37,850	\$51,800
Pool Area - Deck (Repairs - 5%)		9002		Pool & Spa	\$14,040	\$19,215
Pool Area - Deck (Reseal/Waterproof)		9003		Pool & Spa	\$33,800	\$46,258
Pool/Spa - Heater (Pool)		9016		Pool & Spa	\$11,355	\$15,540
Pool/Spa - Heater (Spa)		9017		Pool & Spa	\$9,000	\$12.317
Pool/Spa - Pumps/Motors		9019		Pool & Spa	\$14,000	\$19,160
Solar Powered Cameras		5015		Clubhouse - Patrol Offices	\$10,815	\$13,700
Solar Stubs				Pool & Spa	\$11,350	\$15,533
Spa - Resurface/Tile		9020		Pool & Spa	\$5,400	\$7,390
Welders (2) - Ranger		6074		Maintenance - Equipment	\$7,000	\$9,580
		00/1		• •	l for 2031-2032:	\$2,037,319
2032-2033				1044		<i>42,007,1025</i>
Entry Monuments -		7003		Miscellaneous	\$6,500	\$9,252
Maint/Refurb		7005		MISCENTIEOUS	JU, JU	\$9,232
Ext - Lighting		1033		Clubhouse - Exterior	\$34,600	\$49,247
Frontier BB4278H - 6ft. 6in.		1055		Maintenance - Equipment	\$5,350	\$7,615
Hydraulic Scarifier Box Blade				Maintenance Equipment	\$3,330	\$7,015
Gazebo - Roofing/Repairs		7004		Miscellaneous	\$21,630	\$30,786
Golf - Mower JD2500 (#2002)		6021		Maintenance - Equipment	\$34,770	\$49,489
John Deere 5065E Utility Tractor				Maintenance - Equipment	\$59,500	\$84,687
John Deere 520M Loader				Maintenance - Equipment	\$12,600	\$17,934
Stables - Comp Shingle Roofing		1202		Stables	\$32,915	\$46,848
Stables - Ext Wood (Paint)		1202		Stables	\$19,720	\$28,068
Stables - Panels/Gates		1205		Stables	\$33,450	\$47,610
(Contingency) - 1		1200				
Stables - Panels/Gates (Contingency) - 2				Stables	\$44,885	\$63,885
Utility Vehicle - John Deere Gator (50014)				Maintenance - Equipment	\$17,000	\$24,196
Utility Vehicle - John Deere Gator (50018)				Maintenance - Equipment	\$17,000	\$24,196
2033-2034				Tota	l for 2032-2033:	\$483,812
Bistro - Office/Equip (Refurb)		1025		Clubhouse - Bistro	\$3,245	\$4,803
Club - Sump Pumps - Lift Station		1025		Clubhouse - Mech Equipment	\$19,460	\$28,805
· · · · · · · · · · · · · · · · · · ·		1051		Clubhouse - Mech Equipment	\$19,400	\$25,608
Club - Water Heat Systems Front Loader - Komatsu WA 250 (#121)		6016		Maintenance - Equipment	\$183,000	\$25,668
Golf - Toro Rough Mower (#2093)		6025		Maintenance - Equipment	\$61,000	\$90,295
Golf Course - Bridges		2002		Golf Course	\$6,350	\$9,400
(Rebuild/Repair)						
Golf Course - Course Restroom (Refurb)		2005		Golf Course	\$40,000	\$59,210
HOA/Patrol Offices - Computers/Equipment		1053		Clubhouse - Offices	\$80,000	\$118,420
Lampkin - Playground (Structures)		4008		Lampkin Park	\$68,000	\$100,657
Pool - Resurface/Tile		8006		Pool & Spa	\$23,795	\$35,222
		9005		•		

Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement	Anticipated Expenditures
Pool/Spa – Chem Systems		9011		Pool & Spa	Cost \$6,920	\$10,243
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$4,556
Septic System - Clubhouse		1101		Septic Systems	\$118,000	\$174,669
Snow Plow - Attachment (#163)		6038		Maintenance - Equipment	\$8,000	\$11,842
Snow Plow (#171)		6046		Maintenance - Equipment	\$8,400	\$12,434
Snow Plow (#172)				Maintenance - Equipment	\$8,400	\$12,434
Stables - Fencing (Split Rail)		1207		Stables	\$44,200	\$65,427
Tennis Cts - Chain Link Fence		1301		Tennis Courts	\$19,950	\$29,531
Tennis Cts - Resurface		1306		Tennis Courts	\$19,464	\$28,811
Truck - Ford F-550 (#131)		6065		Maintenance - Equipment	\$69,000	\$102,137
					l for 2033-2034:	\$1,224,254
2034-2035						
Backhoe – New Holland (#143)		6006		Maintenance - Equipment	\$86,000	\$132,393
Campground - Restrooms		1010		Campground	\$8,000	\$12,316
(Refurb)				-		
Concrete - Repair Contingency		1007		Asphalt & Concrete Surfaces	\$25,000	\$38,486
Ext - Paint/Repairs		1034		Clubhouse - Exterior	\$19,465	\$29,965
Golf Course - Cart Paths		2003		Golf Course	\$17,161	\$26,418
(Concrete Repairs 10%) Golf Course - Vertical Cutting Reels		2017		Golf Course	\$8,595	\$13,232
Pavilion (Ext) -		8002		Pavilion	\$18,600	\$28,634
Paint/Repairs/Replace Pavilion (Int) -		8004		Pavilion	\$14,000	\$21,552
Furnishings/Carpeting/Miscl		8004		Favilion	\$14,000	\$21,332
Pro Shop - Furnishings/Displays/Flooring		3002		Golf Course - Pro Shop	\$28,000	\$43,105
Snow Plow - Front Loader (#121)		6042		Maintenance - Equipment	\$32,000	\$49,263
Spreader – Turfco 1550		6047		Maintenance - Equipment	\$20,000	\$30,789
Water Tank - 2,000 Gal		6071		Maintenance - Equipment	\$8,650	\$13,316
2035-2036				Total for 2034-2035:		\$439,469
Bar - Flooring/Furnishings		1016		Clubhouse - Bar	\$52,000	\$83,254
Bar - Restroom (Refurb)		1020		Clubhouse - Bar	\$4,500	\$7,205
Club - Emergency Generator		1048		Clubhouse - Mech Equipment	\$118,500	\$189,722
Electronic Speed limit sign				Miscellaneous	\$6,758	\$10,820
Golf - Green Roller (#158)		6018		Maintenance - Equipment	\$12,735	\$20,389
Golf - Toro Green Mower (#157)		6024		Maintenance - Equipment	\$60,000	\$96,062
Golf Course - Aerators		2001		Golf Course	\$17,025	\$27,258
HOA/Patrol Offices - Restrooms (Refurb)		1055		Clubhouse - Offices	\$17,300	\$27,698
Kitchen - Appliances/Cookware		1029		Clubhouse - Bistro	\$108,000	\$172,911
Truck - Trailer - Boander 20' (#142)		6066		Maintenance - Equipment	\$14,500	\$23,215
Utility Room - Furnishings/Miscl		1060		Clubhouse - Utility Room	\$21,630	\$34,630
				Tota	l for 2035-2036:	\$693,164
2036-2037						
2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$28,636
Bistro - Washer/Dryer (Whirlpool)		1028		Clubhouse - Bistro	\$1,730	\$2,881
Club - Fire Systems - Upgrade/Repairs		1049		Clubhouse - Mech Equipment	\$24,332	\$40,515

Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Club - Heating/Cooling Systems		1050		Clubhouse - Mech Equipment	\$54,075	\$90,039
EC Vehicle - Subaru (#161)		6031		Maintenance - Equipment	\$40,500	\$67,435
Golf Course - Cart Path's /		2004		Golf Course	\$46,001	\$76,594
Rehab (25%)						
Golf Course - Lake Systems (Maintenance)		2011		Golf Course	\$248,745	\$414,179
Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$60,210
Patrol Vehicle - Colorado				Maintenance - Equipment	\$37,850	\$63,023
extended						
Pool Area - Cover & Reel		9001		Pool & Spa	\$7,000	\$11,656
Pool/Spa – Filters		9015		Pool & Spa	\$39,000	\$64,938
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$5,125
Pro Shop - Golf Carts		3003		Golf Course - Pro Shop	\$67,500	\$112,392
Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$15,882
Truck - Dodge 3500 (#163)		6062		Maintenance - Equipment	\$50,000	\$83,254
Truck - Dodge 4500 (#171)		6063		Maintenance - Equipment	\$50,000	\$83,254
Utility Vehicle - John Deere Gator		6069		Maintenance - Equipment	\$18,385	\$30,612
Watering Tank		6072		Maintenance - Equipment	\$17,845	\$29,713
				Total	for 2036-2037:	\$1,280,338
2037-2038						
Bistro - Restroom		1027		Clubhouse - Bistro	\$4,325	\$7,490
Emergency Preparedness -		7002		Miscellaneous	\$17,000	\$29,438
Equip/Materials						
Golf - Green Sweeper		6019		Maintenance - Equipment	\$11,680	\$20,226
Golf Course - Split Rail Fencing		2014		Golf Course	\$31,824	\$55,109
HOA/Patrol Offices -		1053		Clubhouse - Offices	\$80,000	\$138,534
Computers/Equipment						
HOA/Patrol Offices -		1054		Clubhouse - Offices	\$55,500	\$96,108
Furnishings/Flooring						
Stables - Ext Wood (Paint)		1203		Stables	\$19,720	\$34,149
Stables - Ext Wood (Repairs- 20%)		1204		Stables	\$25,500	\$44,158
Truck - Dodge 5500 (#172)		6064		Maintenance - Equipment	\$82,000	\$141,997
				Total	for 2037-2038:	\$567,209
2038-2039						
Bistro - Flooring		1023		Clubhouse - Bistro	\$13,338	\$24,021
Bistro - Furnishings		1024		Clubhouse - Bistro	\$17,800	\$32,057
(Chairs/Tables)						
Bistro - Office/Equip (Refurb)		1025		Clubhouse - Bistro	\$3,245	\$5,844
HOA/Patrol Offices - Security		1056		Clubhouse - Patrol Offices	\$40,000	\$72,038
Cameras						
Kitchen - Flooring/Prep Stations		1030		Clubhouse - Bistro	\$23,000	\$41,422
Pavilion (Ext) - Balc/Patio		7010		Pavilion	\$13,900	\$25,033
Furnishings						
Rec Rm - Flooring		1058		Clubhouse - Rec Room	\$9,300	\$16,749
Street Sweeper (#2044)		6048		Maintenance - Equipment	\$102,000	\$183,696
Tennis Cts - Resurface		1306		Tennis Courts	\$19,464	\$35,054
Tennis Cts - Windscreens		1307		Tennis Courts	\$9,000	\$16,208
Truck - Dodge 2500 (#182)		6061		Maintenance - Equipment	\$56,000	\$100,853
Utility Vehicle - Kubota 1100		6068		Maintenance - Equipment	\$28,000	\$50,426
Utility Vehicle - Kubota 900		6070		Maintenance - Equipment	\$18,000	\$32,417



Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current Replacement	Anticipated Expenditures
				Tot	Cost al for 2038-2039:	\$635,818
2039-2040						····
2010 Dodge Truck 2500				Maintenance - Equipment	\$43,260	\$69,420
Bar - Audio/Video Equip.		1015		Clubhouse - Bar	\$5,400	\$10,114
Campground - Furnishings		1009		Campground	\$17,000	\$31,841
Concrete - Repair Contingency		1007		Asphalt & Concrete Surfaces	\$25,000	\$46,825
Ext - Paint/Repairs		1034		Clubhouse - Exterior	\$19,465	\$36,458
Golf - Aerator (ProCore 864)		6017		Maintenance - Equipment	\$38,800	\$72,672
Golf - Mower Reelmaster 3100-		6022		Maintenance - Equipment	\$44,610	\$83,554
D Sidewinder		0022		- Identification Equipation	<i>Q</i> 1 1/010	¢00,00 .
Golf Course - Irr System		2010		Golf Course	\$350,000	\$655,543
(Replace)					+	+,
Pavilion (Ext) -		8002		Pavilion	\$18,600	\$34,837
Paint/Repairs/Replace						
Pavilion (Ext) - Roofing		8003		Pavilion	\$26,000	\$48,698
(Flat/Mansards)						
Pavilion (Int) - Kitchen		8005		Pavilion	\$17,000	\$31,841
(Remodel/Refurbish)						
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$5,765
Snow Plow - Attachment (#182)		6037		Maintenance - Equipment	\$11,250	\$21,071
Stables - Arena & Pen		1201		Stables	\$46,506	\$87,105
Upgrades/Maint						
Stables - Fencing (Arena		1205		Stables	\$16,264	\$30,462
Fencing)						
Truck - Dodge 2500 (#2101)		6059		Maintenance - Equipment	\$56,000	\$104,887
Truck - Dodge 2500 (191)		6060		Maintenance - Equipment	\$56,000	\$104,887
				Total for 2039-2040:		\$1,475,978
2040-2041						
Campground - Comp Shingle		1012		Campground	\$4,000	\$7,792
Roof						
Cinder Spreader - Meyer (#012-		6008		Maintenance - Equipment	\$9,000	\$17,531
1)						
Cinder Spreader - Meyer (#012-		6009		Maintenance - Equipment	\$9,000	\$17,531
2)						
Golf - Sod Cutters		6023		Maintenance - Equipment	\$17,300	\$33,699
Mailboxes		7007		Miscellaneous	\$19,450	\$37,887
Mailboxes - Enclosure/Structure				Miscellaneous	\$27,000	\$52,593
Stables - Round Pen				Stables	\$83,500	\$138,013
Trash Receptacles		7009		Miscellaneous	\$97,335	\$189,599
Utility Room - Kitchen		1061		Clubhouse - Utility Room	\$6,000	\$11,687
(Appliances)						
				Tot	al for 2040-2041:	\$506,332
2041-2042						
2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$33,197
Bobcat Compact Track Loader				Maintenance - Equipment	\$142,000	\$287,666
(2021)				daulaa		<i>4_0,000</i>
Golf Course - Cart Path's /		2004		Golf Course	\$46,001	\$93,189
Rehab (25%)					. ,	+ /
HOA/Patrol Offices -		1053		Clubhouse - Offices	\$80,000	\$162,065
Computers/Equipment					·	
HOA/Patrol Offices - Security		1057		Clubhouse - Patrol Offices	\$32,000	\$64,826

Anticipated Expenditures (30 Years)

Component	Location GL	Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Lampkin - Roofing (RR/Cover)	4	1011		Lampkin Park	\$9,180	\$18,597
Lobby - Restrooms		.046		Clubhouse - Lobby	\$17,300	\$35,047
Office - Phone System				Clubhouse - Offices	\$16,900	\$28,771
Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$69,800
Patrol Vehicle - Colorado				Maintenance - Equipment	\$37,850	\$76,677
extended				Haintenance Equipment	\$57,636	\$70,077
Pool Area - Deck (Repairs - 5%)	9	002		Pool & Spa	\$14,040	\$28,442
Pool Area - Deck	9	003		Pool & Spa	\$33,800	\$68,473
(Reseal/Waterproof)						
Pool Area - Ext Showers (Tile)	9	004		Pool & Spa	\$34,600	\$70,093
Pool Area - Wood Trellis	9	009		Pool & Spa	\$13,600	\$27,551
Pool/Spa – Heater (Pool)	9	016		Pool & Spa	\$11,355	\$23,003
Pool/Spa – Heater (Spa)	9	017		Pool & Spa	\$9,000	\$18,232
Pool/Spa - Pumps/Motors	9	019		Pool & Spa	\$14,000	\$28,361
Snow Plow - Front Loader	6	043		Maintenance - Equipment	\$24,000	\$48,620
(#2041)						
Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$18,412
Solar Stubs				Pool & Spa	\$11,350	\$22,993
Spa - Resurface/Tile	9	020		Pool & Spa	\$5,400	\$10,939
Stables - Hot Walker	1	209		Stables	\$8,400	\$17,017
Welders (2) - Ranger	6	074		Maintenance - Equipment	\$7,000	\$14,181
					al for 2041-2042:	\$1,266,153
2042-2043						
Bar - Appliances/Serving	1	.014		Clubhouse - Bar	\$28,000	\$58,992
Systems						
Boat - Lake Maintenance (TBD)				Maintenance - Equipment	\$8,650	\$18,224
Diesel Tank/Pump (1) - 2,000 Gal	6	6010		Maintenance - Equipment	\$23,795	\$50,132
Diesel Tank/Pump (2) - 1,000 Gal	e	5011		Maintenance - Equipment	\$17,500	\$36,870
Diesel Tank/Pump (3) - 2,000 Gal	6	5012		Maintenance - Equipment	\$23,800	\$50,143
		007		Missellaneous	\$6 E00	¢17 605
Entry Monuments - Maint/Refurb	/	003		Miscellaneous	\$6,500	\$13,695
Ext - Backflow Device	1	.031		Clubhouse - Exterior	\$11,350	\$23,913
Forklift - Nissan 5K (#062)	6	5013		Maintenance - Equipment	\$14,000	\$29,496
Frontier BB4278H - 6ft. 6in.				Maintenance - Equipment	\$5,350	\$11,272
Hydraulic Scarifier Box Blade						
Golf - Mower JD2500 (#2002)	6	5021		Maintenance - Equipment	\$34,770	\$73,255
Golf Course - Irr Pumps (Replace)	2	009		Golf Course	\$68,100	\$143,476
John Deere 5065E Utility Tractor				Maintenance - Equipment	\$59,500	\$125,358
John Deere 520M Loader				Maintenance - Equipment	\$12,600	\$26,546
Lampkin - Bball Ct (Resurface)	4	003		Lampkin Park	\$61,982	\$130,587
Pool/Spa - Mastic/Waterproof		018		Pool & Spa	\$3,078	\$6,485
Stables - Ext Wood (Paint)		.203		Stables	\$19,720	\$41,547
Stables - Panels/Gates		206		Stables	\$33,450	\$70,474
(Contingency) - 1	-				<i>400,100</i>	ç, c, t/ t
Stables - Panels/Gates				Stables	\$44,885	\$94,566
(Contingency) - 2					÷,	<i>42 1,000</i>
Utility Vehicle - John Deere				Maintenance - Equipment	\$17,000	\$35,816
Gator (50014)						



Anticipated Expenditures (30 Years)

					,	
Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
Utility Vehicle - John Deere Gator (50018)				Maintenance - Equipment	\$17,000	\$35,816
				Total	for 2042-2043:	\$1,076,663
2043-2044						
Asphalt (Maint Yard) - Repair/Replace (1)		1004		Asphalt & Concrete Surfaces	\$52,500	\$115,034
Bistro - Office/Equip (Refurb)		1025		Clubhouse - Bistro	\$3,245	\$7,110
Decking, Ramps, Rails (New)				Clubhouse - Exterior	\$275,000	\$496,681
Golf Course - Gate Valves		2008		Golf Course	\$8,800	\$19,282
(Canal)						
Maint Bldg - Comp Shingle Roofing		5001		Maintenance - Building	\$27,720	\$60,738
Septic System - Clubhouse		1101		Septic Systems	\$118,000	\$258,553
Snow Plow - Attachment (#163)		6038		Maintenance - Equipment	\$8,000	\$17,529
Snow Plow (#171)		6046		Maintenance - Equipment	\$8,400	\$18,405
Snow Plow (#172)				Maintenance - Equipment	\$8,400	\$18,405
Stables - Horse Watering System		1208		Stables	\$43,260	\$94,788
Telehandler - Gradall (#061)		6050		Maintenance - Equipment	\$44,000	\$96,409
Tennis Cts - Lighting		1302		Tennis Courts	\$24,300	\$53,244
Tennis Cts - Resurface		1306		Tennis Courts	\$19,464	\$42,648
Truck - Ford F-550 (#131)		6065		Maintenance - Equipment	\$69,000	\$151,187
					for 2043-2044:	\$1,450,014
2044-2045						
Concrete - Repair Contingency		1007		Asphalt & Concrete Surfaces	\$25,000	\$56,969
Ext - Paint/Repairs		1034		Clubhouse - Exterior	\$19,465	\$44,356
Golf - Toro Rough Mower (#2093)		6025		Maintenance - Equipment	\$61,000	\$139,005
Golf Course - Cart Paths (Concrete Repairs 10%)		2003		Golf Course	\$17,161	\$39,105
Lampkin - Restrooms (Refurbish)		4009		Lampkin Park	\$6,490	\$14,789
Pavilion (Ext) -		8002		Pavilion	\$18,600	\$42,385
Paint/Repairs/Replace						
Pavilion (Int) - Furnishings/Carpeting/Miscl		8004		Pavilion	\$14,000	\$31,903
Pro Shop -		3002		Golf Course - Pro Shop	\$28,000	\$63,806
Furnishings/Displays/Flooring						
Utility Vehicle - John Deere Gator		6069		Maintenance - Equipment	\$18,385	\$41,895
Water Tank - 2,000 Gal		6071		Maintenance - Equipment	\$8,650	\$19,711
				Total	for 2044-2045:	\$493,924
2045-2046						
Bar - Flooring/Furnishings		1016		Clubhouse - Bar	\$52,000	\$123,236
Club - Sump Pumps - Lift Station		1051		Clubhouse - Mech Equipment	\$19,460	\$46,119
Club - Water Heat Systems		1052		Clubhouse - Mech Equipment	\$17,300	\$41,000
Front Loader - Komatsu 250 (#2041)		6015		Maintenance - Equipment	\$200,000	\$473,984
Golf - Green Roller (#158)		6018		Maintenance - Equipment	\$12,735	\$30,181
Golf - Toro Green Mower (#157)		6024		Maintenance - Equipment	\$60,000	\$142,195
Golf Course - Aerators		2001		Golf Course	\$17,025	\$40,348
Golf Course - Wood Ret Walls (Repairs)		2018		Golf Course	\$17,300	\$41,000
HOA/Patrol Offices -		1053		Clubhouse - Offices	\$80,000	\$189,594



Anticipated Expenditures (30 Years)

Component	Location	GL Code	Project Number	Category	Current	Anticipated Expenditures
					Replacement Cost	
Computers/Equipment						
Maintenance - Emergency				Maintenance - Equipment	\$32,000	\$75,837
Generator						
Pool - Resurface/Tile		8006		Pool & Spa	\$23,795	\$56,392
Pool Area - Furnishings		9005		Pool & Spa	\$19,500	\$46,213
Pool/Spa – Chem Systems		9011		Pool & Spa	\$6,920	\$16,400
Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$7,295
Roto Chopper (#141)		6034		Maintenance - Equipment	\$420,000	\$995,366
Utility Room - Furnishings/Miscl		1060		Clubhouse - Utility Room	\$21,630	\$51,261
				Tota	l for 2045-2046:	\$2,376,419
2046-2047						
2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$38,485
Asphalt - Crack Filler		6002		Maintenance - Equipment	\$62,000	\$152,812
Asphalt - Roller CAT (#2055)		6004		Maintenance - Equipment	\$69,000	\$170,065
Bistro - Washer/Dryer		1028		Clubhouse - Bistro	\$1,730	\$4,264
(Whirlpool)						
Cardboard Bailer		6007		Maintenance - Equipment	\$16,000	\$39,435
EC Vehicle - Subaru (#161)		6031		Maintenance - Equipment	\$40,500	\$99,821
Golf Course - Cart Path's / Rehab (25%)		2004		Golf Course	\$46,001	\$113,378
Golf Course - Lake Systems (Maintenance)		2011		Golf Course	\$248,745	\$613,086
Golf Course - Vertical Cutting Reels		2017		Golf Course	\$8,595	\$21,184
Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$80,917
Patrol Vehicle - Colorado				Maintenance - Equipment	\$37,850	\$93,289
extended					<i>407,000</i>	<i>470,207</i>
Pool Area - Pump Rm Roofing		9007		Pool & Spa	\$2,958	\$7,291
Pool/Spa - Fencing (W.I.)		9013		Pool & Spa	\$27,716	\$68,312
Snow Plow - Blade (#131)		6041		Maintenance - Equipment	\$21,630	\$53,312
Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$21,344
Sweeper Vac - PTO (#2006)		6049		Maintenance - Equipment	\$28,000	\$69,012
Truck - Dodge 3500 (#163)		6062		Maintenance - Equipment	\$50,000	\$123,236
Truck - Dodge 4500 (#171)		6063		Maintenance - Equipment	\$50,000	\$123,236
Utility Vehicle - Kubota 1100		6068		Maintenance - Equipment	\$28,000	\$69,012
Utility Vehicle - Kubota 900		6070		Maintenance - Equipment	\$18,000	\$44,365
, ,				••	al for 2046-2047:	\$2,005,858
2047-2048						
Asphalt (Campground) - Repair/Replace		1001		Asphalt & Concrete Surfaces	\$122,500	\$314,005
Bar - Audio/Video Equip.		1015		Clubhouse - Bar	\$5,400	\$13,842
Bar - Remodel/Refurbish		1019		Clubhouse - Bar	\$56,000	\$143,545
Bar - Restroom (Refurb)		1020		Clubhouse - Bar	\$4,500	\$11,535
Emergency Preparedness -		7002		Miscellaneous	\$17,000	\$43,576
Equip/Materials Ext - Lighting		1033		Clubhouse - Exterior	\$34,600	\$88,690
HOA/Patrol Offices - Restrooms		1055		Clubhouse - Offices	\$17,300	\$44,345
(Refurb)						
Kitchen - Appliances/Cookware		1029		Clubhouse - Bistro	\$108,000	\$276,837
Rec Rm - Furnishings/Miscl		1059		Clubhouse - Rec Room	\$10,815	\$27,722
Septic System - Maint Bldg		1105		Septic Systems	\$32,000	\$82,026
Septic System - Stables		1106		Septic Systems	\$22,980	\$58,905



Anticipated Expenditures (30 Years)

Stables - Ext Wood (Paint) Trash Compactor (A) Trash Compactor (B) Truck - Dodge 5500 (#172) 2048-2049 Bistro - Furnishings (Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Watkway (Repair/Replace)	1203 6053 6054 6064 1024 1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061 6061 6072	Clubhouse - Bistro Clubhouse - Bistro Golf Course Golf Course Clubhouse - Patrol Offices Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	Cost \$19,720 \$23,790 \$23,790 \$82,000 1 for 2047-2048: \$17,800 \$3,245 \$6,350 \$40,000 \$40,000 \$40,000 \$40,000 \$40,000 \$40,000 \$40,000 \$13,900 \$112,000 \$112,000 \$19,464 \$9,000 \$17,845	\$50,548 \$60,981 \$60,981 \$210,191 \$1,487,729 \$47,452 \$8,651 \$16,928 \$106,633 \$106,833 \$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,835\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,855\\\$106,8
Trash Compactor (B) Truck - Dodge 5500 (#172) 2048-2049 Bistro - Furnishings (Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6054 6064 1024 1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Maintenance - Equipment Maintenance - Equipment Tota Clubhouse - Bistro Clubhouse - Bistro Golf Course Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Spa Clubhouse - Patrol Offices Clubhouse - Patrol Offices Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$23,790 \$82,000 If or 2047-2048: \$17,800 \$3,245 \$6,350 \$40,000 \$40,000 \$40,000 \$40,000 \$13,900 \$13,900 \$13,900 \$112,000 \$112,000 \$112,000 \$112,000 \$112,000	\$60,981 \$210,191 \$1,487,729 \$47,452 \$8,651 \$16,928 \$106,633 \$106,934\$105,9355555555555555555555555555555555555
Truck - Dodge 5500 (#172) 2048-2049 Bistro - Furnishings (Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6064 1024 1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Maintenance - Equipment Total Clubhouse - Bistro Clubhouse - Bistro Golf Course Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Clubhouse - Patrol Offices Spa Golf Course Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$82,000 1 for 2047-2048: \$17,800 \$3,245 \$6,350 \$40,0000 \$40,0000 \$	\$210,191 \$1,487,729 \$47,452 \$8,651 \$16,928 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$107,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
2048-2049Bistro - Furnishings(Chairs/Tables)Bistro - Office/Equip (Refurb)Golf Course - Bridges(Rebuild/Repair)Golf Course - Course Restroom(Refurb)HOA/Patrol Offices - SecurityCamerasLampkin - Playground(Structures)Pavilion (Ext) - Balc/PatioFurnishingsPool/Spa - Mastic/WaterproofPro Shop - Golf CartsTennis Cts - ReplaceTennis Cts - ResurfaceTennis Cts - WindscreensTruck - Dodge 2500 (#182)Watering Tank2049-2050Campground - Restrooms(Refurb)Concrete - Repair ContingencyExt - Decking / Siding / RailsExt - Decking / Siding / RailsExt - Paint/RepairsFront Loader - JCB (#2081)Golf - Mower Reelmaster 3100-D SidewinderHOA/Patrol Offices -Computer (Ext) - Balc/Walkway	1024 1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Total Clubhouse - Bistro Clubhouse - Bistro Clubhouse - Bistro Golf Course Golf Course Clubhouse - Patrol Offices Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	for 2047-2048: \$17,800 \$3,245 \$6,350 \$40,0000 \$40,0000 \$40,0000 \$40,	\$1,487,729 \$47,452 \$8,651 \$16,928 \$106,633 \$106,635 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,633 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,833 \$106,928 \$106,928 \$106,939\$ \$106,939\$\$106,959\$ \$106,959\$ \$106,959\$\$106,959\$ \$106,959\$\$106,959
Bistro - Furnishings (Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Clubhouse - Bistro Clubhouse - Bistro Golf Course Golf Course Clubhouse - Patrol Offices Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$17,800 \$3,245 \$6,350 \$40,000 \$40,000 \$68,000 \$13,900 \$13,900 \$13,900 \$112,000 \$112,000 \$19,464 \$9,000	\$47,452 \$8,651 \$16,928 \$106,633 \$106,633 \$106,633 \$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Bistro - Furnishings (Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Clubhouse - Bistro Golf Course Golf Course Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$3,245 \$6,350 \$40,000 \$40,000 \$68,000 \$13,900 \$13,900 \$13,078 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$8,651 \$16,928 \$106,633 \$106,633 \$181,277 \$37,055 \$8,205 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
(Chairs/Tables) Bistro - Office/Equip (Refurb) Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1025 2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Clubhouse - Bistro Golf Course Golf Course Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$3,245 \$6,350 \$40,000 \$40,000 \$68,000 \$13,900 \$13,900 \$13,078 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$8,651 \$16,928 \$106,633 \$106,633 \$181,277 \$37,055 \$8,205 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Golf Course - Bridges (Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	2002 2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Golf Course Golf Course Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$6,350 \$40,000 \$40,000 \$68,000 \$13,900 \$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$16,928 \$106,633 \$106,633 \$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
(Rebuild/Repair) Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	2005 1056 4008 7010 9018 3003 1305 1306 1307 6061	Golf Course Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$40,000 \$40,000 \$68,000 \$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$106,633 \$106,633 \$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Golf Course - Course Restroom (Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1056 4008 7010 9018 3003 1305 1306 1307 6061	Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$40,000 \$68,000 \$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$106,633 \$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
(Refurb) HOA/Patrol Offices - Security Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1056 4008 7010 9018 3003 1305 1306 1307 6061	Clubhouse - Patrol Offices Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$40,000 \$68,000 \$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$106,633 \$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Cameras Lampkin - Playground (Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	4008 7010 9018 3003 1305 1306 1307 6061	Lampkin Park Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$68,000 \$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$181,277 \$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
(Structures) Pavilion (Ext) - Balc/Patio Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	7010 9018 3003 1305 1306 1307 6061	Pavilion Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$13,900 \$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$37,055 \$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Furnishings Pool/Spa - Mastic/Waterproof Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	9018 3003 1305 1306 1307 6061	Pool & Spa Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$3,078 \$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$8,205 \$179,944 \$298,574 \$51,888 \$23,993
Pro Shop - Golf Carts Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	3003 1305 1306 1307 6061	Golf Course - Pro Shop Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$67,500 \$112,000 \$19,464 \$9,000 \$56,000	\$179,944 \$298,574 \$51,888 \$23,993
Tennis Cts - Replace Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1305 1306 1307 6061	Tennis Courts Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$112,000 \$19,464 \$9,000 \$56,000	\$298,574 \$51,888 \$23,993
Tennis Cts - Resurface Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1306 1307 6061	Tennis Courts Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$19,464 \$9,000 \$56,000	\$51,888 \$23,993
Tennis Cts - Windscreens Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1307 6061	Tennis Courts Maintenance - Equipment Maintenance - Equipment	\$9,000 \$56,000	\$23,993
Truck - Dodge 2500 (#182) Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6061	Maintenance - Equipment Maintenance - Equipment	\$56,000	
Watering Tank 2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway		Maintenance - Equipment		\$149,287
2049-2050 Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6072		\$17.845	
Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway			+=.,	\$47,572
Campground - Restrooms (Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway		Total	\$1,264,092	
(Refurb) Concrete - Repair Contingency Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway				
Ext - Decking / Siding / Rails Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1010	Campground	\$8,000	\$22,180
Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1007	Asphalt & Concrete Surfaces	\$25,000	\$69,312
Ext - Paint/Repairs Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1032	Clubhouse - Exterior	\$175,000	\$485,182
Front Loader - JCB (#2081) Golf - Aerator (ProCore 864) Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	1034	Clubhouse - Exterior	\$19,465	\$53,966
Golf - Mower Reelmaster 3100- D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6014	Maintenance - Equipment	\$102,000	\$282,792
D Sidewinder HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6017	Maintenance - Equipment	\$38,800	\$107,572
HOA/Patrol Offices - Computers/Equipment Pavilion (Ext) - Balc/Walkway	6022	Maintenance - Equipment	\$44,610	\$123,680
Computers/Equipment Pavilion (Ext) - Balc/Walkway				
Pavilion (Ext) - Balc/Walkway	1053	Clubhouse - Offices	\$80,000	\$221,798
(Repair/Replace)	8001	Pavilion	\$51,000	\$141,396
Pavilion (Ext) - Paint/Repairs/Replace	8002	Pavilion	\$18,600	\$51,568
Snow Plow - Attachment (#182)	6037	Maintenance - Equipment	\$11,250	\$31,190
Snow Plow - Front Loader (#2081)	6044	Maintenance - Equipment	\$30,000	\$83,174
Spreader – Turfco 1550	6047	Maintenance - Equipment	\$20,000	\$55,449
Tractor - John Deere (#083)	6052	Maintenance - Equipment	\$37,850	\$104,938
Truck - Dodge 2500 (#2101)		Maintenance - Equipment	\$56,000	\$155,258
Truck - Dodge 2500 (191)	6059			\$155,258
		Maintenance - Equipment	\$56,000	JTJJ.230



Anticipated Expenditures (30 Years)

ReplacementReplacementSet 39.480Electronic Speed limit sign39.48039.480Nathores19.58Clubhouse - Res Room59.400Res Elm - Flooring19.58Clubhouse - Res Room59.400Dillin y Room - Kitchen10.62Clubhouse - Res Room59.400Sols Sols SolsTable - State - St							
Nultices 7007 Micellaneous 313 430 95500 Rea Rin - Flooring 1058 Cubhouse - Rea Room 59.300 S26.815 National Control 1062 Cubhouse - Bath Room 58.650 S24.941 Iteruturisti Total for 2050-2051: S127.324 S127.324 2051-2052 Total for 2050-2051: S127.324 2051-2052 Maintenance - Equipment 514.200 S42.505 2052-2052 Maintenance - Equipment 54.325 S12.609 2052-2052 Maintenance - Equipment 54.325 S12.620 2052-2051 Maintenance - Equipment 54.325 S12.523 Cub- fire Systems - .049 Cubhouse - Mech Equipment 55.473 S16.2155 Cub- fire Systems - .049 Cubhouse - Esterior S86.500 S25.938 Cub- fire Systems - .040 Cubhouse - Esterior S56.00 S15.930 Cub- fire System . Cubhouse - Offeres S15.900 S15.930 Cub- fire System . Cubhouse - Staro S25.000 S58.66	Component	Location	GL Code	Project Number	Category	Replacement	Anticipated Expenditures
Bee Bm - Flooring 1058 Clubhouse - Rec Room 93.200 53.26.312 Unity Room - Kitchen 1062 Clubnouse - Utility Kom 58.260 52.27.24 Sols-0052 Total for 2050-052 52.27.24 52.27.24 Zonov Provi Kin (131 12 152) Maintenance - Equipment 53.42.050 542.505 Sols-0052 Clubhouse - Mech Equipment 54.200 542.505 Cub- Track Loader Maintenance - Equipment 54.200 542.515 Cub- Track Loader S14.000 532.517 55.007 53.075 53.075 Cub- Track Loader S14.000 S32.517 55.000 53.500 52.513.50 Cub- Track Loader S4.001 S3.53.00 S3.53.93 53.500 53.66.428 Cub- Track Loger System Cub- S3.55.500 S3.66.428 Cub- Track Loger System Cub- S3.55.500 S3.66.428 Cub- Track Loger Correrk System S3.55.500 S3.66.428 Transha System Cub- S3.55.500<	Electronic Speed limit sign				Miscellaneous	\$6,758	\$19,486
Uhlip Room - Kitchen (Refurbich) 1062 Clubhouse - Uklity Room 58.650 524.541 Uster Uster Uster Star 201-2032 Total for 2050-2051 512.724 201-2032 Maintenance - Equipment Star 2007 S19.500 54.455 Star 2012 Maintenance - Equipment Star 2012 S12.203 54.255 Club - File Systems - User Hentry Cooling Systems 1049 Clubhouse - Mach Equipment Star 2012 S12.203 Club - Hentry Cooling Systems 1050 Clubhouse - Mach Equipment Star 2016 S40.000 S13.137 Club - Hentry Cooling Systems 1051 Clubhouse - Offices S40.000 S13.137 Club - Hentry Cooling Systems 1051 Clubhouse - Offices S45.500 S25.93.80 Correct - Kithen Access Read Clubhouse - Offices S45.500 S25.93.80 Correct - Correct Arthin's / Maintenance - Equipment S45.500 S25.93.80 Correct - Kithen Access Read Maintenance - Equipment S45.500 S38.660 Parol Veinite - Corrado estenadad Maintenance - Equipment S43.640 S42.120 Pool System Pool Sys S37.800 <t< td=""><td>Mailboxes</td><td></td><td>7007</td><td></td><td>Miscellaneous</td><td>\$19,450</td><td>\$56,082</td></t<>	Mailboxes		7007		Miscellaneous	\$19,450	\$56,082
العرب العر	Rec Rm - Flooring		1058		Clubhouse - Rec Room	\$9,300	\$26,815
Bit Number of State	Utility Room - Kitchen		1062		Clubhouse - Utility Room	\$8,650	\$24,941
2951-2052 Maintenance - Equipment \$19.500 \$44.51 2 Fnow Plow kits (19.1 9.192) Maintenance - Equipment \$14.2,000 \$425.815 Bobez Compact Track Loader 0.1027 Clubhouze - Bistro \$142.000 \$425.815 Digital Compact Track Loader 0.109 Clubhouze - Mech Equipment \$24.322 \$72.964 Ugala Pirkepairs 0.109 Clubhouze - Mech Equipment \$54.075 \$15.2155 Com - Heating/Coling Systems 0.109 Clubhouze - Mech Equipment \$54.000 \$39.137 To - Poorting 0.105 Clubhouze - Mech Equipment \$55.000 \$52.9388 Coff Course - Cart Path's / 2004 Golf Course \$46.001 \$137.942 Melaho Egystem Clubhouze - Offices \$14.000 \$38.866 Parcol Weice - Colorado Maintenance - Equipment \$41.000 \$38.866 Parcol Weice - Colorado Maintenance - Equipment \$41.000 \$38.866 Parcol Weice - Colorado Maintenance - Equipment \$41.000 \$28.866 Parcol Weice - Colorado Maintenance - Equipment \$31.000 <td>(Refurbish)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	(Refurbish)						
2 Snow Plow kits (191 6 192) Maintenance - Equipment S19,500 544,615 Bitro - Restroom 1027 Clubhouse - Bitro 5,43,200 5,42,5016 Clob - Fire Systems 1049 Clubhouse - Mech Equipment 5,42,000 5,42,5016 Clob - Fire Systems 1050 Clubhouse - Mech Equipment 5,44,305 5,162,155 Clob - Fire Systems 1050 Clubhouse - Mech Equipment 5,46,000 5,91,57 Clob - Fire Systems 2004 Correste siftleme Access Reso 5,85,000 5,85,000 5,85,000 5,85,000 5,85,800<					Tota	l for 2050-2051:	\$127,324
Bistro - Restroom 1027 Clubhouse - Bistro 54.325 512.969 Bobart Compact Track Loader Maintenance - Equipment 53.4200 5435.816 Citub - Fire Systems - 1049 Clubhouse - Mech Equipment 52.432 572.964 Upgrade/Regular Asphalt & Concrete Surfaces 540.000 591.315 502.31 Citub - Heating/Cooling Systems 1050 Clubhouse - Mech Equipment 554.000 592.328 Concrete - Kitchen Access Road Asphalt & Concrete Surfaces 546.001 512.7942 Hon/Yaou Of Mices - 1054 Clubhouse - Offices 515.500 516.64.88 Funishing/Flooring 0 Clubhouse - Offices 516.900 538.866 Funishing/Flooring 9001 Pool f Spa 537.890 513.800 Fool Area - Deck (Repairs - S%) 9002 Pool f Spa 538.00	2051-2052						
bbbcat Compact Track Loader Maintenance - Equipment \$142.000 \$425,816 (2021) Cubhouse - Mech Equipment \$24,332 \$72,964 Upgrade/Repairs 1050 Clubhouse - Mech Equipment \$84,000 \$512,157 Coh - Heating/Cooling Systems 1050 Clubhouse - Mech Equipment \$54,000 \$229,368 Concrete - Kitchen Access Road Asphalt & Concrete Surfaces \$40,000 \$239,368 Colic Course - Carl Path's / 2004 Gold Course \$46,000 \$317,942 Gold Course - Carl Path's / 2004 Gold Course \$46,000 \$38,605 Farol Vehicite - Colorado Crew Maintenance - Equipment \$41,000 \$38,805 Patrol Vehicite - Colorado Crew Maintenance - Equipment \$41,000 \$38,805 Patrol Vehicite - Colorado Crew Maintenance - Equipment \$41,000 \$38,805 Patrol Vehicite - Colorado Crew Maintenance - Equipment \$41,000 \$38,805 Patrol Vehicite - Colorado Crew Maintenance - Equipment \$41,000 \$31,350 Pool Area - Deck (Repairs : 51) 9001 Pool 6 5pa	2 Snow Plow kits (191 & 192)				Maintenance - Equipment	\$19,500	\$44,615
الالت التوالي المعارية التوالية	Bistro - Restroom		1027		Clubhouse - Bistro	\$4,325	\$12,969
Club - Fire Systems - Upgradefitzpains 1049 Clubhouse - Mech Equipment \$24,332 \$72,964 Upgradefitzpains 1050 Clubhouse - Mech Equipment \$54,075 \$516,155 Concrete - Kitchen Access Road Asphatis Concrete Surfaces \$46,000 \$915,175 Krin Roofing 1055 Clubhouse - Ketrior \$46,000 \$253,988 Golf Course - Carl Path's / 2004 Golf Course \$46,000 \$313,942 Weld Course - Carl Path's / 2004 Clubhouse - Offices \$55,500 \$516,428 Furnishings/Flooring Clubhouse - Offices \$16,000 \$93,805 \$313,900 \$33,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$93,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,040 \$42,102 Pool Area - Deck (Repairs - SX) 9002 Pool & 5pa \$37,000 \$20,900 Pool Area - Deck (Repairs - SX) 9002 Pool & 5pa \$31,800 \$31,351 Pool Area - Deck (Repairs - SX) 9002 Pool & 5pa \$31,900 \$34,430 <tr< td=""><td>Bobcat Compact Track Loader</td><td></td><td></td><td></td><td>Maintenance - Equipment</td><td>\$142,000</td><td>\$425,816</td></tr<>	Bobcat Compact Track Loader				Maintenance - Equipment	\$142,000	\$425,816
Upgrade/Repairs Upgrade/Repairs Status	(2021)						
Club - Heating/Cooling Systems 1050 Clubhouse - Mech Equipment \$\$4,075 \$162,155 Concrete - Kitchen Access Road Aspnalt & Concrete Surfaces \$40,000 \$215,17 Ext - Roofing 1055 Clubhouse - Citrices \$86,001 \$313,7942 Rehal (233) Clubhouse - Offices \$55,500 \$516,640 \$388,666 Purrishing/Flooring Clubhouse - Offices \$516,900 \$388,666 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$938,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$938,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$938,805 Patrol Vehicle - Colorado Crew 9001 Pool & 5pa \$7,000 \$20,931 Pool Area - Deck (Repars - SSk) 9002 Pool & 5pa \$314,040 \$42,102 Pool Area - Deck 9001 Pool & 5pa \$31,000 \$43,471 Pool Sade Structure Pool & 5pa \$31,000 \$43,471 Pool Sade Structure Pool & 5pa \$31,0300 \$116,494	Club - Fire Systems -		1049		Clubhouse - Mech Equipment	\$24,332	\$72,964
Concrete - Ntichen Access Road Asphalt & Concrete Surfaces \$40,000 \$51,517 Ext - Rooling 1035 Clubhouse - Exterior \$86,500 \$259,388 Golf Course - Cart Path's / Rehab (25%) 2004 Golf Course - \$86,500 \$137,942 Rehab (25%) 1054 Clubhouse - Offices \$516,500 \$38,666 URD/Patrol Offices - Colorado Crew Maintenance - Equipment \$41,000 \$93,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$77,850 \$113,501 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$77,850 \$213,500 Pool Area - Cover & Reel 9001 Pool 64 \$pa \$77,000 \$20,991 Pool Area - Deck (Repairs - S%) 9002 Pool 64 \$pa \$53,800 \$101,356 Reseau/Waterproof Pool 64 \$pa \$27,000 \$890,615 Pool 64 \$pa \$27,000 \$890,615 Pool Area - Deck (Repairs - S%) 9002 Pool 64 \$pa \$19,000 \$43,471 Pool Bathrooms Pool 64 \$pa \$19,000 \$43,471 \$33,800 \$116,549 Poo	Upgrade/Repairs						
Ext - Roofing 1035 Clubhouse - Exterior S66,500 S259,388 Golf Course - Cart Path's / 204 Golf Course S46,001 S137,942 HOM/Patrol Offices - 1054 Clubhouse - Offices S55,500 S166,428 Furnishing/Flooring Clubhouse - Offices S15,900 S36,666 Patrol Vehicle - Colorado Crew Maintenance - Equipment S41,000 S93,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment S41,000 S93,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment S41,000 S93,805 Pool Area - Deck (Repairs - S73) 9002 Pool Spa S13,800 S103,350 Pool Area - Deck (Repairs - S73) 9002 Pool Spa S14,040 S42,002 Pool Area - Deck (Repairs - S73) 9002 Pool Spa S14,040 S42,002 Pool Bathrooms Pool Spa S13,800 S44,371 S01,356 Resaul/Waterproof 9015 Pool Spa S14,040 S42,421 Pool Spa False 9017 Pool Spa S14,050 <td>Club - Heating/Cooling Systems</td> <td></td> <td>1050</td> <td></td> <td>Clubhouse - Mech Equipment</td> <td>\$54,075</td> <td>\$162,155</td>	Club - Heating/Cooling Systems		1050		Clubhouse - Mech Equipment	\$54,075	\$162,155
Golf Course - Cart Path's / Rehai (25X) 2004 Golf Course \$46,001 \$137,942 Rehai (25X) IDA/Patrol Offices - Furnishings/Flooring 1054 Clubhouse - Offices \$55,500 \$166,428 Office - Phone System Clubhouse - Offices \$16,900 \$538,665 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$938,005 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$37,850 \$113,501 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$7,000 \$22,091 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$33,800 \$103,356 Reesal/Waterproof) Pool & Spa \$297,000 \$890,615 Pool Sabtrooms Pool & Spa \$297,000 \$817,472 Pool Sabtrooms Pool & Spa \$14,040 \$43,471 Pool Sabtrooms Pool & Spa \$14,040 \$43,471 Pool Sabtrooms Pool & Spa \$14,040 \$43,721 Pool Sabtrooms Pool & Spa \$14,580 \$41,721 Pool Sabtrooms 9012	Concrete - Kitchen Access Road				Asphalt & Concrete Surfaces	\$40,000	\$91,517
Rehab (25%) Normal State S	Ext - Roofing		1035		Clubhouse - Exterior	\$86,500	\$259,388
HOA/Patrol Offices - 1054 Clubhouse - Offices S55,500 S166,428 Furnishings/flooring Clubhouse - Offices \$16,900 \$33,666 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$51,500 \$513,501 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$57,850 \$113,501 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$57,850 \$213,501 Pool Area - Cover & Reel 9001 Pool & 5pa \$14,040 \$42,100 Pool Area - Deck (Repairs - 5%) 9002 Pool & 5pa \$14,040 \$42,100 Pool Area - Deck (Repairs - 5%) 9003 Pool & 5pa \$13,000 \$43,471 Pool Expa \$100 \$22,000 \$890,615 \$27,000 \$43,471 Pool Spa \$12,000 \$543,471 Pool & 5pa \$13,500 \$16,474 Pool Spa \$12,000 \$24,392 \$20,000 \$16,474 Pool Spa \$13,000 \$11,355 \$23,4000 \$16,474 Pool Spa \$13,000 \$14,3471 \$20,001 \$2	Golf Course - Cart Path's /		2004		Golf Course	\$46,001	\$137,942
Fundshings/Flooring Clubhose - Offices S16,900 S38,865 Office - Phone System Clubhose - Offices S16,900 S93,805 Patrol Vehicle - Colorado Crew Maintenance - Equipment S37,850 S93,805 Patrol Vehicle - Colorado Maintenance - Equipment S37,850 S20,991 Pool Area - Deck (Repairs - S%) 9003 Pool 5 Spa S33,800 S101,356 Pool Area - Deck (Mepairs - S%) 9003 Pool 5 Spa S33,800 S101,356 Pool Area - Deck (Mepairs - S%) 9003 Pool 5 Spa S297,000 S43,471 Pool Bathoroms Pool 6 Spa S297,000 S43,471 S43,472 Pool Staft Structure Pool 6 Spa S10,903 S43,472 Pool/Spa - Fletrs 9012 Pool 5 Spa S33,000 S43,721 Pool/Spa - Heater (Pool) 9016 Pool 5 Spa S33,000 S22,991 Pool/Spa - Heater (Pool) 9018 Pool 5 Spa S30,700 S22,991 Pool/Spa - Heater (Spa) 9019 Pool 6 Spa S30,708 S22,923	Rehab (25%)						
Office - Phone System Clubhouse - Offices \$16,900 \$38,666 Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$938,065 Patrol Vehicle - Colorado Maintenance - Equipment \$37,800 \$513,501 extended 9001 Pool & Spa \$7,000 \$20,991 Pool Area - Cover & Reel 9001 Pool & Spa \$33,800 \$20,991 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$33,800 \$20,991 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$33,800 \$20,091 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$33,800 \$313,350 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$37,000 \$43,471 Pool Area - Deck (Repairs - 5%) 9003 Pool & Spa \$19,000 \$43,471 Pool Sade Structure Pool & Spa \$27,000 \$643,471 Pool Sade Structure Pool & Spa \$11,550 \$43,400 Pool Sade Structure \$015 Pool & Spa \$11,550 \$43,400	HOA/Patrol Offices -		1054		Clubhouse - Offices	\$55,500	\$166,428
Patrol Vehicle - Colorado Crew Maintenance - Equipment \$41,000 \$93,805 Patrol Vehicle - Colorado Maintenance - Equipment \$37,850 \$115,501 extended 9001 Pool 4 5pa \$7,000 \$20,991 Pool Area - Cover 6 Reel 9001 Pool 5 5pa \$14,040 \$42,102 Pool Area - Deck (Repairs - 5%) 9002 Pool 5 5pa \$14,040 \$42,102 Pool Area - Deck (Repairs - 5%) 9003 Pool 5 5pa \$297,000 \$890,615 Reesal/Waterproof) Pool 6 5pa \$297,000 \$890,615 Pool Stapa \$14,900 \$43,711 Pool 6 5pa \$277,000 \$890,615 Pool Stapa \$14,900 \$43,712 Pool 6 5pa \$277,000 \$890,615 Pool Stapa \$13,900 \$43,712 Pool 6 5pa \$277,000 \$890,615 Pool Stapa \$14,510 \$44,520 \$43,712 \$45,702 \$43,712 Pool Spa \$291 Pool 6 5pa \$37,000 \$44,743 \$44,743 Pool Spa \$13,501 \$44,743 \$44,743 \$44,743 Pool Spa \$10,615	Furnishings/Flooring						
Partol Vehicle - Colorado Maintenance - Equipment \$37,850 \$113,501 Pool Area - Cover & Reel 9001 Pool & Spa \$7,000 \$20,991 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$14,404 \$42,102 Pool Area - Deck (Repairs - 5%) 9003 Pool & Spa \$33,800 \$101,356 Reseal/Waterproof Pool & Spa \$510,000 \$43,471 Pool Shade Structure Pool & Spa \$27,000 \$61,774 Pool Shade Structure Pool & Spa \$31,000 \$43,471 Pool/Spa - Coping 9012 Pool & Spa \$31,000 \$43,471 Pool/Spa - Filters 9015 Pool & Spa \$31,300 \$43,471 Pool/Spa - Heater (Pool) 9016 Pool & Spa \$31,300 \$44,580 Pool/Spa - Heater (Pool) 9017 Pool & Spa \$31,000 \$42,698 Pool/Spa - Heater (Spa) 9019 Pool & Spa \$31,031 \$44,743 Solar Sweed Cameras \$20,991 Solar & Spa \$34,035 Solar S	Office - Phone System				Clubhouse - Offices	\$16,900	\$38,666
extended Pool Area - Cover & Reel 9001 Pool & Spa \$7,000 \$20,991 Pool Area - Deck (Repairs - 5%) 9002 Pool & Spa \$14,040 \$42,102 Pool Area - Deck (Repairs - 5%) 9003 Pool & Spa \$33,800 \$101,356 Pool Area - Deck (Repairs - 5%) 9003 Pool & Spa \$33,800 \$101,356 Pool Expa S27,000 \$65,774 \$7001 \$43,471 Pool Sade Structure Pool & Spa \$27,000 \$61,774 Pool Sade Structure Pool & Spa \$27,000 \$61,774 Pool Sade Structure Pool & Spa \$27,000 \$61,774 Pool Sade Structure Pool & Spa \$31,900 \$543,721 Pool/Spa - Heater (Pool) 9015 Pool & Spa \$30,000 \$256,988 Pool/Spa - Heater (Pool) 9017 Pool & Spa \$31,355 \$34,055 Pool/Spa - Heater (Spa) 9019 Pool & Spa \$31,350 \$34,055 Solar Pourps/Motors 9019 Pool & Spa \$11,350 \$34,055 Solar Stube	Patrol Vehicle - Colorado Crew				Maintenance - Equipment	\$41,000	\$93,805
Pool Area - Cover 6 Reel 9001 Pool 6 Spa \$7,000 \$20,991 Pool Area - Deck (Repairs - 5%) 9002 Pool 6 Spa \$31,4040 \$42,102 Pool Area - Deck (Repairs - 5%) 9003 Pool 6 Spa \$33,800 \$101,350 Reseal/Waterproof) Pool 6 Spa \$297,000 \$890,615 Pool Equipment Room Pool 6 Spa \$297,000 \$43,471 Pool Shade Structure Pool 6 Spa \$27,000 \$43,471 Pool Shade Structure Pool 6 Spa \$27,000 \$43,471 Pool/Spa - Coping 9012 Pool 6 Spa \$29,000 \$43,471 Pool/Spa - Heater (Pool) 9015 Pool 6 Spa \$31,355 \$34,050 Pool/Spa - Heater (Pool) 9016 Pool 6 Spa \$31,355 \$34,050 Pool/Spa - Heater (Pool) 9017 Pool 6 Spa \$31,350 \$242,44 Solar Powerd Cameras Clubhouse - Patrol Offices \$10,815 \$242,44 Solar Powerd Cameras Solar Subs \$24,44 \$20,991 Spa - Resurface/Tile 9020 <td>Patrol Vehicle - Colorado</td> <td></td> <td></td> <td></td> <td>Maintenance - Equipment</td> <td>\$37,850</td> <td>\$113,501</td>	Patrol Vehicle - Colorado				Maintenance - Equipment	\$37,850	\$113,501
Pool Area - Deck (Repairs - 5%) 9002 Pool 6 Spa \$14,040 \$42,102 Pool Area - Deck 9003 Pool 6 Spa \$33,800 \$101,356 Reseal/Waterproof) Pool 6 Spa \$297,000 \$890,615 Pool Bathrooms Pool 6 Spa \$19,000 \$43,471 Pool Shade Structure Pool 6 Spa \$297,000 \$43,471 Pool Shade Structure Pool 6 Spa \$29,000 \$43,472 Pool Shade Structure Pool 6 Spa \$29,000 \$43,472 Pool/Spa - Filters 9015 Pool 6 Spa \$39,000 \$43,600 Pool/Spa - Heater (Pool) 9016 Pool 6 Spa \$39,000 \$266,988 Pool/Spa - Heater (Spa) 9017 Pool 6 Spa \$3,078 \$9,230 Pool/Spa - Paterer (Spa) 9018 Pool 6 Spa \$1,355 \$24,744 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Stubs Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$	extended						
Pool Area - Deck (Reseal/Waterproor) Pool & Spa \$33,800 \$101,356 Pool Bahrooms Pool & Spa \$297,000 \$890,615 Pool Equipment Room Pool & Spa \$297,000 \$43,471 Pool Sade Structure Pool & Spa \$227,000 \$43,471 Pool Spa - Coping 9012 Pool & Spa \$227,000 \$43,721 Pool Spa - Coping 9012 Pool & Spa \$39,000 \$43,721 Pool Spa - Filters 9015 Pool & Spa \$39,000 \$43,721 Pool/Spa - Heater (Pool) 9016 Pool & Spa \$39,000 \$41,693 Pool/Spa - Heater (Spa) 9013 Pool & Spa \$3,078 \$9,2920 Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$11,635 \$24,744 Solar Powered Cameras 9019 Pool & Spa \$11,850 \$21,930 Velders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Solar Subus Solar Diago \$6,500 \$22,911 \$21,943,955 Solar Cost Solar Diago<	Pool Area - Cover & Reel		9001		Pool & Spa	\$7,000	\$20,991
Reseal/Waterproof) Pool & Spa \$297,000 \$890,615 Pool E dujinnent Room Pool & Spa \$297,000 \$43,471 Pool Sade Structure Pool & Spa \$27,000 \$43,471 Pool Spa Coging 9012 Pool & Spa \$27,000 \$61,774 Pool/Spa - Roojng 9012 Pool & Spa \$14,580 \$43,721 Pool/Spa - Heater (Pool) 9016 Pool & Spa \$39,000 \$116,699 Pool/Spa - Heater (Spa) 9017 Pool & Spa \$39,000 \$26,988 Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$31,435 \$24,744 Solar Powered Cameras \$11,355 \$24,744 \$24,744 \$24,744 Solar Sourered Cameras \$10,001 \$20,991 Pool & Spa \$51,400 \$20,991 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Spalt & Conrete Surfaces \$5,400 \$16,193 \$20,991 Spalt & Conrete Surfaces \$5,400 \$16,193 \$20,991 </td <td>Pool Area - Deck (Repairs - 5%)</td> <td></td> <td>9002</td> <td></td> <td>Pool & Spa</td> <td>\$14,040</td> <td>\$42,102</td>	Pool Area - Deck (Repairs - 5%)		9002		Pool & Spa	\$14,040	\$42,102
Pool Bathrooms Pool B 5pa \$297,000 \$890,615 Pool Equipment Room Pool 6 5pa \$19,000 \$43,471 Pool Shade Structure Pool 6 5pa \$27,000 \$61,774 Pool/Spa - Coping 9012 Pool 6 5pa \$27,000 \$61,774 Pool/Spa - Coping 9012 Pool 6 5pa \$14,580 \$43,721 Pool/Spa - Flitters 9015 Pool 6 5pa \$13,555 \$34,050 Pool/Spa - Heater (Pool) 9016 Pool 6 5pa \$9,000 \$26,988 Pool/Spa - Heater (Spa) 9017 Pool 6 5pa \$31,355 \$34,050 Pool/Spa - Mastic/Waterproof 9018 Pool 6 5pa \$31,350 \$34,950 Pool/Spa - Pumps/Motors 9019 Pool 6 5pa \$14,000 \$41,982 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Stubs Pool 6 5pa \$51,030 \$31,835 Spa - Resurface/Tile 9020 Pool 6 5pa \$51,030 \$20,911 State stubs Pool 6 5pa \$51,030 <	Pool Area - Deck		9003		Pool & Spa	\$33,800	\$101,356
Pool Equipment Room Pool 5 Spa \$19,000 \$43,471 Pool Shade Structure Pool 6 Spa \$27,000 \$61,774 Pool/Spa - Coping 9012 Pool 6 Spa \$27,000 \$61,774 Pool/Spa - Filters 9015 Pool 6 Spa \$39,000 \$116,949 Pool/Spa - Heater (Pool) 9016 Pool 6 Spa \$39,000 \$26,968 Pool/Spa - Heater (Spa) 9017 Pool 6 Spa \$3,078 \$92,320 Pool/Spa - Heater (Spa) 9017 Pool 6 Spa \$3,078 \$92,320 Pool/Spa - Pumps/Motors 9018 Pool 6 Spa \$14,000 \$41,982 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Stubs Pool 6 Spa \$54,00 \$16,193 Weld ex(2) - Ranger 6074 Maintenace - Equipment \$7,000 \$20,991 Solar Stubs Total for 2051-2052 \$51,48,959 \$52,250 \$51,63,729 Repair/Replace (2) Total for 2051-2052 \$52,500 \$20,271 Maintenace - Equipment \$7,500	(Reseal/Waterproof)						
Pool Shade Structure Pool 6 Spa \$27,00 \$61,774 Pool/Spa - Coping 9012 Pool 6 Spa \$14,580 \$43,721 Pool/Spa - Filters 9015 Pool 6 Spa \$39,000 \$116,949 Pool/Spa - Heater (Pool) 9016 Pool 6 Spa \$39,000 \$26,988 Pool/Spa - Heater (Spa) 9017 Pool 6 Spa \$3,078 \$9,230 Pool/Spa - Mastic/Waterproof 9018 Pool 6 Spa \$3,078 \$9,230 Pool/Spa - Mastic/Waterproof 9019 Pool 6 Spa \$14,000 \$41,982 Solar Powered Cameras 9019 Pool 6 Spa \$11,355 \$24,744 Solar Stubs Pool 6 Spa \$11,350 \$24,744 Solar Stubs Pool 6 Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Pool 6 Spa \$54,005 \$163,729 \$25,200 \$163,729 Repair/Replace (2) Rool 6 Spa \$54,005 \$20,991 \$20,991 \$20,991 \$20,991	Pool Bathrooms				Pool & Spa	\$297,000	\$890,615
Pool/Spa - Coping 9012 Pool 6 Spa \$14,580 \$43,721 Pool/Spa - Filters 9015 Pool 6 Spa \$39,000 \$116,949 Pool/Spa - Heater (Pool) 9016 Pool 6 Spa \$11,355 \$34,050 Pool/Spa - Heater (Spa) 9017 Pool 6 Spa \$9,000 \$26,988 Pool/Spa - Mastic/Waterproof 9018 Pool 6 Spa \$3,078 \$9,230 Pool/Spa - Mastic/Waterproof 9019 Pool 6 Spa \$10,815 \$24,744 Solar Powered Cameras \$10,815 \$24,744 \$10,815 \$24,744 Solar Powered Cameras \$10,815 \$24,744 \$10,815 \$24,744 Solar Subs Pool 6 Spa \$10,815 \$24,744 \$10,815 \$24,744 Solar Subs Pool 6 Spa \$10,815 \$24,744 \$10,815 \$24,744 Solar Subs Pool 6 Spa \$10,815 \$24,744 \$30,835 \$24,744 Solar Subs Pool 6 Spa \$5,400 \$16,635 \$20,991 \$20,991 \$20,991 \$20,991 \$20,991	Pool Equipment Room				Pool & Spa	\$19,000	\$43,471
Pool/Spa - Filters 9015 Pool & Spa \$39,000 \$116,949 Pool/Spa - Heater (Pool) 9016 Pool & Spa \$11,355 \$34,050 Pool/Spa - Heater (Spa) 9017 Pool & Spa \$9,000 \$26,988 Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$3,078 \$9,230 Pool/Spa - Pumps/Motors 9019 Pool & Spa \$14,000 \$41,982 Solar Powered Cameras 9019 Pool & Spa \$14,000 \$41,982 Solar Stubs 9020 Pool & Spa \$14,000 \$41,982 Solar Stubs Pool & Spa \$11,50 \$34,035 Spa - Resurface/Tile 9020 Pool & Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Stat of the Spa \$5,400 \$16,193 Stat of the Spa \$5,400 \$16,193 Stat of the Spa \$5,400 \$16,729 Stat of the Spa \$5,400 \$16,	Pool Shade Structure				Pool & Spa	\$27,000	\$61,774
Pool/Spa - Heater (Pool) 9016 Pool & Spa \$11,355 \$34,050 Pool/Spa - Heater (Spa) 9017 Pool & Spa \$9,000 \$26,988 Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$3,078 \$9,230 Pool/Spa - Pumps/Motors 9019 Pool & Spa \$14,000 \$41,982 Solar Powered Cameras S10,815 \$24,744 \$24,744 Solar Stubs Pool & Spa \$11,350 \$34,035 Spa - Resurface/Tile 9020 Pool & Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Total for 2051-2052 \$34,4859 \$7003 Asphalt & Concrete Surfaces \$52,500 \$16,5729 7003 Miscellaneous \$6,500 \$20,271 7003 Miscellaneous \$6,500 \$20,271 7003 Miscellaneous \$6,500 \$20,271 \$20,201 Maintenance - Equipment	Pool/Spa - Coping		9012		Pool & Spa	\$14,580	\$43,721
Pool/Spa - Heater (Spa) 9017 Pool & Spa \$9,000 \$26,988 Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$3,078 \$9,230 Pool/Spa - Pumps/Motors 9019 Pool & Spa \$14,000 \$41,982 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Powered Cameras Pool & Spa \$11,350 \$34,035 Spa - Resurface/Tile 9020 Pool & Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Total for 2051-2052: \$3,148,959 2052-2053 \$163,729 Repair/Replace (2) Miscellaneous \$6,500 \$20,271 Maintenance - Equipment \$5,350 \$16,685 \$20,271 Maintenance - Equipment \$5,350 \$16,685 \$20,271 Maintenance - Equipment \$5,350 \$16,685 \$16,685 Hydraulic Scarifier Box Blade \$36,426 \$36,426 Golf - Green Sweeper 6019	Pool/Spa - Filters		9015		Pool & Spa	\$39,000	\$116,949
Pool/Spa - Mastic/Waterproof 9018 Pool & Spa \$3,078 \$9,230 Pool/Spa - Pumps/Motors 9019 Pool & Spa \$14,000 \$41,982 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Stubs Pool & Spa \$11,350 \$34,035 Spa - Resurface/Tile 9020 Pool & Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Total for 2051-2052 \$3,148,959 2052-2053 Asphalt (Maint Yard) - 1005 Asphalt & Concrete Surfaces \$52,500 \$16,3729 Repair/Replace (2) 2000 Miscellaneous \$6,500 \$20,271 Maintenance - Equipment \$5,350 \$16,685 \$16,685 Hydraulic Scarifier Box Blade V Maintenance - Equipment \$5,350 \$16,685 Golf - Green Sweeper 6019 Maintenance - Equipment \$1,680 \$36,426 Golf - Mower JD2500 (#2002) 6021 Maintenance - Equipment \$34,770 <td>Pool/Spa - Heater (Pool)</td> <td></td> <td>9016</td> <td></td> <td>Pool & Spa</td> <td>\$11,355</td> <td>\$34,050</td>	Pool/Spa - Heater (Pool)		9016		Pool & Spa	\$11,355	\$34,050
Pool/Spa - Pumps/Motors 9019 Pool & Spa \$14,000 \$41,982 Solar Powered Cameras Clubhouse - Patrol Offices \$10,815 \$24,744 Solar Stubs Pool & Spa \$11,350 \$34,035 Spa - Resurface/Tile 9020 Pool & Spa \$5,400 \$16,193 Welders (2) - Ranger 6074 Maintenance - Equipment \$7,000 \$20,991 Total for 2051-2052: \$2052-2053 Asphalt (Maint Yard) - 1005 Asphalt & Concrete Surfaces \$52,500 \$163,729 Repair/Replace (2) Entry Monuments - 7003 Miscellaneous \$6,500 \$20,271 Maint/Refurb 7003 Miscellaneous \$6,500 \$20,271 Frontier B84278H - 6ft, 6in, Maintenance - Equipment \$5,350 \$16,685 Hydraulic Scarifier Box Blade	Pool/Spa – Heater (Spa)		9017		Pool & Spa	\$9,000	\$26,988
Solar Powered CamerasClubhouse - Patrol Offices\$10,815\$24,744Solar StubsPool & Spa\$11,350\$34,035Spa - Resurface/Tile9020Pool & Spa\$5,400\$16,193Welders (2) - Ranger6074Maintenance - Equipment\$7,000\$20,991Total for 2051-2052:\$35,148,9592052-2053Asphalt (Maint Yard) - Repair/Replace (2)Entry Monuments - Maintenance - Equipment\$6,500\$20,271Frontier BB4278H - 6ft, 6in. Hydraulic Scarifier Box BladeMaintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436	Pool/Spa - Mastic/Waterproof		9018		Pool & Spa	\$3,078	\$9,230
Solar StubsPool & Spa\$11,350\$34,035Spa - Resurface/Tile9020Pool & Spa\$5,400\$16,193Welders (2) - Ranger6074Maintenance - Equipment\$7,000\$20,991Total for 2051-2052:\$3,148,9592052-2053Asphalt (Maint Yard) - Repair/Replace (2)Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,271Entry Monuments - Maint/RefurbFrontier B84278H - 6ft, 6in. Hydraulic Scarifier Box Blade\$019Maintenance - Equipment\$11,680\$36,426Golf - Green Sweeper6019Maintenance - Equipment\$34,770\$108,436	Pool/Spa - Pumps/Motors		9019		Pool & Spa	\$14,000	\$41,982
Spa - Resurface/Tile9020Pool & Spa\$5,400\$16,193Welders (2) - Ranger6074Maintenance - Equipment\$7,000\$20,991Total for 2051-2052:\$3,148,9592052-2053Asphalt (Maint Yard) - Repair/Replace (2)1005Asphalt & Concrete Surfaces\$52,500\$163,729Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,271Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box Blade7019Maintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$34,770\$108,436	Solar Powered Cameras				Clubhouse - Patrol Offices	\$10,815	\$24,744
Welders (2) - Ranger6074Maintenance - Equipment\$7,000\$20,991Total for 2051-2052:\$3,148,9592052-2053Asphalt (Maint Yard) - Repair/Replace (2)1005Asphalt & Concrete Surfaces\$52,500\$163,729Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,971Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box BladeMaintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436	Solar Stubs				Pool & Spa	\$11,350	\$34,035
Total for 2051-2052:\$3,148,9592052-2053Asphalt (Maint Yard) - Repair/Replace (2)1005Asphalt & Concrete Surfaces\$52,500\$163,729Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,271Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box BladeMaintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436	Spa - Resurface/Tile		9020		Pool & Spa	\$5,400	\$16,193
2052-2053Asphalt (Maint Yard) - Repair/Replace (2)Entry Monuments - Maint/Refurb7003Miscellaneous MiscellaneousFrontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box BladeGolf - Green Sweeper6019Golf - Mower JD2500 (#2002)6021Maintenance - Equipment Maintenance - Equipment\$11,680\$34,770\$108,436	Welders (2) - Ranger		6074		Maintenance - Equipment	\$7,000	\$20,991
Asphalt (Maint Yard) - Repair/Replace (2)1005Asphalt & Concrete Surfaces\$52,500\$163,729Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,271Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box BladeMaintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436					Tota	l for 2051-2052:	\$3,148,959
Repair/Replace (2) Entry Monuments - 7003 Miscellaneous \$6,500 \$20,271 Maint/Refurb Maintenance - Equipment \$5,350 \$16,685 Frontier BB4278H - 6ft. 6in. Maintenance - Equipment \$5,350 \$16,685 Hydraulic Scarifier Box Blade 6019 Maintenance - Equipment \$11,680 \$36,426 Golf - Green Sweeper 6021 Maintenance - Equipment \$34,770 \$108,436	2052-2053						
Repair/Replace (2) Entry Monuments - 7003 Miscellaneous \$6,500 \$20,271 Maint/Refurb Maintenance - Equipment \$5,350 \$16,685 Frontier BB4278H - 6ft. 6in. Maintenance - Equipment \$5,350 \$16,685 Hydraulic Scarifier Box Blade 6019 Maintenance - Equipment \$11,680 \$36,426 Golf - Green Sweeper 6021 Maintenance - Equipment \$34,770 \$108,436	Asphalt (Maint Yard) -		1005		Asphalt & Concrete Surfaces	\$52,500	\$163,729
Entry Monuments - Maint/Refurb7003Miscellaneous\$6,500\$20,271Frontier BB4278H - 6ft. 6in. Hydraulic Scarifier Box BladeMaintenance - Equipment\$5,350\$16,685Golf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436	Repair/Replace (2)					· ·	. ,. ==
Maint/Refurb Frontier BB4278H - 6ft. 6in. Maintenance - Equipment \$5,350 \$16,685 Hydraulic Scarifier Box Blade Solf - Green Sweeper 6019 Maintenance - Equipment \$11,680 \$36,426 Golf - Mower JD2500 (#2002) 6021 Maintenance - Equipment \$34,770 \$108,436	Entry Monuments -		7003		Miscellaneous	\$6,500	\$20,271
Hydraulic Scarifier Box BladeGolf - Green Sweeper6019Maintenance - Equipment\$11,680\$36,426Golf - Mower JD2500 (#2002)6021Maintenance - Equipment\$34,770\$108,436	Maint/Refurb						
Golf - Green Sweeper 6019 Maintenance - Equipment \$11,680 \$36,426 Golf - Mower JD2500 (#2002) 6021 Maintenance - Equipment \$34,770 \$108,436	Frontier BB4278H - 6ft. 6in.				Maintenance - Equipment	\$5,350	\$16,685
Golf - Mower JD2500 (#2002) 6021 Maintenance - Equipment \$34,770 \$108,436	Hydraulic Scarifier Box Blade						
	Golf - Green Sweeper		6019		Maintenance - Equipment	\$11,680	\$36,426
John Deere 5065E Utility Tractor Maintenance - Equipment \$59,500 \$185,560	Golf - Mower JD2500 (#2002)		6021		Maintenance - Equipment	\$34,770	\$108,436
	John Deere 5065E Utility Tractor				Maintenance - Equipment	\$59,500	\$185,560



Anticipated Expenditures (30 Years)

Units: 2,887 | Start Date: 7/1/2023

Component	Location	GL Code	Project Number	Category	Current Replacement Cost	Anticipated Expenditures
John Deere 520M Loader				Maintenance - Equipment	\$12,600	\$39,295
Stables - Ext Wood (Paint)		1203		Stables	\$19,720	\$61,500
Stables - Ext Wood (Repairs- 20%)		1204		Stables	\$25,500	\$79,526
Stables - Panels/Gates (Contingency) - 1		1206		Stables	\$33,450	\$104,319
Stables - Panels/Gates (Contingency) - 2				Stables	\$44,885	\$139,981
Utility Vehicle - John Deere Gator		6069		Maintenance - Equipment	\$18,385	\$57,336
Utility Vehicle - John Deere Gator (50014)				Maintenance - Equipment	\$17,000	\$53,017
Utility Vehicle - John Deere Gator (50018)				Maintenance - Equipment	\$17,000	\$53,017
				Tota	l for 2052-2053:	\$1,119.097

Total for 2052-2053:

\$1,119,097

